

U. S. Department of Agriculture  
FOREST SERVICE

P-23  
already  
posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 31 W. 5th Mer.  
Center 1/4 Corner common to Sections

24, and

Corner consists of a Scribed stake (not) in place  
State condition Poor


Dimensions above ground 10 x 3 x 3 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Pine

Diameter 12"

Bearing N. 84° W.

Distance .54

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*J. Swartz*

J. Swartz

(Signature)

Enrollee


(Title)

4/24/36

(Date)

Metal Location Poster is on a Balsam tree 8 inches diameter, on the side of Tree from which this Corner bears 40° 40' chains distant. Give any further facts which will aid in finding this Corner again.

fence running North East. Put new stake by old stake.



(Make sketch of topography near Corner)

T. 149 N. R. 31 W. 5th Mer.

P-23