

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

225

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 149 N. R. 31 W. 5th. P. Mer.

Twp. Section Corner common to Sections
36, and 31 T. 149 N.
R. 30 W.

Corner consists of a Cement Mon. ~~(cast)~~ in place

State condition Good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Link

New B.T.

Orig. B.T.		
S. 31		
B.T.	B.T.	

Species N. Pine Stp. N. Pine

Diameter 12" 6"

Bearing N. 30° W. N. 78° E.

Distance 25 29

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

John A. Gjelhaug

(Signature)

7/10/39

(Date)

Jr. Civil Eng.

(Title)

2-25

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 149 N. R. 31 W. 5th. P. Mer.

275