

U. S. Department of Agriculture

FOREST SERVICE

Z-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ¹⁵⁰149 R. 26 5th Mer.

Sec. Corner common to Sections
5, 6, 31, and 32.

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

B.T		B.T	
-----	--	-----	--

Species Sec. 6 Sec. 5

Diameter A-10" A-10"

Bearing S 30° W S 50° E

Distance 77 links 78 links

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

D. B. Ames

(Signature)

1-22-34


(Date)

(Title)

Z-5

Corner again.
Corner is in Road where
Turns West

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on an ASPEN at the



(Make sketch of topography near Corner)

T. 149 R. 26 5th Mer.