

U. S. Department of Agriculture  
FOREST SERVICE

N<sup>9</sup>

posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 26 S Mer.

Section 17 Corner common to Sections

17, 16, 20, and 21

Corner consists of a Post (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

17	20	21	16
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

G. Sherman  
(Signature)


1-11-34  
(Date)

ENGINEER  
(Title)

Corner again. Found Post no. 13, T. 5

Give any further facts which will aid in finding this from which this Corner bears 12 links chains distant.

side of Post  
7" inches diameter, on the North  
Metal Location Poster is on a T.C. Post



(Make sketch of topography near Corner)

T. 130 R. 26 Mer.