

U. S. Department of Agriculture  
FOREST SERVICE

*posted*  
*N 11*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *150* R. *26* S. Mer.

*Quarter* Corner common to Sections  
*16*, and *21*

Corner consists of a *Post* (not) in place

State condition *Good*

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>16</i>		<i>21</i>	
-----------	--	-----------	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*G. Sherman*

(Signature)

*1-14-34*


(Date)

*Engineer*

(Title)

T. 150 R. 26 S Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a Stump-Birch  
tree 2 1/2 inches diameter, on the North  
side of Corner  
from which this Corner bears  
20 links ~~chains~~ distant.

Give any further facts which will aid in finding this  
Corner again.

Corner, Center of Road  
Post lays against Stump  
Found no B.T.