

Form 974-0 Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

NPB
P

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 26 W 5TH P Mer.

SECTION Corner common to Sections

15, 16, 21, and 22

Corner consists of a WOODEN STAKE in place


State condition Good

Dimensions above ground 3 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT	BT		

Species CEDAR CEDAR

Diameter 2 IN 2 IN

Bearing S22 1/2° E 50' 0"

Distance 61 CHD 65 CHS

Do you believe this to be a genuine Land Office Corner? _____

If not, why? RESURVEY BY COUNTY

ENGINEER.

Ralph F. Johnson
(Signature)


JULY 17, 1905 FOREMAN, C.M. CU-7

(Date)

(Title)

T. 150 N R. 26 W 5th P Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a CEEDAR
tree 7 inches diameter, on the N.W.
side of TREE
from which this Corner bears N. 22 1/2° W.
.61 chains distant.

Give any further facts which will aid in finding this
Corner again.

CORNER LOCATED ON
PROPOSED ROAD CENTER LINE.