

## U. S. Department of Agriculture

FOREST SERVICE

Z-16

CHIPPEWA NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 150 & 149 R. 26 5<sup>th</sup> 12 Mer.

E. 4.6 Corner common to Sections

34, and 3

Corner consists of a ASPEN STAKE (not) in place

State condition NEW

Dimensions above ground 3X3X36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

NO SCRIBE			
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/5 16			
B.T.			

Species J.P.

Diameter 8"

Bearing S. 64° W

Distance 21 IK

Do you believe this to be a genuine Land Office Corner? NO

If not, why? COUNTY SURVEY

H. C. Norman

(Signature)

Nov. 26, 1935

(Date)

J. L. Foster

(Title)


Z-16

Corner again.

Give any further facts which will aid in finding this

chain distant.

8  
from which this Corner bears  $S 33^{\circ} W$   
side of TREE  
tree  $4\frac{1}{2}$  inches diameter, on the SW  
Metal Location Poster is on a N ASPEN



(Make sketch of topography near Corner)

T. 150 R. 26 5TH Mer.