

Form 874-G—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N-17
P

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N. R. 26 W. 5th P. Mer.

SECTION Corner common to Sections

14, 15, 22, and 23

Corner consists of a WOODEN STAKE in place

State condition GOOD

Dimensions above ground 3 x 3 x 3 1/2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|---|---|
| | | | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| S | S | S | S |
| 15 | 22 | 23 | 14 |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|---------|---------|---------|--|
| S 22 | S 23 | S 14 | |
| BT | BT | BT | |

Species BAM ASH ASPEN

Diameter 18 IN. 10 IN. 12 IN.

Bearing S21°W S39°E N5½°E

Distance 72 CM. 176 CM. 157 CM.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? RESURVEY BY COUNTY

ENGINEER.


Ralph L. Johnson
(Signature)

JULY 17, 1925
(Date)

FOREMAN, C.E.M. CU-7
(Title)

T. 150 N. R. 26 W. 5th P. Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a BONA
tree 18 inches diameter, on the NE
side of TREE
from which this Corner bears N 21° E
.72 chains distant.

Give any further facts which will aid in finding this
Corner again.

CORNER LOCATED ON LOW
GROUND & ON PROPOSED
ROAD CENTER LINE.