

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

N19
P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 15DN R. 26W 5th Mer.

1/4 Corner common to Sections
14, and 23

Corner consists of a Wooden Stake (not) in place
State condition Good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>S.</u>		<u>S</u>	
<u>14</u>		<u>23</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>	<u>1/4</u>		
<u>S 23</u>	<u>S 14</u>		
<u>BT</u>	<u>BT</u>		

Species Cedar Ash

Diameter 12" 8"

Bearing S 6 1/2° W N 53 1/2° E

Distance 82 ch. 65 ch.

Do you believe this to be a genuine Land Office Corner? _____


If not, why? _____

Re-survey by County
engineer.

Ralph R. Johnson
(Signature)
July 17, 1935 (Date)
Foreman L. & M. Co. - 7
(Title)

T. 150N R. 26W 5th Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a Cedar
tree 12 inches diameter, on the NE
side of Tree
from which this Corner bears $N 6\frac{1}{2}^{\circ} E$
82 chains distant.

Give any further facts which will aid in finding this
Corner again.

Corner located on
new ground and proposed
road center line.