

Post & Jack

U. S. Department of Agriculture

FOREST SERVICE

N-21

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 160N. R. 26W. 5th Mer.

SECTION Corner common to Sections

13, 14, 23, and 24

Corner consists of a WOODEN STAKE (not) in place

State condition Good

Dimensions above ground 2 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S	S	S	S
14	23	24	13

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

39.6
2
37.6

S 24	S 23		
BT	BT		

39.6
3.3
36.9

Species TAMARACK TAMARACK

Diameter 7 IN 10 IN

Bearing S.27 1/4° E S.37 1/2° W

Distance .57 CM .65 CM

Do you believe this to be a genuine Land Office Corner? _____

If not, why? RESURVEY BY COUNTY

ENGINEER.

Ralph B. Johnson
(Signature)

JULY 17, 1935
(Date)


FIREMAN, C.R.M. 60-7
(Title)

N-21

CORNER WORMEYAN SWAMP
ON TRAPPED ROAD CENTER
LINE

Corner again.

Give any further facts which will aid in finding this
chains distant.
1.65
from which this Corner bears
N. 37.0° E
side of
TREE
tree 10 inches diameter, on the
Metal Location Poster is on a TAMARACK



T 150 N R 26 W 5th P Mer.
(Make sketch of topography near corner)

U. S. Department of Agriculture

FOREST SERVICE

N-21

M

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N. R. 26 W. S. Mer.

Section Corner common to Sections

13, 14, 23, and 24

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S	S	S	S
14	23	24	13

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S
24

S
23

BT

BT

--

--

Species Tam. Tam.Diameter 7" 10"Bearing S 27° E S 37° WDistance 57 lks 65 lks

Do you believe this to be a genuine Land Office Corner?

If not, why?

Resurvey by county

Oregon

G. R. Johnson

(Signature)

7/1/25

(Date)

Foreman G. M. Clark

(Title)

*Locality is Swamp & on
boundary near center line*

Corner again.


Give any further facts which will aid in finding this
chains distant.

From which this Corner bears *N 37 1/2 E*

side of *tree*

tree 10 inches diameter, on the *N E*

Metal Location Poster is on a *Post*



(Make sketch of topography near Corner)