

435 site of 22K

U. S. Department of Agriculture

FOREST SERVICE

N-23

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N. R. 26 W. 5TH P. Mer.

1/4

Corner common to Sections

13, and 24

Corner consists of a WOODEN STAKE (not) in place

State condition GOOD

Dimensions above ground 3 x 3 x 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>S</u>		<u>S</u>	
<u>13</u>		<u>24</u>	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>	<u>1/4</u>		
<u>S 13</u>	<u>S 13</u>		<u>+</u>
<u>BT</u>	<u>BT</u>		

Species SPRUE BALSAM

Diameter 10 in. 6 in.

Bearing N 6 1/2° W. N 38 1/2° E

Distance .67 chs. .62 chs.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? RESURVEY BY COUNTY

ENGINEER

Ralph F. Johnson
(Signature)

JULY 17, 1935

(Date)

FOREMAN, GRM. CU-7

(Title)

N-23


CORNER BENT ON
PROPOSED ROAD CENTER LINE

Corner again.
Give any further facts which will aid in finding this
67 chains distant.

from which this corner bears
side of TREE

tree 10 inches diameter, on the SE

Metal Location Poster is on a SPRUCE



T. 150 N. R. 26 W. S. 24 P.M. (Please sketch or topograph near corner)

U. S. Department of Agriculture

FOREST SERVICE

N-23

Chipewena NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 26 W 52 Mer.

1/4 Corner common to Sections

13, and 24

Corner consists of a Wooden Stake (not) in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>		<u>1/4</u>	
<u>S</u>		<u>S</u>	
<u>13</u>		<u>24</u>	

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>	<u>1/4</u>		
<u>S 13</u>	<u>S 13</u>		
<u>BT</u>	<u>BT</u>		

Species Spicee Balsam

Diameter 10" 6"

Bearing N 63° 21' N 38° 45'

Distance 26.7 lks 6.2 lks

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Resurvey by County surveyor

R. R. Johnson

(Signature)

Surveyor of Mc47

(Title)

7/17/25
(Date)

N-23

*Corner set in ground
near center of road*

Corner again.

Give any further facts which will aid in finding this

chains distant.

.67

From which this Corner bears *86 1/2° E*

side of

tree

tree 10 inches diameter, on the *SE*

Metal Location Poster is on a *stone*

<p><i>Sec. 4</i></p>	<p><i>Sec.</i></p>
<p><i>Sec. 3</i></p>	<p><i>Sec.</i></p>

(Make sketch of topography near Corner)