

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST N-3

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 22 S. Mer.

1/4 Corner common to Sections
18, and 19

Corner consists of a Post (not) in place

State condition MARKED 1/4 S-18-1/4 S-19

Dimensions above ground 4.20" Dia. 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

45 18			

Species TAM.

Diameter 8"

Bearing N 100° W

Distance 45 LINKS.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

D. Sherman

(Signature)

1-31-34

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


71 LRS. chains distant.

from which this Corner bears N 2° E

side of

tree 4" inches diameter, on the

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

N-3 Mer.

T. 152 R. 27

Section Corners

1/4 (Gr.) 18-19

N3

150

R 27

Cor. 5th

Corner is


a Post

Height 20"

dia 3"

Marked 1/4 S 18

1/4 S 19



MARKING DATA

Size

1/4

Species

Tamm.

Diameter

8"

Spacing

N 10 W

District

45 Links

Total posts on

4" Birch 71 Links N 2 E

Remarks:

Date

1/31/34

Signed

G. Sherman

N-3

