

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST V-5

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 5 Mer.

See.

Corner common to Sections

29, 30, 31, and 32

Corner consists of a Post. (not) in place


7150-27-See 29-300-381-S-32.

Dimensions above ground 4 2/2" Dia 4" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter No B.T.

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

F. B. Ames.

(Signature)

2-18-34

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

12745 ~~distance~~-distant.

from which this Corner bears


side of

tree 14" inches diameter, on the

Metal Location Poster is on a

ASPEN

South




(Make sketch of topography near Corner)

Mer. V-5

T. 158 R. 27 5

Section Corners 29-30-31-32

T 150 R 27 Mer. 5th



Corner is a POST

Height 72"

Dia 4"

Marked T150 R27

S29 S30 S31 S32

BEARING TREES No B.Ts.

Marks _____

Species _____

Diameter _____

Bearing _____

District _____

Metal poster on Aspen 14" South

Remarks: 12h in R5

Date 2-13-34 Signed [Signature]

V-5

