

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

CHIPPEWA NATIONAL FOREST L-5

CORNERS OF THE PUBLIC SURVEY

T. 152 N R. 27 W 5th Mer.

4 Corner common to Sections
17, and 18

Corner consists of a WOOD STAKE (not) in place
 State condition FAIR

Dimensions above ground 2 1/2 x 2 1/2 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u> <u>S</u> <u>18</u>		<u>1/4</u> <u>S</u>
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 18

1/4 S 17

BT

BT

Species ASPEN ~~REDWOOD~~ N. PINE

Diameter 11" 7"

Bearing S 20° W N 43° E

Distance 0.25 0.29 ch

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

H. C. Norman
 (Signature)

Sept 6, 1935
 (Date)

Forest
 (Title)

FIRE TOWER

APPROX. 7 CH. SW. OF MOOSE LAKE

Corner again.

Give any further facts which will aid in finding this


0.24 chains distant.

from which this Corner bears S 82° E

side of TREE

tree 8 inches diameter, on the EAST

Metal Location Poster is on a WHITE PINE



(Make sketch of topography near Corner)

T 152 N. R. 27 W. 5th

Mer. L-5