

U. S. Department of Agriculture
 FOREST SERVICE
 P

Chippewa NATIONAL FOREST J-5

CORNERS OF THE PUBLIC SURVEY

 T. 150 R. 27 S. 5 Mer.
 Sec. Corner common to Sections

7, 8, 17, and 18

 Corner consists of a OAK post (not) in place
 State condition MARKED-S-7-S8-S-17-S18.

 Dimensions above ground H. 30" Dia 5" x 5"
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

 Sketch markings of Bearing Trees (or Rocks) in proper box and
 fill blanks below, giving bearings from Corner to Trees and
 Distances in Links.

 Species S. P. ROCE TAM. TAM.
 Diameter 5" 3" 8"
 Bearing S 22° W N 80° W S 40° E
 Distance 35 1/2 LKS. 6 LKS. 30 1/2 LKS.

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

L. Th. Johnson

(Signature)

1-30-34

(Date)

Surveyor


(Title)

Lined writing area for notes.

No Posters

Corner again.

Give any further facts which will aid in finding this chains distant. from which this Corner bears side of tree inches diameter, on the Metal Location Poster is on a



(Make sketch of topography near Corner)

