

U. S. Department of Agriculture
FOREST SERVICE

C⁹
posted

Wapiti NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 27W 5 Mer.

14 Corner common to Sections
4, and 5

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? No. 27. 1/2 sec. 14

is not a genuine corner

because of the

location of the corner

(Signature)

Jan 15 - 1934


(Date)

(Title)

C-9

Corner again.
Give any further facts which will aid in finding this

chains distant.
from which this Corner bears
side of Road
inches diameter, on the West
Metal Location Poster is on a Tel. Pole



(Make sketch of topography near Corner)
Mer. T. 150 R. 27 N. 9-9