

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST V-11

CORNERS OF THE PUBLIC SURVEY

T. 120 R. 27 5 Mer.

114 Corner common to Sections

28, and 33

Corner consists of a POST (not) in place

State condition good

Dimensions above ground 3' x 3" 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*L. D. Johnson*

(Signature)

*Surveyor*

(Title)

*1-23-34*

(Date)

V-11

-----  
-----  
-----


Cent of R.R. 740E  
of 1/4 cor. 28  
33

Corner again. of R.R. 7chs.  
NSW of 1/4 33

Give any further facts which will aid in finding this  
chains distant.

from which this Corner bears S 37° W

side of Tree  
tree 2 inches diameter, on the S.W.  
Metal Location Poster is on a BISSAM



(Make sketch of topography near Corner)

Mer. V-11

T. 150 R. 27 5