

U. S. Department of Agriculture

FOREST SERVICE

*R-11*  
*posted*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *150* R. *27* S. *5* Mer.

Corner common to Sections *14*, *21*, and *28*

Corner consists of a *POST* (~~not~~) in place  
State condition *good*

Dimensions above ground *3" x 3" x 30* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		S 21	
		B.T.	

Species *OAK*  
Diameter *10*  
Bearing *N 26° E*  
Distance *10 LKS*

Do you believe this to be a genuine Land Office Corner? *yes*  
If not, why? \_\_\_\_\_

*Lloyd W. Johnson*  
(Signature)  
*Jan. 23 - 1934*  
(Date)  
*Surveyor*  
(Title)  
*R-11*

Dark Bl. N 20' W. to top

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N 40 E

side of

tree 15 inches diameter, on the N.E.

Metal Location Poster is on a ~~board~~



(Make sketch of topography near Corner)