

U. S. Department of Agriculture

FOREST SERVICE

9

Chippewa NATIONAL FOREST E-11

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 22 5 Mer.

114 Corner common to Sections

4 and 9

Corner consists of a Post (not) in place

State condition good.

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

L. D. Johnson

(Signature)

1-15-34


(Date)

(Title)

E-11

Corner again.
 No B.T. found. Car can
 be located from road
 Notes Post North of
 Center of Road.

Give any further facts which will aid in finding this
 30 LMS ~~center~~ distant.
 from which this Corner bears
 S 60 E.
 side of Road.
 tree 8" inches diameter, on the North
 Metal Location Poster is on a
 Tel Pole



(Make sketch of topography near Corner)

Mer. E-11

T. 150 R. 27

5-