

U. S. Department of Agriculture

FOREST SERVICE

E 12
posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1504 R. 27 Mer. 5

E-116 Corner common to Sections
4, and 9

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

_____ (Signature)

Jan. 15-1934 (Date) _____ (Title) E-12

Can Can Be Located
Insect Road Nests

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of Road

tree 8 inches diameter, on the

Metal Location Poster is on a

Tel. pole



(Make sketch of topography near Corner)