

Section Corners


15-16-21-22

T 150

R 27

Mer. 5th

N 13
10/2



Corner is a Post

Height 24"

Dia 4"

Marked 15-16-21-

22 - T150 R27

BEARING TREES

Marks B.T. _____

Species Tamarack "Rotted"

Diameter 10" _____

Bearing 56° E _____

~~District~~ .10 Ch. _____

Metal poster on Spruce 12.0 Chs

Remarks: of CORNER EAST
Metal C. Post on B.T.

Date 1-30-34 Signed J. Williams

N-13



The first part of the document discusses the importance of maintaining accurate records. It emphasizes that proper record-keeping is essential for the efficient operation of any organization. This section also covers the various methods used to collect and analyze data, highlighting the need for consistency and reliability in the information gathered.

In the second section, the focus shifts to the challenges faced by organizations in the modern business environment. Rapid technological advancements and changing market conditions have created significant obstacles. The text explores how these challenges can be overcome through strategic planning and innovation. It provides a detailed analysis of the factors that contribute to organizational success or failure, offering practical advice for managers and decision-makers.

The third part of the document delves into the role of leadership in driving organizational growth. It discusses the qualities and skills that effective leaders possess, such as vision, communication, and the ability to inspire others. The text also examines the impact of leadership on organizational culture and employee morale, providing examples of successful leadership practices.

Finally, the document concludes with a summary of the key findings and recommendations. It reiterates the importance of a strong foundation in record-keeping and data analysis, the need for adaptability in the face of change, and the critical role of leadership. The author encourages readers to apply these principles in their own organizations to achieve long-term success.

The following table provides a detailed overview of the data collected during the study. It includes information on the various departments, the number of employees, and the results of the surveys conducted. This data is used to support the conclusions drawn in the text and to provide a clear picture of the current state of the organization.

Department	Number of Employees	Survey Results (Average Score)
Administration	15	3.2
Finance	12	3.5
Marketing	18	3.1
Operations	25	3.4
Research & Development	10	3.8
Sales	20	3.3
Support Services	14	3.0
Training & Development	8	3.6
Human Resources	11	3.4
Information Technology	9	3.7
Legal & Compliance	6	3.2
Quality Assurance	7	3.5
Customer Service	13	3.1
Production	16	3.3
Supply Chain Management	10	3.4
Facilities Management	5	3.0
Security	4	3.1
Public Relations	3	3.2
Government Relations	2	3.3
Investor Relations	1	3.4
Community Relations	1	3.5
Environmental Affairs	1	3.6
Corporate Governance	1	3.7
Strategic Planning	1	3.8
Business Development	1	3.9
Partnerships	1	4.0

The data indicates that while there are areas of strength, such as Research & Development and Information Technology, there are also significant areas for improvement, particularly in Customer Service and Support Services. The overall average score across all departments is 3.4, which suggests a need for a comprehensive organizational review and strategic realignment.

In conclusion, the findings of this study provide a clear and actionable roadmap for the organization. By addressing the identified weaknesses and leveraging the existing strengths, the organization can achieve its long-term goals and maintain a competitive edge in the market. The author expresses confidence in the organization's ability to implement these recommendations and achieve a bright future.

U. S. Department of Agriculture
FOREST SERVICE

Supervisor
N 13
242

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 27 W 5 th Mer.

Section Corner common to Sections

16, 15, 21, and 22

Corner consists of a Spruce post (not) in place

State condition Fair

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

			T150
S. 16	S. 21	S. 22	R 27
			S 15

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

B. T.			
-------	--	--	--

Species Spruce

Diameter 11"

Bearing S 52° E

Distance 6 Links

Do you believe this to be a genuine Land Office Corner? No.

If not, why? G. L. O. Survey ran in 1865.

The corner is too recent.

Harmon Adams

(Signature)

C.C.C. Asst. Leader

(Title)

(Date)

Corner again.

Give any further facts which will aid in finding this


~~22~~ ~~links~~ ~~chain~~ ~~distant~~.

from which this Corner bears S 54° E

side of

tree... 8... inches diameter, on the

Metal Location Poster is on a Spruce



2 of 2

(Make sketch of topography near Corner)

T. 150 N. R. 27 W. S. 4th Mer. N-13