

U. S. Department of Agriculture

FOREST SERVICE

9

Chippewa NATIONAL FOREST G-13

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 5 P. Mer.

1/4 Corner common to Sections 9, and 10

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	sec. 9		
	B.T.		

Species OAK.

Diameter 14"

Bearing N20°W

Distance 36 LKS.

Do you believe this to be a genuine Land Office Corner? yes.

If not, why?

L. H. Johnson.

(Signature)

Surveyor

(Title)

1-15-38

(Date)

Can be located from
Road notes

Corner again.

Give any further facts which will aid in finding this

chains distant.


36

from which this Corner bears S 20° E

side of Road

tree 1 1/4 inches diameter, on the North side.

Metal Location Poster is on a
OAK B.T.



(Make sketch of topography near Corner)

G-13

T. 150 R. 27 5 P. Mer.