

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

Chippewa NATIONAL FOREST R-21

CORNERS OF THE PUBLIC SURVEY

T. 151 R. 27 5th Mer.

Sec. Corner common to Sections
 23, 24, 25, and 26

Corner consists of a Balsam Poplar (not) in place
 State condition good.

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 26	S 23	S 24	S 25
---------	---------	---------	---------

B.T.	B.T.	B.T.	B.T.
------	------	------	------

Species Balsam Poplar Balsam Poplar Balsam Poplar

Diameter 7" 9" 8" 8"

Bearing N37°W N9°W N8°E N68°W

Distance 35.5 ft. 49.1 ft. 56.7 ft. 58 ft.

Do you believe this to be a genuine Land Office Corner? yes.

If not, why? _____


L. M. Johnson
 (Signature)

1-10-34
 (Date)

 (Title) R-21

Center Rail Road
675 chs. W.
Metal Postery 30" W
Center County 8" W
Corner again.

Metal Location Poster is on a
tree 7" inches diameter, on the
side of *Cor.*
from which this Corner bears
8 LKS. *shows distant.*
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)