

U. S. Department of Agriculture

FOREST SERVICE

M-21
posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 27 W Mer. 5

5-116 Corner common to Sections
14, and 13

Corner consists of a Post (~~not~~) in place

State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? 1

If not, why? _____

Floyd W. Johnson

(Signature)

Jan. 10, 1934

(Date)

Swiggin


(Title)

M-21

T. 150N R. 27W 5 Mer.

(Make sketch of topography near Corner)

M-21



Metal Location Poster is on a Tel. Pole

8" inches diameter, on the East

side of Road

from which this Corner bears 545° E

19 LKS chains distant.

Give any further facts which will aid in finding this

Corner again.

W-Rail of Track 27 LKS East

of Cor.

Cont. of County Road

West 154 LKS