

U. S. Department of Agriculture  
 FOREST SERVICE
 P

CHIPPENWIZ NATIONAL FOREST L-21

## CORNERS OF THE PUBLIC SURVEY

T. 150 R. 27 S. Mer.

 14 Corner common to Sections  
 14, and 13

 Corner consists of a Square post (not) in place  
 State condition Good

 Dimensions above ground 30 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

 Sketch markings of Bearing Trees (or Rocks) in proper box and  
 fill blanks below, giving bearings from Corner to Trees and  
 Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

 L. W. Johnson  
 (Signature)

 1-10-34  
 (Date)

(Title)

Can be located from  
County road notes.

Center County Road 50450 W  
West rail is 397 ft. E. of Post

Corner again.

Give any further facts which will aid in finding this


877 ft. S. ~~chain~~ distant.

from which this Corner bears  
N 86° E

side of Road

tree 5 inches diameter, on the West

Metal Location Poster is on a Fence Post



(Make sketch of topography near Corner)

L-21

Mer.

T. 150 R. 27 5