

U. S. Department of Agriculture

FOREST SERVICE

E-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *150* R. *27* *5 P.* Mer.

1/4 Corner common to Sections

1, and *12*

Corner consists of a *Fence Post* (not) in place

State condition

Dimensions above ground *H. 48" Dia. 7"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

L. St. Johnson

(Signature)

2-5-34

(Date)

Surveyor

(Title)

Fence West
Fence South
MR. Wm. HAINES put fence
post in place of 1/4 cor.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a *Corner*.



(Make sketch of topography near Corner)

E-23

T. 150 R. 27 5 P. Mer.

423 posted


Section Corners

1/1 of 1 and 12

15 ON

27

5 PM



Facing to

Fence Post

Height 48"

Dia. 7"

Notes

No Marks

Section

Area

Species

Quantity

Location

District

Total posted as CORNER

Fence West

Fence South

1/4 W. Haives Put Fence Post in place of 1/4 cor.

2-5-34

H. W. Johnson

YE-23

[Faded text, possibly header information including a date and title]

[Faded text, possibly a list or table of data, mostly illegible due to scan quality]