

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST V-25

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 22 S. Mer. Sec.



Corner common to Sections 25, 36, 30, and 31

Corner consists of a Post (not) in place State condition

Dimensions above ground 420" D. 2" inches Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species TAM. Diameter 11" Bearing S 62° W Distance 12 LKS.

Do you believe this to be a genuine Land Office Corner? yes.

If not, why?

J. B. Ames (Signature)

2-5-34 (Date)

(Title)

41.5 chs. North.

Andan Fence Post

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of Due East

tree ~~inches diameter~~, on the

Metal Location Poster is on a BIRCH



(Make sketch of topography near Corner)

Mer V-25


T. 156 R. 27

5

V-25 Post

Section Corners 75-36-30-31

T 150 R 27 Mer. 5ch
36



Corner is a POST

Height 20"

Dia 2"

Marked None

BEARING TREES

Marks 150
R-27
36

Species Tarr

Diameter 11"

Bearing 56° 21'

District 136

Metal poster on Birch 4ch
DOE

Remarks: EAST AND ON
FENCE POST 41.50-41.5 N

Date 7-5-34 Signed [Signature]

V-25

Faint, illegible text on the left side of the page, possibly bleed-through from the reverse side.



Multiple columns of faint, illegible text on the lower half of the page, likely bleed-through from the reverse side.

Faint text at the bottom of the page, possibly a footer or page number.