

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 5 Mer.

1/4 Corner common to Sections
 19, and 20

Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		1/4 S-20	
		B.T	

Species _____ Elm _____
 Diameter _____ 7" _____
 Bearing _____ S E _____
 Distance _____

Do you believe this to be a genuine Land Office Corner? *yes.*

If not, why? _____

Carl Hobbs

(Signature)

Estimator

(Title)

12-22-23

(Date)

E. T. B. I. 222

ON ROAD CORNER

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

NO POST CH AVAILABLE

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 150 R. 28 5 Mer.