

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 S Mer.

47

Corner common to Sections

29, and 32

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

H. Adams
(Signature)

12/12/34
(Date)

U. S. Department of Agriculture

FOREST SERVICE

V7

Chippewa

NATIONAL FOREST

Posted

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 28W 5th Mer.

Quarter Corner common to Sections

29, and 32

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

No Bearing Trees			

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?

A. Adams (Signature)

Asst. Leader (Title)

12/12/34 (Date)

(Date)

V-7

