

U. S. Department of Agriculture  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150N R. 22W S. 5th Mer.

Section 5 Corner common to Sections  
28, 27, 33, and 34

Corner consists of a 5 pruc Post (not) in place  
State condition Good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|   |   |   |   |
|---|---|---|---|
|   |   |   |   |
| N | W | S | E |

|      |      |      |      |
|------|------|------|------|
|      |      |      |      |
| S-28 | S-33 | S-34 | S-27 |
| NW   | SW   | SE   | NE   |

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|                       |    |    |  |
|-----------------------|----|----|--|
| 1-150<br>R-28<br>E-27 |    |    |  |
| BT                    | BT | BT |  |

Species ASP Spruce Ash  
Diameter 7 1/2 2 1/2 4 1/2  
Bearing N150E S10W N16W  
Distance 47 63 32

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Too Recent

Harrison Adams  
(Signature)

(Date)

(Title)

.....

.....

.....

.....

.....

.....

.....


.....

.....

.....

Corner again.

Give any further facts which will aid in finding this  
 ..... chains distant.  
 from which this Corner bears  
 side of  
 tree ..... inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 5 Mer.  
 Sec. Corner common to Sections

27, 28, 33, and 34

Corner consists of a Spruce Post in place

State condition good

Dimensions above ground 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|   |   |   |   |
|---|---|---|---|
|   |   |   |   |
| N | W | S | E |

|          |         |         |         |
|----------|---------|---------|---------|
| S.<br>28 | S<br>33 | S<br>34 | S<br>27 |
| NW       | SW      | SE      | NE      |

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|       |      |      |  |
|-------|------|------|--|
| T-150 |      |      |  |
| R-28  |      |      |  |
| S-27  |      |      |  |
| B.T.  | B.T. | B.T. |  |

Species Aspen Spruce Ash

Diameter 7" 20" 13"

Bearing N150E S10W N160W

Distance 47LKS. 63LKS. 32LKS.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Corner appears too recent for a corner.

Harrison (Signature)

12/19/34 (Date)

Asst. Leader (Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 157 R. 28 Mer. 5

U. S. Department of Agriculture  
FOREST SERVICE

V-13

Chippewa Co. NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 N R. 28 W 5th Mer.



Section Corner common to Sections  
28, 27, 33, and 34

Corner consists of a spruce post (not) in place  
State condition good

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|                         |       |       |  |
|-------------------------|-------|-------|--|
| T-150N<br>R-28W<br>S-27 |       |       |  |
| B. T.                   | B. T. | B. T. |  |

Species Aspen spruce Ash  
Diameter 7" 20" 12"  
Bearing N15° E S1° W N16° W  
Distance 47 Li. 63 Li. 32 Links

Do you believe this to be a genuine Land Office Corner? No  
If not, why? Corner appears too recent for  
B. L. O. corner.


*Hudson Adams*  
(Signature)

12/19/34  
(Date)

Asst. Leader  
(Title)

V-13

Metal Location Poster is on a tree.....inches diameter, on the side of ..... from which this Corner bears ..... chains distant.  
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)