

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 S. 5 Mer.

Sec Corner common to Sections

2, 3, 10, and 11

Corner consists of a Stake (not) in place



State condition poor

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? When the road was
built S & K was
thrown aside road

[Signature]

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

Approx 66' ~~from~~ distant.


from which this Corner bears

S-20-E

side of Road

tree 4 inches diameter, on the south side

Metal Location Poster is on a ASPAN



(Make sketch of topography near Corner)

Mer.

T. 150 R. 28 5