


V19 *posted*

Section Corners 1/4 of 26th 1st

R 38



Corner 38

1st

2nd

3rd

4th

5-35

Section

Area

38

Notes

Aspen

Number

12

Bearing

N 71° E

District

37

Notes on Aspen

Remarks: Aspen

2-14-34

V19

SECRET

SECRET

SECRET	SECRET	SECRET	SECRET	SECRET
SECRET	SECRET	SECRET	SECRET	SECRET
SECRET	SECRET	SECRET	SECRET	SECRET
SECRET	SECRET	SECRET	SECRET	SECRET
SECRET	SECRET	SECRET	SECRET	SECRET
SECRET	SECRET	SECRET	SECRET	SECRET

SECRET

SECRET

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 5 Mer.

1/4 Corner common to Sections
26, and 35

Corner consists of a post (not) in place

State condition 4x4" - 36"

Dimensions above ground 1/4 S - 26 1/4 S - 35 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S.			
B.T.			

Species Aspen

Diameter 12"

Bearing N77°W

Distance .07.

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

L. Th. Johnson

(Signature)

2-14-34


(Date)

(Title)

V-19

Corner again.
Post on hill logging
Road 8 LKS. North of Cor.

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 150 R. 28 Mer. 5