

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 37 Mer.

Sec. Corner common to Sections 11, 12, 13, and 14

Corner consists of a Post (not) in place

State condition T 150 R 28 W. 3-11-S-12.

Dimensions above ground 4"x4" 30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

L. Th. Johnson

(Signature)

2-7-34

(Date)

(Title)

513+14 billed.

And Metal Poster on
Maple Tree 21.41 chs.
South of cor. $\frac{1112}{1113}$

bears S-69°W. 81 chs.

Poster also on Balsam 5" Dia.
Corner again.

Give any further facts which will aid in finding this


211 chs. seems distant.

from which this Corner bears
N 60° W

side of

tree 1/4" inches diameter, on the

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 150 R. 28 S. Mer.

521

posted

Station Corners

11, 12, 13, 14


150

R

28

Mer.

5



Corner is

Post

Height

30"

Dia

4" x 4"

Marked

T-500

R 28 LU 5-11-54

BEARING TREES

Species

Diameter

Bearing

District

Metal poster on

Birch 14" N 60 W 31 1/2'

marker

Balsam 5" S 63 W 8 1/2'

Metal poster on Maple Tree

21.4' Ch south of cor 4/3

Date

2-7-34

Signed

Howard W. ...

521

