

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 150 R. 28 5 Mer.

14 Corner common to Sections 13, and 24

Corner consists of a Post (not) in place

State condition 3"x4" 32"

Dimensions above ground 45-13 45-14 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter B.T. = not found.

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

L. Ph. Johnson

(Signature)

Surveyor

(Title)

2-13-34

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


20

from which this Corner bears N 25° W.

~~side of The cor.~~

~~tree inches diameter on the spot from~~

Metal Location Poster is on a East side of Birch



(Make sketch of topography near Corner)


T. 150 R. 28 Mer. 5

N23

posted

Section Corners 1/4 13 14

150 R 28 Mer. 5



Corner 20

215

Height 32

W. 3" x 4"

Marked 14-5-37

14-5-37

MEASURING DATA

	No	Dist	Angle	Area
Mark	_____	_____	_____	_____
Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
District	_____	_____	_____	_____

Initial poster on East side

Remarks: Stub iron stake in hole
600' N 23° W - 20 00'

Date 2-15-37 Signed Lloyd Johnson

N-23

[Illegible text]

[Illegible text]