

CORNER
RESTORATION
T145N R25W



MINING
TRANSIT BOOK

No. 3844

Book 1

CORNER RESTORATION T145N R25W

All Pages


ARE

Blank

D.R. District

Survey in back of book

Do Not
Film



FS3 168-48-30
BS1 00-00-00
π@2 168-48-30

348-48-52
180 00 20
168 48-32

168-48-31

VA2-1 89-15-27 ✓ 270-44-17
2-3 90-58-00 269-01-42

254.745 77.649
378.02 115.222

FS4 231-45-35
BS2 00-00-20
π@3 231-45-15

51-45-57
180-00-37
231-45-20

231-45-18

VA3-4 90-41-30 ✓ 269-10-28

108.09 32.946

FS5 140-50-45
BS3 00-00-20
π@4 140-50-25

320-51-10
180-00-59
140-50-17

140-50-21

VA4-5 90-10-10 ✓ 269-49-44

125.62 38.290

FS6 210-53-20
BS4 00-00-05
π@5 210-53-15

30-53-37
180-00-25
210-53-12

210-53-14

VA5-6 90-42-40 ✓ 269-17-17

94.095 28.682

N
↑

DR district office

SP 2.95' south
SP 3.55' East

Highway

SP 3.6' East

SP 6.3' north
SP 3.20' west

Trailer court