

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
C	+	6	+			+	5	+		+	4	+		+	3	+		+	2	+		+	1	+	●
D	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
E																					●	●	●	●	●
F	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
G	+	7	+			+	8	+		+	9	+		+	10	+		+	11	●	●	●	●	●	●
H	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
J																			●	●	●	●	●	●	●
K	+	+	+			+	+	+		+	+	+		+	+	+		+	●	●	●	+	+	+	+
L	+	18	+			+	17	+		+	16	+		+	15	+		+	14	●	●	●	●	●	●
M	+	+	+			+	+	+		+	+	+		+	+	+		+	●	●	●	+	+	●	●
N																			●	●	●	●	●	●	●
O	+	+	+			+	+	+		+	+	+		+	+	+		+	●	●	+	+	●	+	●
P	+	19	+			+	20	+		+	21	+		+	22	+		+	23	+		+	●	+	●
Q	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	●	+	●
R																					●	●	●	●	●
S	+	+	+			+	+	+		+	+	+		+	+	+		+	●	●	+	+	●	+	+
T	+	30	+			+	29	+		+	28	+		+	27	+		+	●	●	●	●	+	+	25
U	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
V																									
W	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
X	+	31	+			+	32	+		+	33	+		+	34	+		+	35	+		+	36	+	+
Y	+	+	+			+	+	+		+	+	+		+	+	+		+	+	+		+	+	+	+
Z																									

LEGEND

○ = Corner having information on farm 7100-52 in this file.


T143N R31W 5th PM

FILING INSTRUCTION

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.



Index No. A-21
(Alphabetical - Numerical)

LAND CORNER SURVEY
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143N R. 31W 5th Mer. N.F. Chip. County Cass State MN.
Section 1 Corner common to sections 1 and 36

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument 3' x 3" square 4' high cedar stake
(Wood post, stone, pile of stones, pipe, etc.)

Species	Bearing Trees			
<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
<u>8</u>	<u>6</u>	<u>7</u>	<u>6</u>	
<u>S61W</u>	<u>N69W</u>	<u>S43E</u>	<u>N48E</u>	
<u>351Ks.</u>	<u>51Ks</u>	<u>55Ks</u>	<u>361Ks</u>	
<u>23.10</u>	<u>3.30</u>	<u>36.30</u>	<u>23.76</u>	

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded C.R.D.
Monument 3' long x 2" diam set 28" in ground with brass cap.
(Original, concrete spat., or red, etc.)

Species	Bearing Trees, Reference Objects			
<u>TAM</u>	<u>Cedar</u>	<u>TAM</u>	<u>Spr</u>	<u>Spr</u>
<u>10"</u>	<u>6"</u>	<u>10</u>	<u>5 2/51</u>	<u>4 1/1919</u>
<u>N45E</u>	<u>S67E</u>	<u>S53W</u>	<u>N29W</u>	
<u>261Ks</u>	<u>561K</u>	<u>35Ks</u>	<u>111K</u>	
<u>17.16</u>	<u>36.96</u>	<u>23.10</u>	<u>7.26</u>	

Original Evidence Found

Year of search 1919 By GLO
Monument found wood post with scribe
scribe visible 3' x 3" x 4'


Original Bearing Trees Found

Species	Original Bearing Trees Found			
<u>TAM</u>	<u>TAM (Dead)</u>	<u>TAM spr</u>	<u>TAM spr</u>	
<u>14</u>	<u>8"</u>	<u>10"</u>	<u>10"</u>	
<u>N45E</u>	<u>S40°E</u>	<u>S61W</u>	<u>N80°W</u>	
<u>361Ks</u>	<u>551Ks.</u>	<u>351Ks</u>	<u>51Ks.</u>	
<u>23.76</u>	<u>36.30</u>	<u>23.10</u>	<u>Orig was 69W</u>	

Evidence of Subsequent Corner Restoration Found

Year of search 2/7/90 By Brama, Main, Minich
Fd. 2" x 36" I.P. with B.C. laying ^{west} under ground about 1".
Stood straight up.
Fd. remains or well rotted cedar post. Fd. pt. of a two-inch wood point

Species	Bearing Trees, Reference Objects		
<u>Cedar</u>	<u>TAM - rotted spr.</u>	<u>Spruce</u>	<u>well ro.</u>
<u>12"</u>	<u>6"</u>	<u>10"</u>	<u>10"</u>
<u>N47E</u>	<u>S52°W</u>	<u>N29W</u>	
<u>36.96</u>	<u>3.10'</u>	<u>7.26</u>	
<u>Fd. scribe</u>	<u>Fd. scribe</u>		



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-21

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Corner falls in a TAM & Cedar Swamp.
 Rest GLO monument a foot high with a
 8' sign post driven down. No S.E. C.P. (7').
 Sign post was I.P.
 GLO cedar cut down to find corner.
 GLO cedar. BT had two old F.S. I.P.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. L.T.S.

3. Man hours spent in search 1 Hr

4. Do you think additional search might
 recover evidence? Yes _____ No

5. Signature Larry Bruma

Perpetuation Record

Monument and accessories established. Include brief description of area.

MKD W.
 Cedar 8" N75° E 2.1" MKD T144 NR31W
 F.S. 6" N 31° E 8.1" T144
 TAM 9" 38.5"
 TAM 1" SITE 38.5" MKD T144 NR31W
 Sign posts with both signs: W. 2.6' & S. 2.8';
 N. 3.5' - E. 0.4'
 Line cut is too F.S. STANDARD

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

T. 113 R. 30-31 5 Mer. N.F. Chippewa County Cass State Minn
1 Corner common to sections 1, 6, and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
 Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species TAMARACK TAMARACK
 Diameter 3" 5"
 Bearing N44W N82E
 Distance 54 20

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search 1966 By BROWN, -MARTINSON
 Monument found No Evidence Found


Original Bearing Trees Found

Species TAMARACK TAMARACK
 Diameter 5" 8"
 Bearing N44W N82E
 Distance 54 20

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

S - 1



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Compass-Chaining

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes No _____

5. Signature Jerry E. Martinez

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 30-31 Mer. N.F. Chippewa County Cass State Minn
N 1/16 Corner common to sections 1 6 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed UNKOWN By UNKOWN

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____


Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1966 By BROWN, -MARTINSON**BRASS CAP****TAMARACK** **TAMARACK**Stub 4" Stub 4"N40W S85E15 45



Sketch

○ Corner ▨ F.S. Land

○ F.S.

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No **X** _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. **Compass, -Chaining**

3. Man hours spent in search **None**

4. Do you think additional search might recover evidence? Yes _____ No **X** _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

5. Signature **Jerry E. Martinson**

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. E-21
(Alphabetical or Numerical)Book 1
Pg 70LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 602-127T. 143N S. 31W 5th Mer. N.F. Chp. County LTW State MN
Section Corner common to sections 1, 2, 11 and 12

EXISTING SURVEYS

Original Government Survey

Year surveyed 875
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	TAM	TAM	TAM
Diameter	9"	9"	8"
Bearing	S 73° E	S 11° E	S 82° W
Distance	38 1/2	33 1/2	22 1/2

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded St. Paul
Monument 2" x 36" I. P. with B.C.
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	TAM	T. stake	Jamaica	
Diameter	6"	4"	5"	
Bearing	N 49 1/2° E	S 11 1/2° E	S 7 1/2° W	N 41° W
Distance	16.78	31.66	17.82	15.18

Original Evidence Found

Year of search 1919 By GLO
Monument found TAM. BT with scribe marks

Original Bearing Trees Found


Species	Jamaica		
Diameter	Stump		
Bearing	S 11° E		
Distance			

Evidence of Subsequent Corner Restoration Found

Year of search 1919 By GLO
Fd. old metal 1/2" x 1 1/2" N 18° E. This given
to Paul [unclear] place. Stump
straight up and base it. 1" high
Fd. 1 1/2" diam wood post about 5' long
along rd.

Bearing Trees, Reference Objects

Species	TAM. scribe	TAM Stab	
Diameter	6"	6"	
Bearing	N 50° E	N 41° W	
Distance	21.78	15.18	



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

E-22

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Corner falls in a cedar ^{black spruce} swamp.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. COMPASS

3. Man hours spent in search 1:5

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Dary Brian

Perpetuation Record

Monument and accessories established, include brief description of area.

MKD, NEW BT'S, Cedar, S66°W, MKD, Wt₆ 512 BT.
 Cedar N20°W MKD, Wt₆ 51 BT. BK. Sp₅ 87 E MKD Wt₆ 512 BT
 FSLP on a Black Spruce, 8", S51°E at 15.39'
 Sign posts with both signs ea 72.30' & south 1.85'
 I. P. was set by proportionate distance and on line between sect. on corner 1, 2, 11, 12 and 4 & 13.
 (See traverse field book).
 Line east is to f. s. SPAN, S.C. 1313.07 Wt₆ 1313.07 4

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. E-23
(Alphabetical - Numerical)Book
pg 71LAND CORNER SURVEY
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 802-127

T. 143N 31W 5th Mer. N.F. Chip County Cass State Mn
Quarter Corner common to sections 1 and 13

EXISTING SURVEYS

Original Government Survey

Year surveyed _____ By _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species N. Pine N. Pine _____Diameter 6" 4" _____Bearing N51W S7E _____Distance 101.15 36.11 _____
6.60 22.76

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found


Species N. Pine N.P. Stk. _____Diameter 12" 12" _____Bearing S7E N81W _____Distance 117.48 98.39 _____
117.48 98.39

Evidence of Subsequent Corner Restoration Found

Year of search 1912 By BRAMA, W. N. & OkleyFd. I. P. on 4th E. 1" pipe set6" iron pipeFd. N. Pine Stk. at 58° E, N. Pine Stk.at 57° E and stump hole at N81W.Fd. F.S.L.P. on 10" R.P., 4 1/2"

Bearing Trees, Reference Objects

Species N.P. GLO N.P. N.P. Stump HoleDiameter 13 Stk Stk _____Bearing N51W S7E S8E N81WDistance 6.60 23.76 117.48 98.39



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

E-23

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. compass

3. Man hours spent in search 2.5 hr

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Bary Burns

Perpetuation Record

Monument and accessories established. Include brief description of area.

Mkd. 2 New B.Y.'S:
 1. N. PINE 13" S64E 47' 80" V4 92 BT
 2. N. PINE 13" S14W 26' 77" V4 512 BT
 Put up new F.S. L.P., N. Pine, 10, S48E at 2.69.

line to STANDARD WEST.
 Signs pts west 4.25' & on + 4.25' with both signs

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

BOOK # 1
PAGE # 71

T. 143 R. 31 S. 5 Mer. N.F. Chippewa County Cass State Minn
Corner common to sections I, 12, and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species N Pine N Pine
Diameter 12" 12"
Bearing S8E N81W
Distance 178 149

Original Evidence Found

Year of search 1966 By BROWN, -MARTINSON
Monument found none

Original Bearing Trees Found

Species No evidence found
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded _____
Monument Iron Post
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1966 By BROWN, -MARTINSON


Iron Post

Bearing Trees, Reference Objects

Species N Pine N Pine
Diameter 6" 8"
Bearing N51E S74E
Distance 10 36

N Pine N Pine

12" Stump
N51E S74E
10 36



Sketch

O Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Chaining-Compass

3. Man hours spent in search None

4. Do you think additional search might
 recover evidence? Yes _____ No X

5. Signature MARTINSON

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 30-31 Mer. N.F. Chippewa County Cass State Minn
 S Corner common to sections 1, 6, 7 and 12

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

	Bearing Trees			
Species	<u>TAMARACK</u>	<u>CEDER</u>	<u>CEDER</u>	<u>CEDER</u>
Diameter	<u>12"</u>	<u>8"</u>	<u>12"</u>	<u>4"</u>
Bearing	<u>N41E</u>	<u>S8E</u>	<u>S20W</u>	<u>N35W</u>
Distance	<u>24</u>	<u>44</u>	<u>43</u>	<u>45</u>

Original Evidence Found

Year of search 1966 By BROWN, -MARTINSON

Monument found none

	Original Bearing Trees Found	
Species	<u>CEDER</u>	<u>CEDER</u>
Diameter	<u>14"</u>	<u>12"</u>
Bearing		
Distance		

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____


Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____



Sketch F.S.

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. Compass-Chaining

3. Man hours spent in search 2

4. Do you think additional search might
 recover evidence? Yes No _____

5. Signature Jerry E. Martin

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

r. 145 N. r. 31 W 5th Mer. N.F. Chip County Las State IN
North 1/4 Corner common to sections _____ and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 8/1/33 GB-RM-JB.
 Original monument set "x" 10" 92
(wood post, stone, pile of stones, pipe, etc.)
 Bearing Trees
 Species TAM TH17 Cedar T143NR3
 Diameter 9" 8" 7" 1 1/2"
 Bearing S74W N6E S6E 12
 Distance 21.17 19.78 35.94 1.1

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

F-21

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Corner 11 to 12

At time of search:

1. Did you have the record description?
 Yes No _____

3. L.P. 2 TALL " 36 E
 Sign at 127 South Ave 1284 East (Both signs)

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. _____

Perpetuation Record

Monument and accessories established. Include brief description of area.

Mkd. New G.T.
 TAM. 74W-M. N 1/4 S 1/4 G.T.
 2. TAM. N 1/4 E " N 1/4 S 1/4 G.T.
 Cedar 1/4 E N 1/4 S 1/4
 on a 1/4 1/4 at 1247.00
 1247.00

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

5. Signature Mary Brana

Identified on aerial photo No. _____ Which is filed at _____

Index No. G-20
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143N R. 31W Mer. N.F. Chipp County CASS State MIN.
CORNER EAST Corner common to sections _____ and 11

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded St. Paul

Monument 1" x 3/8" I.P. with BE
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 8/5/20 By Erma Haines

Ed. Co. chn at bearing + d. corner

Fd. 1" x 3/8" I.P. monument

found men

Flanges on


Found

Bearing Trees, Reference Objects

Species	<u>Blk. Ash</u>	<u>Blk. Ash</u>
Diameter	<u>14"</u>	<u>12"</u>
Bearing	<u>S150°E</u>	<u>N28°W</u>
Distance	<u>100 Iks.</u>	<u>70 Iks.</u>
	<u>66"</u>	<u>46.20</u>

Bearing Trees, Reference Objects

No GLO B.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

G-20

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Steamboat Bay approx. 300 west of corner

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps
 etc. _____

Compass

3. Man hours spent in search 15 M.A.

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Jay [unclear]

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

New 1/2
 1. A. 48.9', N53W°, MKD CEY, S BT.
 2. Ash, 7', 25.44', N6°W. MKD CEY, S BT.
 3. Ash, 10', 73.08', S54W. MKD CEY, S BT.

FS & P in Elm, 7", 10.05', N41W Line 0 + 1.
 Rest mon. 30' in ground. F.S. 11/13/11
 in posts east with both signs.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. G-21
(Alphabetical - Numerical)Book 1
Pg 68LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 803-127T. 143 N. R. 31 W. 5th Mer. N.F. Chic County Cass State Mn.
Corner common to sections 11 12 and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species J.P. J.P.
Diameter 7" 9"
Bearing S 77° E N 79° W
Distance 71.166' 27.165'

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded St. Paul
Monument 1" A36" I.P. with B.C.
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Red P White P
Diameter 14" 18"
Bearing N 83° E N 45° W
Distance 4.62' 19.80'

Original Evidence Found

Year of search 1919 By GLO
Monument found Two original B.T.'s.

Original Bearing Trees Found


Species JACK P White P - does not check
Diameter stump 18" with orig. J.P.
Bearing S 77° E N 45° W call
Distance 46.86' 19.80"

Evidence of Subsequent Corner Restoration Found

Year of search 8/7/80 By Barbara M. Hain, M.D.
Red GLO mon. in place set 2" above
top.
1" GLO Red Pin 2" from
location. Scribe visible

Bearing Trees, Reference Objects

Species P. Pine W.P. stp.
Diameter 22"
Bearing N 83° E N 46° W
Distance 4.62' 19.80'



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

G-21

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any.

F.S. trail on south of corner approx.
 400', F.S.P. next to trail.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. L.T.S.

3. Man hours spent in search 0

4. Do you think additional search might
 recover evidence? Yes _____ No

5. Signature Navy Brana

Perpetuation Record

Monument and accessories established. Include brief description of area.

1. New BT's!
1. R. OAK, 7" 52" at MKd 1/4 911 BT.
 2. R. Pine, 7" N37W at 34.91.
 3. R. Pine, 21" N11W at 71.57.

Sign posts with both signs north & west.
 Lines north & west to F.S. STANDARD.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Minn
5 Corner common to sections 11, 12 and _____

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)
 Bearing Trees
 Species _____
 Diameter _____
 Bearing N 1/2 W
 Distance _____

Original Evidence Found
 Year of search 1966 By BROWN, -MARTINSON
 Monument found none
 Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____


Subsequent Corner Restoration
 Year surveyed 1919 By GLO
 Where filed or recorded _____
 Monument Iron Post
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found
 Year of search 1966 By BROWN, -MARTINSON
Iron Post

Bearing Trees, Reference Objects
 Species N Pine W Pine
 Diameter 14" 18"
 Bearing N85E N45 1/2 W
 Distance 7 30

N Pine W Pine
22" 24"
N85E N45 1/2 W
7 30

S-11



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes No

2. How was search area located?

Pacing, chaining, photos, maps,

etc. COMPASS-CHAINING3. Man hours spent in search NONE4. Do you think additional search might
recover evidence? Yes No 5. Signature Larry E. Martin

Relation of Evidence to Record Features Along Section Lines

Section line to sections -----

Object -----

Record distance -----

Measured distance -----

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes No

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 N R. 31 W Mer. N.F. 5th Chip County Cass State MN
Center West 1/2 Corner common to sections _____ and 12

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By Geo

Where filed or recorded Paul

Monument 1" x 3/8" I.P. W
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By BRADLEY


set 2" above gr. with BC.
Iron st. in
Ed. of GLO BT'S. Both trees are
dead with scribe visible.

Bearing Trees, Reference Objects

Species	<u>J.P.</u>	<u>J.P.</u>
Diameter	<u>6"</u>	<u>4"</u>
Bearing	<u>N60°E</u>	<u>S26°E</u>
Distance	<u>95'</u>	<u>73.4'</u>

Bearing Trees, Reference Objects

Species	<u>J.P. stb.</u>	<u>J.P. stb.</u>
Diameter	<u>11"</u>	<u>12"</u>
Bearing	<u>S26°E</u>	<u>N60°W</u>
Distance	<u>73.92</u>	<u>62.7'</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

G-22

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Young thick ASPEN all around corner.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps, etc. *Compass*

3. Man hours spent in search *1 hr*

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature *Nancy Brown*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MRD. NEW BT'S:
 1. W. Pine, 10" N 23° E at *17.53* CW 1/4 S 12 BT. *MRD.*
 2. W. Pine, 10" S 13° E at *26.79* CW 1/4 S 12 BT
 3. Pine, 6" N 34° N at *41.17* E 1/2 1651 BT

*Est. on 5" W. Pine N 42° W at *2.2* ...
 Cut both GHO BT trees with a slanted top for
 water drainage.*

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 30W Mer. N.F. CHITPEWA County CASS State MINNESOTA
CENTER WEST SIXTEENTH Corner common to sections 12 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1924 By U.S. GLO
Where filed or recorded _____
Monument BRASS CAP C WEST SECTION 12
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species ELM ASPEN
Diameter 8" 5"
Bearing N75°W S19°30'W
Distance 76LKS 51 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1963 By Lultgers & GAMACHE
BRASS CAP FOUND

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. COMPASSING

3. Man hours spent in search 1/2 HR

4. Do you think additional search might recover evidence? Yes _____ No X

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____
PAINTED A BLUE LINE TO THE EAST AND ALSO ONE TO THE NORTH
ON THE PROPERTY LINE

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

BOOK # 1
PAGE # 63

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Minn
C1 Corner common to sections 12 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument Iron Post 1' Long 1" Diam
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1966 By BROWN, -MARTINSON


Iron Post

Bearing Trees, Reference Objects

Species	<u>N Pine</u>	<u>J Pine</u>
Diameter	<u>20"</u>	<u>6"</u>
Bearing	<u>N31W</u>	<u>N17E</u>
Distance	<u>198</u>	<u>84</u>

FALLEN DOWN

N Pine	J Pine
<u>20"</u>	<u>12"</u>
<u>N31W</u>	<u>N17E</u>
<u>198</u>	<u>84</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Compass-Chaining

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes _____ No X

5. Signature Jerry E. Masterson

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Mn
CE 1/16 Corner common to sections 12 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 GLC

Original monument 1" x 36" brass cap monument
(wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Aspen Jackpine

Diameter 6" 14"

Bearing S 70 1/2° E N 61 1/2° W

Distance 46 lbs. 105 lbs.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 12-27-82 By Walter Curo + Ken Mitchell
found monument bent over - no Bt B - Set 2" x 5" brass cap monument in place of bent pipe

Bearing Trees, Reference Objects

Species _____


Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>W. Oak</u>	<u>Poplar</u>	<u>Poplar</u>
<u>10"</u>	<u>9"</u>	<u>10"</u>
<u>N 55° E</u>	<u>S 32° E</u>	<u>S 30° W</u>
<u>87.17</u>	<u>40.20</u>	<u>36.83</u>



Sketch

○ Corner F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CERTIFICATE FILED

Certified corner restoration certificate prepared: _____

Yes Walter Cure No _____

Filed in county records at Carroll

Date 7/8/83

County Document No. 268840


Identified on aerial photo No. _____

Which is filed at _____

T. 143 R. 31 Mer. N.F. Chippewa County Cal State MN
E 1/4 Corner common to sections 12 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1919 G.L.O.</u>	Year of search _____ By _____
Original monument <u>1" x 36" brass cap monument</u> <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species <u>Aspen Aspen</u>	Species _____
Diameter <u>4" 9"</u>	Diameter _____
Bearing <u>S 83 E S 37 W</u>	Bearing _____
Distance <u>37 lbs. 80 lbs.</u>	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>3-4-83</u> By <u>Walter Cure &</u>
Where filed or recorded _____	<u>Ken Nuttall could not find original monument bc BT's - Set 2" x 36" iron pipe with brass cap flush with ground in ditch bottom - on line with SE corner plos. on S 1/4 corner at proportional distance - Bearing + distance west to CE 1/4 corner checks with Govt bearing + distance.</u>
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<u>W. Oak W. Oak White Oak</u> <small>8" 5"</small>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	<u>S 52 W N 50 E S 2 E</u>
Diameter _____	<u>57.27 127.32 78.54</u>
Bearing _____	
Distance _____	



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CERTIFICATE FILED

Certified corner restoration certificate prepared: *by Walter Curo* Yes No

Filed in county records at Case Date 5/8/83 County Document No. 268850

Identified on aerial photo No. _____ Which is filed at _____

5. Signature _____

Index No. H-25
(Alphabetical - Numerical)

143 30 (Book # 10)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143W R. 31W S. 5 Mer. N.F. CHIPPewa County CASS State MINNESOTA
S 1/16 Corner common to sections 7 and 12
R30W R31W

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1966 By HIRSCHY & SARFF

Located directly under power line beside road.

Bearing Trees, Reference Objects

Species J.P. J.P.


Diameter 7" 6"

Bearing N46° W N52 3/4° E

Distance 54 LKS 12LKS

Bearing Trees, Reference Objects

NONE



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

12-23-83 Walter Curo & Ken Metcalf found
 monument - No BT's
 New BT's marked.
 Poplar Red Oak Red Oak 5' W
 5" 6" 4" of Power
 526W 570E N 88W Line
 84.12 99.96 39.37

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. MAP

3. Man hours spent in search 1/2 HR

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature JOHN R. HIRSCHY

Perpetuation Record

Monument and accessories established. Include brief description of area.
 To perpetuate this corner I scribed 3 new bearing trees as
 follows: W.Oak 10 N62E 119.07' mkd. S 1/16 S7 BT
 W.Oak 7 N33W 84.40' mkd. S 1/16 S12 BT
 J.Pine 12 S67W 65.20' mkd. S1/16 S12 BT
 SET 8' STEEL POST DUE SOUTH 4.4' W/FS SIGNS 54-2 & 4
 SET 8' STEEL POST DUE EAST 4.4' W/FS SIGNS 54-2 & 4

CERTIFICATE FILED

Certified correct and true. Prepared: Walter Curo Yes _____ No _____
 Filed in county records at Coll Date 7/18/83 County Document No. 268853
 Identified on aerial photo No. _____ Which is filed at _____

Index No. J-18,19
(Alphabetical - Numerical)BOOK # 1
PAGE # 45LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 31W
MEANDERMer. N.F. CHIPPEWA County CASSState MINN
11 and 14

Corner common to sections _____, _____, _____, _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing Needs Cert.

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument SET IRON POST WITH CAP MKD
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 8-19-76 By RANDY MARTIN
FOUND IRON & CAP IN GOOD CONDITION

Bearing Trees, Reference Objects

Species W. Oak R. OakDiameter 5" 16"Bearing N28° E S26° EDistance 12 LKS 19 LKS

Bearing Trees, Reference Objects

NONE R. OAK16" SNAGGED AT BRG. & DIST.SCRIBE VISIBLE



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

To perpetuate this corner we scribed 3 new bearing trees as

follows: W.Oak 9" S66°E 34.43' mkd.SMC S14 BT

W.Oak 13" S12°E 28.40' mkd.SMC S14 BT

W.Oak 13" N22°E 7.50' mkd.SMC S11 BT

Set 8' steel sign post due East 3.7' W/FS sign 54-4

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-19
(Alphabetical - Numerical)

BOOK # 1
PAGE # 46

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 808-127

T. 143N R. 31W

5TH

Mer. N.F. CHIPPEWA County CASS

State MN

Corner common to sections 11 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Red Oak _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument SET IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species N. Pine N. Pine _____

Diameter 30" 24" _____

Bearing N. 15° E S. 19° E _____

Distance 52 LKS 67 LKS _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____


Evidence of Subsequent Corner Restoration Found

Year of search 8-19-76 By R. Morten & T. Jonsson

Found Iron & Cap in place in good condition

Bearing Trees, Reference Objects

NONE NONE _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

TO PERPETUATE THIS CORNER WE SCRIBED 3 NEW BEARING TREES AS
FOLLOWS: W. OAK 7" N⁷⁵°E 19.10' mkd. $\frac{1}{4}$ " S11 BT
W. OAK 7" N⁶⁰°W 18.40' mkd. $\frac{1}{4}$ " S11 BT
W. OAK 6" S18°W 43.83' mkd. $\frac{1}{4}$ " S14 BT
SET 8' STEEL SIGN POST DUE EAST 4.9' W/FS SIGN 54-4

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

BOOK # 1
PAGE # 47

T. 143 R. 31 Mer. N.F. 5 Chippewa County Cass State Minn
11/16 Corner common to sections 11, 14 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument Iron Post
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species J Pine J PineDiameter 14 14Bearing N28E S61EDistance 14 32

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By MARTINSONIron PostSpecies J Pine J PineDiameter 17 StumpBearing N20E N28E S20E S61EDistance 14 32

S-11



lake

Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Maps3. Man hours spent in search None4. Do you think additional search might
recover evidence? Yes _____ No X5. Signature Jerry E. Martinson

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared:

Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-21

BOOK 1

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 802-127

T. 143 R. 31 S. Mer. N.F. CHIPPEWA County CASS State MN.
 SECTION Corner common to sections 11 12 13 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875 B.C. BALDWIN
 Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>
Diameter	<u>4</u>	<u>6</u>	<u>10</u>	<u>5</u>
Bearing	<u>N62E</u>	<u>S44E</u>	<u>S63W</u>	<u>N37W</u>
Distance	<u>10 LKS.</u>	<u>20 LKS.</u>	<u>28 LKS.</u>	<u>30 LKS.</u>
	<u>6.60'</u>	<u>13.20'</u>		<u>19.80'</u>

Subsequent Corner Restoration

Year surveyed 1919 By GLO RESURVEY
 Where filed or recorded ON FILE AT S.O.
 Monument 2" X 36" IRON POST w/ BRASS CAP
(Original, concrete post, iron rod, etc.)

USED (2) ORIG. BT'S AS TIESNEW BT'S Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>J. PINE</u>
Diameter	<u>20</u>	<u>9</u>
Bearing	<u>N42 3/4 E</u>	<u>S33 1/2 E</u>
Distance	<u>67 LKS.</u>	<u>28 LKS.</u>

Original Evidence Found

Year of search 1919 By GLO RESURVEY
 Monument found Fd. REMAINS OF (4) ORIG. BEARING TREES

Original Bearing Trees Found


Species	<u>J. PINE STP.</u>	<u>J. PINE STP.</u>	<u>J. PINE</u>	<u>J. PINE</u>
Diameter			<u>18</u>	<u>14</u>
Bearing	<u>N62E</u>	<u>S44E</u>	<u>S64W</u>	<u>N34W</u>
Distance	<u>11 LKS.</u>	<u>20 LKS.</u>	<u>28 LKS.</u>	<u>30 LKS.</u>
			<u>NEW BT</u>	<u>NEW BT</u>

Evidence of Subsequent Corner Restoration Found

Year of search 8-6-76 By CK-TJ
 Fd. IRON + CAP - IN PLACE - 4" ABOVE GROUND - CORNER IN ASPEN REGENERATION + THICK BRUSH - PLACED FSLP ON 12" W. PINE 195' EAST OF COR. ON NW SIDE OF WOODS ROAD

Bearing Trees, Reference Objects

Species	<u>J. PINE STUB</u>	<u>J. PINE STP.</u>	<u>J. PINE STP.</u>	<u>ORIG J. PINE STP.</u>
Diameter	<u>10" HIGH</u>			
Bearing	<u>N43E</u>	<u>S33E</u>	<u>S64W</u>	<u>N84W</u>
Distance	<u>44.2'</u>	<u>18.48</u>	<u>18.48</u>	<u>19.80</u>
Condition	<u>SCRIBED</u>	<u>SCRIBED</u>	<u>ROTTED</u>	<u>SCRIBED</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. 8-6-76

BLAZED FOR SCRIBING IN 1976

1. N. PINE SW NOT SCRIBED 76
2. W. PINE SW " " 76

1. USED THIS N. PINE - NEW BLAZED SURFACE S10W' 159.30
2. W. PINE IS NOW A STUB 20' HIGH

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 1 1/2 HR.

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature Curt Krause

Perpetuation Record

CK
6-9-95

Monument and accessories established. Include brief description of area.

MKD NEW BT'S.

- N. PINE 11 1/2" S10W 159.30' MKD S14 BT
- N. PINE 17" S02 E 141.25' MKD S13 BT
- W. OAK 7 1/2" N83E 41.72' MKD S12 BT

8" STEEL SIGN POST NORTH 3.4'

CORNER IS APPROX. 550' NW OF OAK POINT ROAD
NE-SW - APPROCH OFF OAK POINT ROAD WILL END UP
225' SOUTH OF CORNER

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-21
(Alphabetical - Numerical)

BOOK # 1 LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143N R. 31W
SECTION SE

PAGE # 48
5TH Mer. N.F. CHIPPEWA County CASS

State MINN
13 and 14

Corner common to sections 11, 12, 13 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.

Where filed or recorded _____

Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects

Species J. PINE _____

J. PINE _____

Diameter 20" _____

9" _____


Bearing N43°E _____

S33½°E _____

Distance 67LKS _____

28LKS _____

Bearing Trees, Reference Objects



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

*12-27-82 Walter Curot Ken Metcalf found
 2" iron pipe with brass cap in good condition
 No B.T.'s found New B.T.'s marked*

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area.

**TO PERPETUATE THIS CORNER I SCRIBED 4 NEW BEARING TREES AS
 FOLLOWS: N. PINE MKDT 143NR31WS14BT
 W. PINE MKDT 143NR31WS13BT
 SET 8' STEEL POST DUE WEST W/FS SIGN 54-4**

CERTIFICATE FILED

Certified corner restoration certificate prepared: *Walter Curot* Yes _____ No _____

Filed in county records at *Crow* Date *5/18/83* County Document No. *268838*

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 31 Mer. N.F. Chippewa County Wis State Wis
E 1/16 Corner common to sections 12, 13, and _____

EXISTING SURVEYS

Original Government Survey
Year surveyed 1919 GLO
Original monument 1" x 3/16" brass cap monument
(wood post, stone, pile of stones, pipe, etc.)

Bearing Trees
Species Jackpine Jackpine
Diameter 8" 8"
Bearing S 36 1/2° E N 33 1/2° W
Distance 63 lks. 82 lks.

Subsequent Corner Restoration
Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found
Year of search _____ By _____
Monument found _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found
Year of search 12-27-82 By Walter Curo
& Ken Metcalf found monument in
good condition & rotted stump
S 36 1/2° E 63 lks.

Bearing Trees, Reference Objects
White Oak White Oak Trple W Oak
8" 8" 6"-8"-8"
N 20° E N 35° W S 85° W
22.28 17.66 24.92



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

CERTIFICATE FILED

Certified corner restoration certificate prepared: Yes No *by Walter Curs*

Filed in county records at *Cass* Date *5/18/83* County Document No. *268839*

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W
SECTION

Mer. N.F. CHIPPEWA County CASS
Corner common to sections 12, 13,
R31W and R30W

State MINN
7 and 18

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G. L. O.
Where filed or recorded _____
Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, wax red, etc.)

Bearing Trees, Reference Objects

Species	<u>W. OAK</u>	<u>W. OAK</u>	<u>POPLAR</u>	<u>POPLAR</u>
Diameter	<u>4"</u>	<u>4"</u>	<u>12"</u>	<u>5"</u>
Bearing	<u>N 5° E</u>	<u>S 46° E</u>	<u>S 29° W</u>	<u>N 31° W</u>
Distance	<u>39LKS</u>	<u>26 LKS</u>	<u>53LKS</u>	<u>29LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
FOUND IRON & CAP IN PLACE IN GOOD CONDITION

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, ~~maps~~
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

PUT F.S.L.P. ON 6" W. OAK 150' EAST OF CORNER ON WEST SIDE OF SQUAW POINT ROAD

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W S. 5th Mer. N.F. Chip County CASS State MN.
S.M.C. Corner common to sections _____ and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1914 By GRC

Where filed or recorded _____

Monument 36 I.P. W. +
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 8/1/30 By BRAND MAIN


FD, I.P. 10' above ground set in
place with E.C.
I.P. in W.P., 4' N50°E at 5'.
See also book - New trees have
been marked before.

Bearing Trees, Reference Objects

Species	<u>J.P.</u>	<u>R. OAK</u>
Diameter	<u>18"</u>	<u>"</u>
Bearing	<u>N39°E</u>	<u>S40W</u>
Distance	<u>20 Hs.</u>	<u>69 Hs.</u>

U.S.S. Bearing Trees, Reference Objects

	<u>R. OAK</u>	<u>W. OAK</u>	<u>R. OAK</u>
	<u>7"</u>	<u>8"</u>	<u>12"</u>
	<u>S44°E</u>	<u>N25°E</u>	<u>N62°E</u>
	<u>12.75</u>	<u>18.25</u>	<u>64.25</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

K-1819

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

I.P. sits on high bank overlooking steamboat BAY

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. *L.T.S.*

3. Man hours spent in search *C*

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature *[Signature]*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

*Sign post with both signs east of corner.
 Line east is F.S. STANDARD.*

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. K-18,19
(Alphabetical - Numerical)BOOK # 1
PAGE # 44LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 31W
S.M.C.Mer. N.F. CHIPPEWA County CASS
Corner common to sections _____State MINN
14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing West Cert.
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.
Where filed or recorded _____
Monument SET IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species J. PINE R. OAK
Diameter 10" 8"
Bearing N39°E S31°W
Distance 20LKS 69LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 8-17-70 By R. MORTON & T. JOHNSON
FOUND IRON & CAP IN PLACE IN GOOD CONDITION

Bearing Trees, Reference Objects

NONE
NONE



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

TO PERPETUATE THIS CORNER WE SCRIBED 3 NEW BEARING TREES

AS FOLLOWS: W. OAK 7" N25° E 18.25' MKD. S14 SMC BT

R. OAK 9" N62° E 64.25' MKD. S14 SMC BT

R. OAK 7" S44° E 12.75' MKD. S14 SMC BT

SET 8' STEEL SIGN POST DUE EAST 0.2' W/FS SIGNS 54-2 & 54-4

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. K19
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 17314 R. 21W 5TH Mer. N.F. Chip County Cass State MO
Center North 1/4 Corner common to sections _____ and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded St. Paul
Monument 1" x 3/8" I.P. with F.I.
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 2/180 By BRAMA & MAIN
Fd. I.P. 4" above ground set
in piece with B.I.
F.S.L.P. - R. Oak, 8", N15°W at 13/ks.
Fd. three F. Service BT'S - see
field book.


Bearing Trees, Reference Objects

Species	<u>J.P.</u>	<u>J.P.</u>
Diameter	<u>14"</u>	<u>14"</u>
Bearing	<u>S34°E</u>	<u>N35°W</u>
Distance	<u>195/ks.</u>	<u>92/ks.</u>

Bearing Trees, Reference Objects

Species	<u>R. Pine</u>	<u>J. Pine</u>	<u>R. Pine</u>
Diameter	<u>12"</u>	<u>9"</u>	<u>8"</u>
Bearing	<u>S67°E</u>	<u>N49°E</u>	<u>N20°W</u>
Distance	<u>13.05'</u>	<u>24.25</u>	<u>23.80'</u>

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

old fruit west + corner about 200 runs
N + S.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. A.T.S.

3. Man hours spent in search 0

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Da. B. ...

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Sign posts with both signs east and west of corner.

Lines east + west ARE too F.S. STANDARD.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. K-19
(Alphabetical - Numerical)

BOOK # 1
PAGE # 43

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/81)

T. 143 R. 3T Mer. N.F. Chippewa County Cass State Minn
CENTER N 1/16 Corner common to sections 14 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded _____
Monument Iron Post
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1966 By BROWN, MARTINSON

Iron Post

Bearing Trees, Reference Objects

Species J Pine J Pine
Diameter 14" 14"
Bearing S23E N35 W
Distance 195 92

No evidence found



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Compass-Chaining

3. Man hours spent in search none

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature MARTINSON

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. K-20
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7 150-4 (Rev. 6/13/67)
GPO 502-127T. 143N. R. 31W
North East5thMer. N.F. Chip.County CassState MINN.

Corner common to sections _____

and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919By GLOWhere filed or recorded St. PaulMonument 1' x 36" I.P. with B.C.
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species J.P. R. OAKDiameter 16" 8"Bearing N50°E S23°WDistance 132.15' 45.15'
87.12' 29.70'

Original Evidence Found

Year of search _____

By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 8/4/8By B. H. M. A. GUSTIN, PedersonPl. mark a place 6" above g.g.10 4x4 post with F&B about1.0' SE of corner, filled postNo remains of bearing trees

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

K-20

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Forest service road is west of corner about 40'.

Saw cut top is east approx.
 Place 4x4 wood post with attention signs +
 F.S. east of corner 166 ft. on west side
 of squaw pt. road.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

- Mkd. New DT'S.
1. J. Pine 8" N77°E 68.36'
 2. W. C. 5" 5.20' S28 E°
 3. W. P. 9" 34.22' S34 W°

Line west is top of ...
 Sign posts west 2 1/4' & south 2 1/4' from corner with ...
 signs

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. Line to standard

3. Mon hours spent in search 5 min.

4. Do you think additional search might
 recover evidence? Yes _____ No

5. Signature Ray Beama

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____


Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W S. 5th Mer. N.F. CHITPEWA County CASS State MINNESOTA
NE 1/16 Corner common to sections 14 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1919</u> By <u>G.L.O.</u>	Year of search <u>1965</u> By <u>GAMACHE & SCHLUTER</u>
Where filed or recorded _____	<u>BRASS CAP FOUND</u>
Monument <u>BRASS CAP SET</u> <small>(Original, concrete post, iron rod, etc.)</small>	<u>BEARING TREES HAVE BEEN CUT FOR ROADSIDE CLEARING</u>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species <u>J. PINE</u> <u>R. OAK</u>	<u>NONE</u> <u>NONE</u>
Diameter <u>16"</u> <u>8"</u>	
Bearing <u>N50 1/2° E</u> <u>S23° W</u>	
Distance <u>132 LKS</u> <u>45 LKS</u>	

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

CORNER IS JUST OFF THE EAST EDGE OF THE SQUAW POINT ROAD.

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. COMPASSING AND
CHAINING

3. Man hours spent in search 2 HRS.

4. Do you think additional search might
 recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

5. Signature CEDRIC A. SCHLUTER

*BOOK # 1
 PAGE # 42*

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Minn
NE 1/16 Corner common to sections 14 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
 Where filed or recorded _____
 Monument Iron Post
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects

Species	<u>J Pine</u>	<u>RED OAK</u>
Diameter	<u>160L</u>	<u>8"</u>
Bearing	<u>N50E</u>	<u>S23W</u>
Distance	<u>132</u>	<u>45</u>

Evidence of Subsequent Corner Restoration Found

Year of search 1966 By BROWN, MARTINSON
Iron Post

No Evidence Found



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Compass-Chaining

3. Man hours spent in search None

4. Do you think additional search might recover evidence? Yes X No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

5. Signature Larry E. Martinson

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W Mer. N.F. CHIPPEWA County CASS State MINN
N 1/16 Corner common to sections 13 and 18
R 31W and R 30W

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Maple - New Haven H +
Diameter _____
Bearing BT
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G. L. O.
Where filed or recorded _____
Monument SET IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species W. OAK N. PINE
Diameter 12" 12"
Bearing N66°W S69°E
Distance 101 LKS 40 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
FOUND IRON IN PLACE - BENT TO GROUND CAP
HAS BEEN REMOVED - BUT IRON IS SET SOLID
IN GROUND

Bearing Trees, Reference Objects

Species W. OAK N. PINE
Diameter 10" STUMP
Bearing scribe
Distance overgrown



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

PUT FSLP ON POWER POLE NORTH OF CORNER APPROX. 12'

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. L-20
(Alphabetical-Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143 N. R. 31 W. Mer. 5th N.F. Chip County Cass State MN.
Center East 1/4 Corner common to sections _____ end 14

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1919</u> By <u>GLO</u>	Year of search <u>10/10/80</u> By <u>BRAMA & Uggren</u>
Where filed or recorded <u>ST. PAUL</u>	Fd. <u>I.P. bent but in place with</u>
Monument <u>1" x 36" I.P. w. th B.C.</u> <small>(Original, concrete post, iron rod, etc.)</small>	<u>B.C. About 6" of pipe above grd.</u>
	<u>Fd. dead I.P. with scribe visible.</u>
	<u>Stp. hole for R. oak.</u>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species <u>I.P.</u> <u>R Oak</u>	<u>I.P. (Dead)</u>
Diameter <u>14"</u> <u>14"</u>	
Bearing <u>S75°E</u> <u>S32°W</u>	<u>S74°E</u>
Distance <u>1241ks.</u> <u>901ks.</u>	<u>81.84'</u>
<u>81.84'</u>	



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

L-20

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps, etc. L.T.S.

3. Man hours spent in search 0

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Bery Brand

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MARKED New BT'S: MRD,
P.O.C. 7" N 27° E AT 7.17 CEYB 514 BT.
Point 6" S 73° E AT 8.41 CEYB 514 BT
Point 5" N 61° W AT 19.73 CEYB 514 BT.

Sign Posts 1.8 south of + 1.55 20' with both signs.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W Mer. N.F. Chippewa County Cass State Missouri
E 1/4 Corner common to sections 14 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter N 13

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument Brass Cap
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1965 By C. Schluter + Gammbo

Found brass cap bent over
and one bearing tree just
about eaten away by wood
peckers.

Bearing Trees, Reference Objects

Species JPine R. Oak

Diameter 14" 14"

Bearing S 74° 30' E S 92° 15' W


Distance 124 LKS 90 LKS

JPine

14"

S 74° 30' E NONE

124 LKS



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

corner is S.W. of old opening. In scrub oak and hazel brush

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. chaining & compass

3. Man hours spent in search _____

2 hrs

4. Do you think additional search might recover evidence? Yes: _____ No: _____

5. Signature Calvin Schultze

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W 5th Mer. N.F. CHIPPEWA County CASS State MINNESOTA
 Corner common to sections 13 & 14 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1968</u> By _____
Where filed or recorded _____	BRASS CAP FOUND
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	_____
_____	_____
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes X No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

5. Signature ELDRED JOHNSON

Index No. L-23
(Alphabetical - Numerical)Boon # 1 LAND CORNER RECORD
PAGE # 54 (RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 31W
CENTER 1/4Mer. N.F. CHIPPEWA County CASS State MINN
Corner common to sections _____ 13

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G. L. O.

Where filed or recorded _____

Monument SET IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species J. PINE J. PINEDiameter 6 12Bearing N76³⁰E S44³⁰EDistance 73LKS 28LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

FOUND IRON & CAP - IN PLACE ABOVE
GROUND IN GOOD CONDITION


Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 1-24
(Alphabetical - Numerical)BOOK # 1
PAGE # 58
574LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 91W Mer. N.F. CHIPPEWA County CASS State MO.
CENTER EAST 1/4 Corner common to sections 9 & 13

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed. 1919 By G.L.O.
Where filed or recorded _____
Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species W. OAK N. PINE
Diameter 16 26
Bearing S43 1/2 E S21W
Distance 40LKS 72LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
FOUND IRON & CAP - IN PLACE ABOVE GROUND
IN GOOD CONDITION

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W Mer. N.F. Chippewa County Cass State Mn
 Corner common to sections 13 and 18

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument Set iron post with brass cap
(Original, concrete post, iron rod, etc.)
marked

Evidence of Subsequent Corner Restoration Found

Year of search 1983 By Walter Cass


Ken Metcalf found iron bent and buried in power line clearing. Cap is on iron and believe iron is in place. No BT's found - Replaced monument with 2" x 36" brass cap monument

Bearing Trees, Reference Objects

Species	<u>Jackpine</u>	<u>Q Oak</u>	<u>W Oak</u>
Diameter	<u>24"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>S28E</u>	<u>N23 1/2 W</u>	<u>N20E</u>
Distance	<u>20 lks</u>	<u>34 lks</u>	<u>18 lks</u>

Bearing Trees, Reference Objects

<u>New</u>	<u>W. Oak</u>	<u>Q. Oak</u>	<u>Red Oak</u>	<u>4' E</u>
	<u>12"</u>	<u>9"</u>	<u>8"</u>	<u>of Power</u>
	<u>N65E</u>	<u>N82W</u>	<u>S50W</u>	<u>line.</u>
	<u>67.80'</u>	<u>54.27</u>	<u>61.97</u>	



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CERTIFICATE FILED

Certified corner restoration certificate prepared: Walter Curo Yes _____ No _____

Filed in county records at Iss Date 5/8/83 County Document No. 268854

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W 5th Mer. N.F. Chippewa County CASS State Mn
Center South 1/4 Corner common to sections _____ end 14

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed _____		Year of search _____ By _____	
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>		Monument found _____	
Bearing Trees		Original Bearing Trees Found	
Species _____	_____	Species <u>R OAK</u>	_____
Diameter _____	_____	Diameter <u>8"</u>	_____
Bearing _____	_____	Bearing <u>S 41° E</u>	_____
Distance _____	_____	Distance <u>15 1/2</u> <u>9.90 FT</u>	_____
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed <u>1919</u> By _____		Year of search <u>10/2/80</u> By <u>MAIN</u>	
Where filed or recorded _____		Fd I.P. 8" above grd. set in place.	
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>		<u>No remains of other BT OAK.</u>	
Bearing Trees, Reference Objects		Bearing Trees, Reference Objects	
Species <u>R.OAK</u>	<u>R. OAK</u>	<u>R OAK</u>	_____
Diameter <u>5"</u>	<u>14"</u>	<u>18"</u>	_____
Bearing <u>S 41° E</u>	<u>S 40° W</u>	<u>S 41° E</u>	_____
Distance <u>15 1/2</u> <u>9.90</u>	<u>14 1/2</u> <u>9.90</u>	<u>9.90</u>	_____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

M-19

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Found monument in hole 8" above ground. GLO ROAK 5" Bearing S41°E Distance 11' still above ground 18'.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps, etc. Compass

3. Man hours spent in search LHF

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Jay Brana

Perpetuation Record

Monument and accessories established. Include brief description of area.
MKD New Pits
 W Oak 7" N 70° E 49.20' MKD CS 1/16 S 1/4 BT
 W Oak 7" N 17° W 6.43' " CS 1/16 S 1/4 BT
 W Oak 8" S 66° W 12.33' " CS 1/16 S 1/4 BT
 ROAK 18' S 41° E 7.90' MKD CS 1/16 S 1/4 BT

Set two iron pins in ground, 5' 4" post less than 1" is 3 1/4" from monument, 5' 8" post 200' in S 41° E 2.14' from monument.

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

Index No. M-19
(Alphabetical - Numerical)

BOOK # 1
PAGE # 38

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

89-5680-11 (5/12/81)

T. 143 R. 31 Mer. N.F. 5th Chippewa County Cass State Minnesota
S 1/16 Corner common to sections 14 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter N. 1/4 _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By M. Sarff

Brass cap found.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Maps and chaining

3. Man hours spent in search 1/2

4. Do you think additional search might

recover evidence? Yes No _____

5. Signature M. Sarff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. M-20
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)

GPO 802-127

T. 143N & 31W
Southeast 1/4

5th

Mer. N.F. Ch. 0

County Cass

State MN

Corner common to sections _____

and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

See

Original Evidence Found

Year of search _____

By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____

By _____

Where filed or recorded _____

Monument _____

(Original, concrete post, iron rod, etc.)

Field Book

Evidence of Subsequent Corner Restoration Found

Year of search 10/10/80

By BRAMA, Upgren

Fd. I.P. with B.C. in place.

Bearing Trees, Reference Objects


Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

M-20

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Line tree north of corner, + west (R.P.)

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Parcel adjoining photos, maps, etc. *K.T.S.*

3. Man hours spent in search 0

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature *Gary Brana*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Sign posts with iron signs:
 1. West - 2.15'
 2. East - 2.45'
 3. North - 4.6'
 4. South - 2.75'
 Line west, east, north & south are 100 F.S. STAND
 5' x 5' Wood Post with *1/2* along trail south of corner

Repainted BT's.

Certified corner restoration certificate prepared: Yes _____ No 335.0'
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

Index No. M 20
(Alphabetical - Numerical)

BOOK # 1
 PAGE # 37

LAND CORNER RECORD
(RECTANGULAR SURVEYS)


RS-5820-11 (5/12/61)

F

T. 143N R. 31W Mer. N.F. Chippewa County Cass State MINN
SE 1/4 Corner common to sections 14 and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
Bearing Trees Species _____ Diameter _____ Bearing _____ Distance _____	Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration Year surveyed <u>1919</u> By <u>GLO</u> Where filed or recorded _____ Monument <u>Brass Cap</u> <small>(Original, concrete post, wax rod, etc.)</small>	Evidence of Subsequent Corner Restoration Found Year of search <u>1965</u> By <u>C Schuler + Gamph</u> <u>Found Brass cap under wind fall.</u>
Bearing Trees, Reference Objects Species <u>R Pine</u> <u>R Pine</u> Diameter <u>10"</u> <u>10"</u> Bearing <u>N 25 1/2° E</u> <u>S 21 1/4° W</u> Distance <u>164 LKS</u> <u>242 LKS</u>	Species _____ Diameter _____ Bearing _____ Distance _____ <u>NONE</u> <u>Red Pine</u> <u>10"</u> <u>S 21 1/4° W</u> <u>242 LKS</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Corner is 3 chains North of Bear trap Loop Road in aspen area.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,

etc. *Compass &*

Chaining

3. Man hours spent in search

2

4. Do you think additional search might

recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

5. Signature *Berrie Schluter* Identified on aerial photo No. _____ Which is filed at _____

Index No. M-21
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
502-127

142 R. 31W 5th Mer. N.F. Chip County Cass State MO
South Corner common to sections 13 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 10/10/80 By BRAGA & Loggins

Fd. + P. 8" above grad set in
place with P.C.

Fd. J.P. stub laying down. Push out of place

FSLP st. Poplar stub 3 1/2' ks
N 76° E. Remains of rotted pop. stp.

Bearing Trees, Reference Objects

Species J.P. _____ Poplar _____

Diameter 16" _____ 12" _____

Bearing N 77° E _____ N 47° W _____

Distance 73 ks. _____ 14 ks. _____


450

Bearing Trees, Reference Objects

J.P. stub _____ Poplar stub _____

N 77° E _____ N 47° W _____

48.18' _____ 9.25' _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

M-21

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Pine plantation bears SE.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. *L.T.S.*

3. Man hours spent in search *10 min*

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature *Darryl Brown*

Perpetuation Record

Monument and accessories established. Include brief description of area.


MRD. NEW BTS: MKD.
 1. W. OAK, 4" S45°E at 25.60' S 1/6 S 13 BT.
 2. W. OAK, 8" S2°W at 27.36' S 1/6 S 14 BT.
 3. W. OAK, 4" N78°W at 20.60' "X" BT
FSLP - R. OAK, 4" S45°E at 1.8'
Signs posts with both signs west 2.97 & south 2.39 from corner.
Lines west & south are Forest Service stand

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Relation of Evidence to Record Features Along Section Lines



○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,

etc. Compass & chaining

3. Man hours spent in search _____

2

4. Do you think additional search might

recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

5. Signature Leslie Schuster

Index No. M-24
(Alphabetical - Numerical)

BOOK # 1
PAGE # 57
5TH

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143N R. 31W
SOUTH EAST 1/16

Mer. N.F. CHIPPEWA County CASS

State MINN
13

Corner common to sections _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.
Where filed or recorded _____
Monument SET IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species W. OAK POPLAR
Diameter 6 8
Bearing N85W S144E
Distance 35LKS 2 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
FOUND IRON & CAP - IN PLACE IN GOOD
CONDITTON ABOVE GROUND

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 21 Mer. N.F. Chippewa County Cass State Mn
5716 Corner common to sections 13, 18 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 GLO
Original monument 1" x 36" brass cap monument
5716
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. Oak W. Oak
Diameter 4" 12"
Bearing S76E N28E
Distance 25 lbs. 29 lbs.

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 2-23-83 By Walter Curo & Ken Metcalf
searched under powerline
No trace of corner or BT's. Set
2" x 36" brass cap monument flush with
ground at midpoint between E 1/4 corner
& SE corner of section.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W Oak</u>	<u>10"</u>	<u>N32E</u>	<u>70.47</u>
<u>W Pine</u>	<u>14"</u>	<u>S52E</u>	<u>51.18</u>
<u>W. Oak</u>	<u>8"</u>	<u>N60W</u>	<u>58.18</u>
			<u>13 16.08</u>
			<u>to E 1/4</u>
			<u>SE cor</u>
			<u>of sec.</u>



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CERTIFICATE FILED

Certified corner restoration certificate prepared: Yes Walter Cure No

Filed in county records at Cass Date 5/8/83 County Document No. 268841

Identified on aerial photo No. _____ Which is filed at _____

Index No. N 19
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
GPO 502-127

T. 143N R. 31W 5th Mer. N.F. Chip County Cass State MN.
Quarter Corner common to sections 14 and 23

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species J.P. J.P.
Diameter 18" 4"
Bearing N19°E S5°E
Distance 328 fms. 641 fms.
216.78 72.24

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species J.P. Stump J.P. Stp.
Diameter 1 _____
Bearing N7°E S11°E
Distance 58 fms. 45 fms.
2170

Evidence of Subsequent Corner Restoration Found

Year of search 10/9/80 By BRAMA
Ed. I.P. 7" above ground set
in place with B.C.
Ed. Stump for J.P. at S5°E at 42.24'
Ed. GLO 18" J. Pine - Stump with
BT visible, No remains of original.

Bearing Trees, Reference Objects

J. Pine Stp.
18"
N19°E
216.48

Index No. N-19
(Alphabetical - Numerical)

BOOK # 1
PAGE # 31

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/81)

T. 143 R. 31 5th Mer. N.F. Chippewa County Cass State Minnesota
64 Corner common to sections 14, 23 and

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ By _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search 1967 By M. Sarff

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Brass cap found.

Bearing Trees, Reference Objects

Jackpine

Species _____

18"


Diameter _____

S

Bearing _____

50 ft.

Distance _____



Sketch

O Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Maps, chaining

3. Man hours spent in search 30 min.

4. Do you think additional search might recover evidence? Yes No _____

5. Signature M. Sarff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. N-20
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-7150-4 (Rev. 6/15/67)
GPO 802-127

143N R. 21W 5th Mer. N.F. Chip County Cass State MN
EAST 1/2 Corner common to sections 23 and 14

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search <u>10/10/80</u> By <u>BRAMM & Upgren</u> Fd. I P. 6" <u>brass ground</u> <u>all</u> <u>place with 1/2"</u> <u>ETLD - R. d. nai, - 11 pt 55° 10' 11"</u> <u>NO remains of poplar.</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species <u>W. Oak</u> _____ <u>Poplar</u> _____ Diameter <u>14"</u> _____ <u>8"</u> _____ Bearing <u>N6°W</u> _____ <u>137°E</u> _____ Distance <u>33 lks.</u> _____ <u>137 lks.</u> _____ <u>958</u> _____ <u>864</u> _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species <u>W. OAKS</u> _____ _____ Diameter _____ _____ Bearing <u>N6°W</u> _____ _____ Distance <u>858'</u> _____ _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

N-20

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. L.T.S.

3. Man hours spent in search 0

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Gay Brana

Perpetuation Record

Monument and accessories established. Include brief description of area.

MKD NEW BT'S! MKD.
 1. W. OAK, 7', N 70° E AT 20.5' E 1/16 S 14 BT.
 2. W. OAK, 6", S 56° W AT 23.92' E 1/16 S 3 BT.
 3. W. OAK, 9", N 19° W AT 26.85' E 1/16 S 14 BT.

Sign posts north 2.53' and east 4.92' from corner.

L.T.S. north east cor to F.S. STAND

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. N-20
(Alphabetical - Numerical)

BOOK # 1
PAGE # 30 LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/81)

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Minnesota
SE 1/16 Corner common to sections 14, 23 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____


Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By M. Sarff & W. Molash

Brass cap found.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No **X** _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. **maps, chaining**

3. Man hours spent in search **1 hour**

4. Do you think additional search might
recover evidence? Yes **X** No _____

5. Signature **M. Sarff**

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 14N R. 31W 5th Mer. N.F. Chipp County Lass State MN.
See Corner common to sections 13, 14, 23 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, rod, etc.)

Field Book

Evidence of Subsequent Corner Restoration Found

Year of search 10/10/80 By BRAMA & Upgren

Fd. mon. set in place w. th B.C.

Bearing Trees, Reference Objects

Species _____


Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Pine plantation bear east, runs N+S.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. *L.T.S.*

3. Man hours spent in search *0*

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature *Larry Bean*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Lines north + west are 100 F.S. Standard, Repainted, all the BT'S.

Sign post + 4x4 wood post with both signs already there.

4x4 wood post with prop. boundary + F.S.L.P place on F.S. Trail 4.07' south of S.E.

Certified *Formal* restoration certificate prepared. Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. N-23
(Alphabetical - Numerical)

BOOK # 1
PAGE # 26

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)
 GPO 802-127

T. 143N R. 31W
1/4

5TH

Mer. N.F.

CHIPPEWA

County

CASS

State

MINN

Corner common to sections _____

13 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.

Where filed or recorded _____

Monument IRON POST WITH BRASS CAP
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

FOUND IRON & CAP IN PLACE IN GOOD CONDITON

Bearing Trees, Reference Objects

Species J. PINE

J. PINE

Diameter 10"

12"

Bearing N. 1E

S. 36 W

Distance 33 LKS

16LKS

Bearing Trees, Reference Objects

J. PINE

J. PINE

12"


14"

S23 1/2W

N 78 E

53 LKS

55 LKS



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W Mer. N.F. 5 CHIPPEWA County CASS State MINNESOTA
EAST 1/16 Corner common to sections 13 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, peg, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.
 Where filed or recorded _____
 Monument SET IRON POST WITH CAP MKD
(Original, concrete post, wood rod, etc.)

Bearing Trees, Reference Objects

Species W. OAK ASPEN
 Diameter 14 8
 Bearing N6W S19°30E
 Distance 13 LKS 13LKS

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found


Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 5-13-76 By CURTIS B. KRAUSE
FOUND IRON & CAP IN PLACE IN GOOD CONDITION

Bearing Trees, Reference Objects

W. OAK POPIAR
18 15
SCRIBE SCRIBE OVERGROWN
OVERGROWN



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 R. 31-30 5th Mer. N.F. CHIPPewa County CASS State MO
 Section Corner common to sections 13 18 19 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
 Original monument wood Post
(wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>W.OAK</u>	<u>N.PINE</u>	<u>W.OAK</u>	<u>W.OAK</u>
Diameter	<u>4"</u>	<u>24"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N 83° E</u>	<u>N 62° W</u>	<u>S 16° W</u>	<u>S 15° E</u>
Distance	<u>35 Lks</u>	<u>102 Lks</u>	<u>177 Lks</u>	<u>150 Lks</u>

Original Evidence Found

Year of search 1919 By CLO
 Monument found No Post

Original Bearing Trees Found

Species	<u>W.OAK</u>	<u>N.PINE</u>	<u>W.OAK</u>	<u>W.OAK</u>
Diameter	<u>Stump</u>	<u>24" Stump</u>	<u>Stump</u>	<u>Stump</u>
Bearing	<u>N 83° E</u>	<u>N 62° W</u>	<u>S 16° W</u>	<u>S 15° E</u>
Distance	<u>35 Lks</u>	<u>102 Lks</u>	<u>177 Lks</u>	<u>150 Lks</u>

Subsequent Corner Restoration

Year surveyed 1919 By CLO
 Where filed or recorded _____
 Monument Set Iron post 2" dia. 36" long
(Original, concrete post, iron rod, etc.)
w/ BRASS CAP.

Evidence of Subsequent Corner Restoration Found


Year of search 4-25-74 By ERT KRAWSE
R. OAK, J. PINE - gone BECAUSE
OF POWER LINE.
N. Pine, J. Pine - Now Stumps

Bearing Trees, Reference Objects

Species	<u>R.OAK</u>	<u>J.PINE</u>	<u>N.PINE</u>	<u>J.PINE</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N 47° 45'</u>	<u>S 68° 40' E</u>	<u>S 30° W</u>	<u>N 83° W</u>
Distance	<u>38 Lks</u>	<u>40 Lks</u>	<u>69 Lks</u>	<u>39 Lks</u>
	<u>gone</u>	<u>gone</u>	<u>Stump</u>	<u>Stump</u>

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>15"</u>	<u>11"</u>	<u>17"</u>	<u>11"</u>
Bearing	<u>S 17° W</u>	<u>S 68° 45' E</u>	<u>N 68° W</u>	<u>N 57° E</u>
Distance	<u>96.7'</u>	<u>66.55'</u>	<u>54.9'</u>	<u>91.2'</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

STEEL Post 8' Long SET DWB NORTH
 2.7' with F.S. signs 154-2 + 54-4

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Mon hours spent in search _____

2 HR.

4. Do you think additional search might
 recover evidence? Yes _____ No

Signature Jim Schoonover

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CERTIFICATE FILED

Certified corner restoration certificate prepared _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 N R. 31 W Mer. N.F. CHIPPEWA County CASS State MINN
SECTION Corner common to sections 24, 13, 18 and 19
R 31 W R 30 W

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875

Original monument SET POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>W. OAK</u>	<u>N. PINE</u>	<u>W. OAK</u>	<u>W. OAK</u>
Diameter	<u>4"</u>	<u>2"</u>	<u>5"</u>	<u>5"</u>
Bearing	<u>N83E</u>	<u>N62W</u>	<u>S16W</u>	<u>S15E</u>
Distance	<u>35LKS</u>	<u>192 LKS</u>	<u>171 LKS</u>	<u>150LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By G. L. O.

Where filed or recorded _____

Monument SET IRON POST W/BRASS CAP
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 4-25-74 By CURTIS R. KRAUSE

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>J. PINE</u>	<u>N. PINE</u>	<u>J. PINE</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N47E</u>	<u>S68E</u>	<u>S30W</u>	<u>N83W</u>
Distance	<u>38LKS</u>	<u>40LKS</u>	<u>69LKS</u>	<u>39LKS</u>

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>15"</u>	<u>11"</u>	<u>17"</u>	<u>11"</u>
Bearing	<u>S17°W</u>	<u>S68 E</u>	<u>N68°W</u>	<u>N57°E</u>
Distance	<u>96.7</u>	<u>66.55</u>	<u>54.9</u>	<u>91.2</u>



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

2-27-83 Walter Curo & Ken Mitchell found concrete monument lying by a tree N of new road at fall of '82. Reset monument using BT's made by Curt Krause & the original BT stamp N 83 W 39 lts.

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

TO PERPETUATE THIS CORNER I SET A "5 1/2 X 5 1/2" SQUARE CONCRETE MONUMENT 60" LONG WITH 4" ABOVE GROUND MONUMENT HAS 3" DIA. BRASS TABLET STAMPED AS FOLLOWS

SET 8' STEEL SIGN POST DUE NORTH 2.7'

WITH F.S. SIGNS 54-2 & 54-4 ATTACHED.

T 143 N

<i>R 31 W</i>	<i>R 30 W</i>
<i>S 13</i>	<i>S 18</i>
<i>S 24</i>	<i>S 19</i>
<i>1974</i>	

CERTIFICATE FILED

Certified corner restoration certificate prepared: Yes No *Walter Curo.*

Filed in county records at *Cass* Date *3/18/83* County Document No. *768843*

Identified on aerial photo No. _____ Which is filed at _____

Index No. 0-1712
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 502-127

T. 143 N R. 31 W Sth Mer. N.F. Chio County Cass State MN
SMC (ON N.H. LINE) Corner common to sections _____ and 23

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found


Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
 Where filed or recorded St Paul
 Monument 1 x 36"
(Original, concrete post, iron rod, etc.)



Evidence of Subsequent Corner Restoration Found


Year of search 10/8/80 By KRAUSE, BRAMA
Fd. I.P. with E.C. leaning.
Fd. W. OAK sp. at N85°E and at 44.88'
Checked distance from GEO BT.
Faint survey mark on JT.

Bearing Trees, Reference Objects

Species W. OAK W. OAK
 Diameter 14 8"
 Bearing N85°E S16°E
 Distance 68 lks. 119 lks.

Bearing Trees, Reference Objects

W. OAK sp.
2' High
N85°E
44.88'



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

0-17, B

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Reset GLO(SMC) 7" above ground. 6' sign drove down on SW side of I.P. with 7" above ground. Corner falls on shore line of Steamboat Bay about 5' west of high bank. Set W.C.I.P. 2" x 3/8" 11.14' east of GLO I.P. with 4" above ground with P.C. mark. (See below.) Sign post with both signs is 2.60' east from W.C. line to the east is 100 F.S. STANDARD. 3.84' east of GLO.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?

a. Pacing, chaining, photos, maps, etc. L.T.S.

3. Man hours spent in search 10

4. Do you think additional search might recover evidence? Yes _____ No


5. Signature

Gary Bruma

Perpetuation Record

Monument and accessories established. Include brief description of area. New BT'S:
W. OAK, 6", S 6° W at 46.75' MKD. SMC 23 BT.
W. OAK, 5", N 16° E at 12.49' MKD. SMC 23 BT.
W. OAK, 4", S 62° E at 31.15 MKD "X" BT.
SMC (GLO) BT'S. (No tags)
1. W. OAK 6", S 11° W AT 47.28'
2. W. OAK 5", N 50° E AT 18.64'
3. W. OAK 4", S 71° E AT 47.77'

Witnessed by _____



Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 0-19
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 502-127

T. 143N R. 31W Mer. N.F. 5th Chip County Cass State MN
Center North 1/4 Corner common to sections _____ end 23

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 19.9 By GLO
 Where filed or recorded St. Paul
 Monument "x36" I.P. with B.C.
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Red Oak</u>
Diameter	<u>4"</u>	<u>4"</u>
Bearing	<u>S61°E</u>	<u>N70°E</u>
Distance	<u>21.1Ks,</u> <u>13.86'</u>	<u>8.1Ks,</u> <u>5.28'</u>

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found


Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 10/9/80 By BRAMA
 E.d. I.P. 7" above ground set in
 place, E.S.L.P. on a 9" W. OAK at S83° Wat 90°
 E.d. remains of a rotten red oak
 stump (flush with grd.) at bear & dist
 E.d. remains of a rotten poplar stp. at order

Bearing Trees, Reference Objects

Poplar stp.	<u>R. OAK</u>
<u>S61°E</u>	<u>N70°E</u>
<u>13.86'</u>	<u>5.29'</u>



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Pine plantation bears NW.

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. *L.T.S.*

3. Man hours spent in search 0

4. Do you think additional search might
 recover evidence? Yes _____ No

5. Signature *Gary Brana*

Perpetuation Record

Monument and accessories established. Include brief description of area.

<i>MKD. New BT'S.</i>		<i>MKD.</i>
<i>1. W. OAK, 9", S83°E</i>	<i>A+8.0'</i>	<i>CN 46 S 23 BT.</i>
<i>2. W. OAK, 8", S15°E</i>	<i>A+97.72'</i>	<i>CN 46 S 23 BT.</i>
<i>3 R. Pine, 17", N84°W</i>	<i>A+71.13'</i>	<i>CN 46 S 23 BT</i>

*Sign Posts with both signs in N. 1.50' and
W. 7.70' from corner.
lines North & West are to F.S. STANDARD*

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

Index No. 0-19
(Alphabetical - Numerical)

*BOOK # 1
PAGE # 32*

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-5680-11 (5/12/61)

T. 143 R. 31 Mer. N.F. 5th Chippewa County Cass State Minnesota
N 1/16 Corner common to sections 23 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By M. Sarff & W. Molash
Brass cap found.

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
 Yes _____ No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. Maps, chaining

3. Man hours spent in search 1

4. Do you think additional search might
 recover evidence? Yes No _____

5. Signature M. Sarff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____
F. S. tag on Squaw Point Road

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

Index No. 0-23
(Alphabetical - Numerical)BOOK # 1
PAGE # 25
5THLAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 31WMer. N.F. SHIPPEWA County CASSState MINNCENTER NORTH 1/16 Corner common to sections _____24

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing Weeds Cert.

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.

Where filed or recorded _____

Monument SET IRON POST WITH CAP MKD
(Original, concrete post, man rod, etc.)

Bearing Trees, Reference Objects

Species W. OAK W. OAKDiameter 9 14Bearing N25E S52WDistance 37LKS 43LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____


Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 8-9-16 By CURT KRAUSEFOUND IRON & CAP IN PLACE IN GOOD CONDITIONNEEDS CERTIFICATE

Bearing Trees, Reference Objects

Species OAK W. OAKDiameter ROTTED 19Bearing HAS AXE RESCRIBED BTDistance MARKS SCRIBE OVERGROWN



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

TO PERPETUATE THIS CORNER I SCRIBED 2 NEW BEARING TREES AS

FOLLOWS: W.OAK 15 N74W 38.15' MKD CN1/16 S24 BT

S.OAK 10 N20E 23.0' MKD CN1/16 S24 BT

SET 8' STEEL POST DUE EAST 2.9' W/F.S. SIGN 54-4

200' EAST OF WOODS ROAD BRG. N/S PUT FSLP ON 13" BALSAM N70E

9.0' SET 4"X4"X6" CEDAR POST AT EAST EDGE OF ROAD -WITH FSLP

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. T143 N R. 31-30W 5th Mer. N.F. Chippewa County CASS State MN
N 1/4 Corner common to sections 24, 19 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Where filed or recorded _____
Monument Iron Post 3' Long 1" diam. 28" IN GROUND
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species R. OAK R. OAK _____
Diameter 4" 6" _____
Bearing N 44 1/2° E S 55° W _____
Distance 41Ks 231Ks _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 2-1-80 By Jim Schaeffer
Found IRON WITH METAL DETECTOR
2" PIPE IN PROPER TIE BUSH
WITH SECTION CORNER OF 24/19 AND
1/4 CORNER OF 24/19. WILL MONUMENT

Bearing Trees, Reference Objects

NO EVIDENCE NO EVIDENCE WHEN GROUND
R. OAK OF R. OAK THAW'S
POWERLINE POWER LINE



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

2 hr.

4. Do you think additional search might

recover evidence? Yes X No _____

5. Signature Jim Schorom

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. P-23
(Alphabetical - Numerical)BOOK # 1
PAGE # 24LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 21W
CENTER 1/4Mer. N.F. CHIPPEWA County CASS
Corner common to sections _____State MINN
24

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing used to Cert.
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species ASPEN R. OAK
Diameter 12" 8"
Bearing N69°E S16°W
Distance 28LKS 15LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1963 By C.A. SCHLUTER
FOUND BRASS CAP BUT NO BEARING TREES

Bearing Trees, Reference Objects

NONE NONE



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

A BLUE LINE RUNS FROM A TAG ON A TREE TO THE CORNER FROM THE OLD RICE CAMP ROAD ON SQUAW POINT.

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. COMPASS AND CHAINING

3. Man hours spent in search 1/2 HR.

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature CEDRIC A. SCHLUTER

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 N R. 31W 5th Mer. N.F. CHIPPEWA County CASS State MINNESOTA
1/4 Corner common to sections 19 and 24
R30W R31W

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	<u>B. OAK</u>	<u>R. OAK</u>
Diameter	<u>14</u>	<u>12</u>
Bearing	<u>S25E</u>	<u>S80W</u>
Distance	<u>20LKS</u>	<u>23LKS</u>

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.
Where filed or recorded _____
Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 2-3-'76 By CURTIS R. KRAUSE
FOUND IRON & CAP IN PLACE IN GOOD CONDITION

Bearing Trees, Reference Objects

Species	<u>W. OAK</u>	<u>R. OAK</u>
Diameter	<u>14</u>	<u>9</u>
Bearing	<u>S32E</u>	<u>N5W</u>
Distance	<u>49LKS</u>	<u>44LKS</u>

Bearing Trees, Reference Objects G.L.O.

Species	<u>W. OAK</u>	<u>R. OAK</u>	<u>W. OAK</u>	<u>R. OAK</u>
Diameter	<u>19</u>		<u>24</u>	<u>9</u>
Condition	<u>INSIDE ROT</u>	<u>ROTTED</u>	<u>SCRIBE OVERGROWN</u>	<u>DOWN LOG ROTTED</u>



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MARKED NEW BT'S: MAPLE 10" N62°E 9.0' MKD. 1/4 S19 BT

W. OAK 12" S63W 70.1 MKD. 1/4 S24 BT

W. OAK 0" N3E 33.75 MKD. 1/4 S19 BT

CORNER IS APPROX. 197' W. OF _____ OF SQUAW PT. RD.. PUT FSLP ON 0"

MAPLE 112' E. OF CORNER - MAPLE IS ON W. SIDE OF SQUAW PT. RD.

ON TOP OF BACK SLOPE OF DITCH. HIKER TRAIL RUN W-SW APPROX. 59'

S. OF CORNER. SUMMER HOMES ROAD ACROSS FROM ABOVE TRAIL RUNS

E-SE

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143 N R. R 31-30W 5th Mer. N.F. Chippewa County CASS State Mn
V4 Corner common to sections 24, 19 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By GLO

Where filed or recorded _____

Monument SET IRON POST 1" DIA. X 36" LONG
(Original, concrete post, iron pipe, etc.)
WITH BRASS CAP

Evidence of Subsequent Corner Restoration Found

Year of search 2-3-76 By CURT KRANSE


Found Monument AND 1919
BTS.

Bearing Trees, Reference Objects

Species	<u>BURR OAK</u>	<u>RED OAK</u>	<u>W. OAK</u>	<u>R. OAK</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>14"</u>	<u>9"</u>
Bearing	<u>S 25° E</u>	<u>S 80° W</u>	<u>S 32° E</u>	<u>N 5° W</u>
Distance	<u>13.2'</u>	<u>15.2'</u>	<u>32.3'</u>	<u>29.0'</u>
	<u>(New 19")</u>	<u>(New Stump)</u>	<u>(New 24")</u>	<u>(Rotte Stump)</u>
	<u>Dying</u>	<u>2-3-76</u>	<u>HOLLOW</u>	

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>W. OAK</u>	<u>W. OAK</u>
Diameter	<u>10"</u>	<u>12"</u>	<u>8"</u>
Bearing	<u>N 62° E</u>	<u>S 63° W</u>	<u>N 30° E</u>
Distance	<u>9.0'</u>	<u>79.1'</u>	<u>33.75'</u>



Sketch 30
 Corner F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines,
 plantations, etc.. Cite source of testimony if any. _____

FROM 1/4 CORNER TO S 1/4 - NOT TIME 150°
 TURN FROM SECTION CORNER OF 13, 18, 19, 24
 0° 42' WEST OF TRW 4 SOUTH LINE.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Monument and BT'S IN GOOD
 CONDITION. SET STEEL POST WITH ATTENTION
 AND BOUNDARY SIGNS 2.5" SOUTH OF Monument

1-29-80
 Jim Schoonover

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 9-21
(Alphabetical - Numerical)

BOOK # 1
PAGE # 75

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5880-11 (5/12/64)

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Minnesota
S 1/16 Corner common to sections 24 and 23

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Year of search _____ By _____
Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____
Diameter 1 1/2 1 1/2 1 1/2 1 1/2 1 1/2 1 1/2 1 1/2 1 1/2
Bearing N 45 W 45 E 45 S 45
Distance _____

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)


Year of search 1967 By M. Sarif

F. S. tag on 12" aspen 6 lks N 58° W

Brass cap found.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____



Sketch

O Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Pacing, chaining, photos, maps, etc. maps, chaining

3. Man hours spent in search 1/2 HOUR

4. Do you think additional search might recover evidence? Yes X No _____

5. Signature M. Sarff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Q-23
(Alphabetical - Numerical)

BOOK # 1
PAGE # 23

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5660-11 (5/12/61)

T. 143 R. 31 Mer. N.F. 5th Chippewa County Cass State Minnesota
C- S1/16 Corner common to sections 24 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____


Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By M. Sarff

Brass cap found.

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Maps, chaining

3. Man hours spent in search 1

4. Do you think additional search might

recover evidence? Yes X No _____

5. Signature

M. Sariff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Q-25
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143 N R. 31-30W 5TH Mer. N.F. CHIPPewa County CASS State Mn
S 1/16 Corner common to sections 24, 19 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed <u>1919</u> By <u>GLO</u> Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search <u>1-31-80</u> By <u>Jim Schoonover</u>
<u>Iron Post 3' Long 2" dia. 28"</u> <u>IN GROUND WITH BRASS CAP.</u>	<u>Found Monument In Good Condition</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species <u>Poplar</u> <u>R. OAK</u> Diameter <u>6"</u> <u>6"</u> Bearing <u>N 68° E</u> <u>WEST</u> Distance <u>151ks.</u> <u>71ks.</u> <u>9.9</u> <u>4.62</u>	<p style="text-align: center;">Bearing Trees, Reference Objects</p> <u>No</u> <u>No</u> <u>TRACE</u> <u>TRACE</u>



25 30
Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Q-25

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

OAK TREE BEARING N24°W 20.7' WITH
 LOCATION STICKER

At time of search:

1. Did you have the record description?

Yes Y No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc.

LINE TO STANDARD

3. Man hours spent in search _____

4 HRS.

4. Do you think additional search might recover evidence? Yes _____ No X

Perpetuation Record

Monument and accessories established. Include brief description of area.

MADE Two B.Ts., AND SET STEEL POST WITH ATTENTION AND Boundary signs 1.87' SOUTH OF Monument

W. OAK

W. OAK

10"

8"

BOTH SCRIBED

N84°E

S24°E

5/16

25.6'

20.7'

SECT. 19

BT.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

5. Signature Jim Schoonover

Identified on aerial photo No. _____ Which is filed at _____

Index No. B-21
(Alphabetical - Numerical)

BOOK # 1
PAGE # 14

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/61)

T. 143 R. 31 Mer. N.F. 5th Chippewa County Cass State Minnesota
Sec. cor. Corner common to sections 23, 24, 26 and 25

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By M. Sarff

Brass cap found.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. maps, chaining

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes No _____

5. Signature M. Sarff

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. R 23
(Alphabetical - Horizontal)

BOOK # 1
PAGE # 18

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/61)

T. 143N R. 31E Mer. N.F. Chippewa County Cass State MIND
1/4 Corner common to sections 24 and 25

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter Wood Cut
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects

Species Red Pine Birch
Diameter 14" 5"
Bearing N 48 1/2 E S 72 1/2 W
Distance 65 LKs 25 LKs

Evidence of Subsequent Corner Restoration Found

Year of search 1963 By _____
Brass Cap Found

None



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

*old rice corner
 on square, runs to
 corner*

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps,

etc. *Chaining &*

Compass

3. Man hours spent in search

4 hrs

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature *[Signature]*

Perpetuation Record

Monument and accessories established. Include brief description of area.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. R 24
(Alphabetical - Book/Case)

BOOK # 1
PAGE # 19

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-5680-11 (5/12/61)

+

T. 143N R. 31W S. 24 Mer. N.F. Chippew County Miss State
E 1/4 Corner common to sections 24 and 5

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species H - D - 1/4 - Tree
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration


Year surveyed 1919 By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1963 By C. Schluter
Found brass cap

Bearing Trees, Reference Objects

Species Birch Red Oak
Diameter 8" 6"
Bearing N 75° E S 10 1/2° W
Distance 25 LKS 65 LKS



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

*A blue line runs from a tree on
 west to the corner from the old
 rice camp road on D. Gray Point.*

At time of search:

1. Did you have the record description?

Yes _____ No t

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Compass +
chaining

3. Man hours spent in search _____

4 hrs

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature J. J. [unclear]

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. R-25
(Alphabetical-Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 143N R. 31-30W 5TH Mer. N.F. CHIPPewa County CASS State Mn
SECTION Corner common to sections 24, 19, 25 and 30

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1919</u> By <u>GLO</u>	Year of search <u>1-31-80</u> By <u>Jim Schoonover</u>
Where filed or recorded _____	
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<u>Monument in good condition</u> <u>AND ONE BT.</u>
<u>Iron Post 3' Long 2" dia. 28" IN</u> <u>GROUND WITH BRASS CAP</u>	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species <u>BIAH</u> <u>Poplar</u> <u>Poplar</u> <u>W.OAK</u>	<u>No</u> <u>No</u> <u>B. of G. W.OAK</u>
Diameter <u>6"</u> <u>8"</u> <u>6"</u> <u>8"</u>	<u>TRACE</u> <u>TRACE</u> <u>TRACE Stub 12' 17"</u>
Bearing <u>N74 3/4° W</u> <u>S57 1/4° E</u> <u>S56 1/2° W</u> <u>N61 1/2° W</u>	<u>55° W</u> <u>N55° W</u>
Distance <u>30 lks.</u> <u>18 lks.</u> <u>21 lks.</u> <u>15 lks.</u>	<u>13.9</u> <u>9.9'</u>
<u>19.8</u> <u>11.9</u> <u>13.9</u> <u>(9.9')</u>	<u>Scar visible</u>



○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

R-25

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Found 2 white oaks with scars. From old scribe. Will remark and tag.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc.

Land line to standard

3. Man hours spent in search _____

4 Hrs.

4. Do you think additional search might recover evidence? Yes _____ No

Perpetuation Record

Monument and accessories established. Include brief description of area.

SET STEEL Post with Attention and Boundary Signs 1.6' NORTH OF MONUMENT.

W.OAK

W.OAK

6"

6"

SCRIBED BT

557°W

522°E

on BOTH.

32.2'

17.0'

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

5. Signature Jim Schramm

Index No. S-17, 18
(Alphabetical - Numerical)BOOK # 1
PAGE # 9
5THLAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 31W
SMCMer. N.F. CHIPPEWA County CASSState MINN

Corner common to sections _____

26

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

New BT

Original Evidence Found

Year of search _____

By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1919By G.L.O.

Where filed or recorded _____

Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search _____


By _____

FOUND IRON & CAP - IN PLACE IN GOOD
CONDITION - 10" ABOVE GROUND

Bearing Trees, Reference Objects

Species R. OAKR. OAKDiameter 67Bearing N52³WS9³WDistance 54LKS81LKS

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. How many hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

BOOK # 1
PAGE # 2

T. 143 R. 31 Mer. N.F. 5th Chippewa County Cass State Minnesota
NW 1/16 Corner common to sections 26 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing N 20° E
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>Red Oak</u>	<u>Red Oak</u>
Diameter	<u>10"</u>	<u>12"</u>
Bearing	<u>N25°E</u>	<u>S39°E</u>
Distance	<u>117 lks</u>	<u>46 lks</u>

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By R. Rockis, & M. Sarff


Brass cap found.

Red Oak

22"

N25°E

117 lks



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. maps and chaining

3. Man hours spent in search

1/2

4. Do you think additional search might recover evidence? Yes No _____

5. Signature Ron Rockis

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

F.S. tag on road on 6" burr oak bears E 7 chs and 79 lks to NW 1/16 Sec. 26.

F. S. bearing tree tag on 22" red oak bears S25°W 117 lks to NW 1/16 of Sec. 26

Oak on slight knob

20 lks S of brass cap old road runs E and W

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. S-23
(Alphabetical - Numerical)BOOK # 1
PAGE # 20LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 143N R. 31W5THMer. N.F. CHIPPEWA County CASSState MINNCENTER NORTH 1/16 Corner common to sections _____25

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing Weeds etc.Distance Monument & near etc.

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.

Where filed or recorded _____

Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species R. OAK N. PINEDiameter 8 12Bearing N31 1/2 E S18 1/2 WDistance 56LKS 22LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____


Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 7-28-76 By CURTIS R. KRAUSEFOUND IRON AND CAP IN PLACE BUT TOP 10" IS
BENT AT 90° TO GROUND - TRY TO STRAIGHTEN
IRON AND IT BROKE OFF=REPLACE GLO IRON WITH
FS CORNER

Bearing Trees, Reference Objects

NONENONE



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

WITNESSED BY:

N. PINE 10" N38E 34.35

W. PINE 10" N86E 43.7'

W. OAK 7" S32E 16.40'

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

TO PERPETUATE THIS CORNER I SET A 2" DIA. X5' LONG GALVANIZED
STEEL PIPE, FILLED WITH CONCRETE AND CAPPED WITH A 3" DIA.
BRASS TABLET MARKED *7143 DR316*
SET GLO IRON AT NORTH EDGE *N 1/4 S 2 E*
AT 2" DIA. IRON PIPE *C*

1976

SET 8' STEEL POST DUE WEST 2.8' W/FS SIGNS 54-2 & 4
SET 0' STEEL POST DUE SOUTH 3.4' W/FS SIGNS 54-2 & 4

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. T-18
(Alphabetical - Numerical)


BOOK # 1
PAGE # 7 LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-5680-11 (5/12/61)

T. 143 R. 31 5th Mer. N.F. Chippewa County Cass State Minnesota
W 1/16 Sec. 26 Corner common to sections 26 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found																				
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____																				
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing <u>N 88° E</u> Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____																				
<p style="text-align: center;">Subsequent Corner Restoration</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p>																				
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	Year of search <u>1967</u> By <u>M. Sariff & R. Rockis</u> <u>BRASS CAP FOUND</u>																				
<p style="text-align: center;">Bearing Trees, Reference Objects</p> <table border="0"> <tr> <td>Species</td> <td><u>Red oak</u></td> <td><u>Red Oak</u></td> </tr> <tr> <td>Diameter</td> <td><u>7"</u></td> <td><u>8"</u></td> </tr> <tr> <td>Bearing</td> <td><u>N 84 1/2° E</u></td> <td><u>S 42° W</u></td> </tr> <tr> <td>Distance</td> <td><u>102 lks</u></td> <td><u>40 lks</u></td> </tr> </table>	Species	<u>Red oak</u>	<u>Red Oak</u>	Diameter	<u>7"</u>	<u>8"</u>	Bearing	<u>N 84 1/2° E</u>	<u>S 42° W</u>	Distance	<u>102 lks</u>	<u>40 lks</u>	<table border="0"> <tr> <td>Species</td> <td><u>Red Oak</u></td> </tr> <tr> <td>Diameter</td> <td><u>13"</u></td> </tr> <tr> <td>Bearing</td> <td><u>S 42° W</u></td> </tr> <tr> <td>Distance</td> <td><u>39 lks</u></td> </tr> </table>	Species	<u>Red Oak</u>	Diameter	<u>13"</u>	Bearing	<u>S 42° W</u>	Distance	<u>39 lks</u>
Species	<u>Red oak</u>	<u>Red Oak</u>																			
Diameter	<u>7"</u>	<u>8"</u>																			
Bearing	<u>N 84 1/2° E</u>	<u>S 42° W</u>																			
Distance	<u>102 lks</u>	<u>40 lks</u>																			
Species	<u>Red Oak</u>																				
Diameter	<u>13"</u>																				
Bearing	<u>S 42° W</u>																				
Distance	<u>39 lks</u>																				



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Woven wire fence south and west from brass cap.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing _____
chaining photos, maps, etc. **Maps & Chaining**

3. Man hours spent in search **1**

4. Do you think additional search might recover evidence? Yes No _____

5. Signature **Ron Rockis**

Perpetuation Record

Monument and accessories established. Include brief description of area.
**USFS bearing tree tag put on 13" red oak that bears N42°E
39 lks to brass cap
Monument on highland on SE corner of pothole**

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. T-19
(Alphabetical - Numerical)BOOK # 1
PAGE # 1LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/81)

T. 143 R. 31 5th Mer. N.F. Chippewa County Cass State Minnesota
C1 Corner common to sections 26 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____ By _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing N 25° E
Distance _____
125

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Red Oak N. Pine
Diameter 12" 20"
Bearing N80°E S77°E(W)
Distance 170 lks 190 lks

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By M. Sarff & R. Rockis
Brass cap found.Species N. Pine
Diameter 24"
Bearing S77°W
Distance 190 lks

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. **Maps and chaining**

3. Man hours spent in search _____

4

4. Do you think additional search might recover evidence? Yes No _____

5. Signature **Ron Rockis**

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

**FS bearing tree tag on 24" red pine bears
 N77°E 190 lks to C of Sec. 26**

**Hardwood on level ground Brass cap in junk pike on E side
 of road**

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. T-1
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

T. 143 R. 31 S. 5th Mer. N.F. Chippewa County Cass State Minnesota

API | AP2

Corner common to sections 26 and _____

Com | SPSR

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By R. Rockis & M. Sarff

Brass cap found.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Maps and chaining

3. Man hours spent in search 1

4. Do you think additional search might

recover evidence? Yes _____ No

5. Signature Ron Rockis

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Mixed hardwoods on level ground. Barb wire fence runs W

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 143N R. 31W
SEC-EAST 1/4

5TH Mer. N.F. CHIPPEWA County CASS

State MINN
26

Corner common to sections _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1919 By G.L.O.
 Where filed or recorded _____
 Monument SET IRON POST WITH BRASS CAP MKD
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species R. OAK R. OAK
 Diameter 12 8
 Bearing S43¹W N62W
 Distance 44LKS 27LKS

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found


Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 8-26-76 By T. JOHNSON
FOUND IRON & CAP IN PLACE - IN GOOD
CONDITION

Bearing Trees, Reference Objects

R. OAK R. OAK
22 13
SCRIBE SCRIBE
OVERGROWN OVERGROWN



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. TO

PERPETUATE THIS CORNER WE SCRIBED 3 NNW BEARING TREES AS

FOLLOWS: W. OAK 7" N81°E 41.65' MKD:CE 1/16 S26 BT

W. OAK 0" S19°E 24.45' MKD:CE 1/16 S26 BT

R. OAK 10" N15°W 11.55' MKD:CE 1/16 S26 BT

SET 8' STEEL SIGN POST DUE SOUTH 4.1' W/F.S. SIGN 54-4

PUT FSLP ON 12" R. OAK S. SIDE SQUAW PT. RD. CORNER IS 51S'

SOUTH OF TAG. PUT FSLP ON 10" R. OAK W. SIDE CORNER IS S58°W

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 7-419
(Alphabetical - Numerical)BOOK # 1
PAGE # 2LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-660-11 (5/12/61)

T. 143 R. 31 5th Mer. N.F. Chippewa County Cass State Minnesota
Corner common to sections 26 and _____

SPSR

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____


Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By R. Rockis & M. SarffBrass cap found.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
Yes No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. Maps & chaining

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No

5. Signature Ron Rockis

Perpetuation Record

Monument and accessories established. Include brief description of area. _____
Flat land of hardwoods on N side of cemetery

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____

7-11-19-20

BOOK #1
PAGE #4

Index No. _____
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

T. 143 R. 31 Mer. N.F. Chippewa County Cass State Minnesota

Corner common to sections 26 and _____

SPSR
AP3
AP4

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1967 By R. Rockis & M. Sarff

Brass cap found.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Maps and chaining

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Ron Rockie

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Mixed hardwoods on level ground.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____