

LEGEND

○ = Corner having information on form 7100-52 in this file.

T145N R29W 5th PM


FILING INSTRUCTION

(Ref. FSM 7160)

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.



T. 145 R. 29 5th Mer. N.F. VII. ILLINOIS County CASS State MO.
SECTION 4 Corner common to sections 5, 6, 31 and 32

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>JACK PINE</u>	<u>JACK PINE</u>
Diameter	<u>8"</u>	<u>15"</u>
Bearing	<u>N 34 E</u>	<u>S 68 W</u>
Distance	<u>18 Links</u>	<u>67 Links</u>

Subsequent Corner Restoration

Year surveyed 1934 By G.L.O.
 Where filed or recorded Secretary of State
 Monument 6" dia x 24" conc. mon with 3 1/2" brass cap.
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>JACK PINE</u>	<u>JACK PINE</u>	<u>JACK PINE</u>	<u>JACK PINE</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>8"</u>	<u>6"</u>
Bearing	<u>N 22 E</u>	<u>S 17 E</u>	<u>S 57 1/2 W</u>	<u>N 16 W</u>
Distance	<u>12 Links</u>	<u>11 Links</u>	<u>48 Links</u>	<u>35 Links</u>

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found


Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Evidence of Subsequent Corner Restoration Found

Year of search 1964 By William Okerman
Found a concrete monument set by G.L.O.
Resurvey in 1934 with a 3 1/2" dia. brass cap

Bearing Trees, Reference Objects

Species	<u>JACK PINE</u>	<u>JACK PINE</u>	<u>Steel sign Post</u>
Diameter	<u>10"</u>	<u>12"</u>	<u>72" long 24" in dia. rod</u>
Bearing	<u>S 65 W</u>	<u>N 40 W</u>	<u>N 78 W</u>
Distance	<u>16.5</u>	<u>154.1</u>	<u>3.2'</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

A-5

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. CORNER IS IN NORWAY

Pine Plantation

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Photo

3. Man hours spent in search 0

4. Do you think additional search might

recover evidence? Yes _____ No X

5. Signature Anthony E. Keiser

Perpetuation Record

Monument and accessories established. Include brief description of area.

Found 6" Conc. Mon. with 3/2" brass cap. as evidenced by William O. Kerman certificate No. 379. bearing trees found o.k. also steel fence post o.k. tagged bearing trees & added sign to steel fence post.

Certified corner restoration certificate prepared: Yes X No _____

Filed in county records at walker Date 2-2-65 County Document No. 379

Identified on aerial photo No. _____ Which is filed at _____

Index No. AS
(Alphabetical - Memorials)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RS-5680-11 (5/12/74) 4

T. 145 N R. 29 W Mer. N.F. CHIPPEWA County CASS State MINN.
Section Corner common to sections 5, 6, 31 and 32

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____


Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections -----
 Object -----
 Record distance -----
 Measured distance -----

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Good grasses in concrete monument and good bearing trees.

At time of search:

1. Did you have the record description?

Yes _____ No ✓

2. How was search area located?

Pacing, chaining, photos, maps, etc. Compass + bearing tree and road.

3. Man hours spent in search 0

4. Do you think additional search might recover evidence? Yes _____ No ✓

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____


5. Signature S. B. Jalukhe

LAND CORNER RECORD

5680-2

1. T 145 R 29 No. A-9 Cor. S Mer. 5th State MINNESOTA N.F. CHIPPEN Dist. CASS LAKE

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

J. Pine	28.00'	186.78'
J. Pine	23.10'	
J. Pine		26.4'
J. Pine		31.68'

7. Photo Identification

Photo No. DET. A-12-222
Ident. By: 2/24/59

8. Plane Coordinate Position Data

State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

5. Investigation Notes:

WITNESS TREE WAS FOUND BY D. MARTIN ON HIS TIMBER SALE. AREA IS IN A CLEARCUT. WITNESS TREE IS A MATURE JACK PINE 2" DBH ABOUT TO DIE. TREE MAY BE LOCATED AS FOLLOWS

North from US#2
TAKE I R #2348, FIND ROAD TO MARINE CAMP (2 km E)

of some on of the 2 ... TAKE WOOD ROAD ... FOR
about 500. ... IS AB ... ROAD - IT'S
T-10 ... A ... - FIELD OF ... 1500
... A ... D R ...

9. Evaluation

Authentic X
Needs Verif. X Monument X
Re-estab. _____ Survey _____
Land Status _____

6. Signed M. Reed Title Asst. Ranger Date 2/9/61

7
16
S

PERPETUATION RECORD

10. Monument :

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

License _____ Agency _____ Date _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:

LAND CORNER RECORD

5680-2

1. T ¹⁴⁶ 145 R ²⁷ 29 No. A-11 Cor. 1/4 Mer. 5 State MINN. N.F. _____ Dist. _____

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

7. Photo Identification
 Photo No. _____
 Ident. By: _____

5. Investigation Notes:

Found GLO Bras capped iron pipe proj
 6" above ground c. 1/4 ³³³/₃₄ 1934 USGL
 From w bears a Red pine snag (40' high) 2
 MKD 1/4 S 33.0 N 14° E 56.0'
 F.S. Poster is on J. Pine from which
 22'

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation
 Authentic _____
 Needs Verif. _____ Monument _____
 Re-estab. _____ Survey _____
 Land Status _____

6. Signed Robert N. K... Surveyor, Teek Date _____

PERPETUATION RECORD

10. Monument :

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:

Index No. 15

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

145 N 29 W

T. 146 N R. 29 W

5th

Mer. N.F.

Chippewa

County Cass

State MINN.

Quarter

Corner common to sections 34

3

and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species J. Pine

Diameter 5"

Bearing N35°W

Distance 6 Lks

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1934 By G.L.O.

Where filed or recorded State Capitol

Monument Iron Post w/ brass Cap MKD
(Original, concrete post, iron rod, etc.)

$\frac{1}{4}$ 534
7 53
1934

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects

Species J. Pine

Pine Post

Diameter 7"


6"

Bearing N78°W

N78°W

Distance 248 Lks (163.68')

248 Lks (



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections 3-34
Object road bearing N15°E
Record distance 10.50 ch East to road
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search: _____

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

5. Signature _____

T. 145 R. 29 S. 5th Mer. N.F. Chippewa County Cass State MU.
NADA 1/16 Corner common to sections 5 and 6

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
 Original monument NONE
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species NONE
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed NONE By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species NONE
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search NONE By _____
 Monument found _____

Original Bearing Trees Found


Species NONE
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1981 by T. Kerick
Set 2" x 5' Iron pipe with brass cap:
Set three bearing trees with nail
on side

Bearing Trees, Reference Objects

Jack Pine	Jack Pine	Jack Pine
10"	11"	11"
N22°W	S76°30'W	S34°E
9.15'	19.05'	26.97'



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. None

3. Man hours spent in search None

4. Do you think additional search might
recover evidence? Yes X No _____

5. Signature Anthony P. Kerick

Relation of Evidence to Record Features Along Section Lines

B-5

Section line to sections E 1/4 COR. SEC. 6 to NE COR. 6

Object

2" 45' EROD PIPE with brass cap - 8" CONC. MON. WITH BRASS CAP

Record distance

41 Chains 1320 15 14.71 North

Measured distance

3105.16 2706 3105.16 at the E 1/4 COR.

SET COR. ON LINE SINGLE PROPORTION

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. COR FALK SOUTH OF PINE Tree Plantations. Approx 100 ft.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

North 1/16 CORNER IS ON HIGH GROUND

All bearing trees scribed, painted and tagged

Set 8' Fence Post, Approx 5' North and South of Corner with double signs.

CERTIFICATE FILED

Perpetuation certificate prepared by _____ Yes _____ No _____

Anthony Kerick

Filed in County of Missouri

Case Date 9/29/82

County Document No. 265249

Identified on aerial photo No. _____

Which is filed at _____

T. 145 R. 29 S. 5th Mer. N.F. Chippewa County Cass State MN.
Quarter Corner common to sections 5 and 6

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>yellow Pine</u>	<u>Black Pine</u>	
Diameter	<u>18"</u>	<u>6"</u>	
Bearing	<u>S56°W</u>	<u>N40°E</u>	
Distance	<u>70 links</u>	<u>50 links</u>	

Original Evidence Found

Year of search 1981 By T. Kerick

Monument found NONE

Original Bearing Trees Found

Species	<u>NONE</u>		
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed NONE By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1981 By T. KERICK


Set 2" x 5" Iron Pipe with brass cap;
Set Three new bearing trees with
nail on side

Bearing Trees, Reference Objects

Species	<u>NONE</u>		
Diameter			
Bearing			
Distance			

Bearing Trees, Reference Objects

<u>JACK PINE</u>	<u>JACK PINE</u>	<u>JACK PINE</u>
<u>8" - 4"</u>	<u>10"</u>	<u>8"</u>
<u>N45°30'W</u>	<u>S85°W</u>	<u>S74°E</u>
<u>N 9.05'</u>	<u>17.22'</u>	<u>10.38'</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

C-5

Section line to sections SE COR. SEC. 6 TO NE. COR. SEC. 6
 Object 2" X 5' Iron Pipe with brass cap, 6" CONC. MIN. WITH CAP
 Record distance 81 chains = 5346' 2640' X 3029.42
 Measured distance 6134.57' 5846' 6134.58' 9014' FROM SE COR. 6
 Set COR. by Lo. Method; Proportional distance.

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. NONE

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. Chaining Photos Maps

3. Man hours spent in search 5 HOURS

4. Do you think additional search might recover evidence? Yes NO

5. Signature Anthony E. Kerick

Perpetuation Record

Monument and accessories established. Include brief description of area. ORIGINAL NOTES SHOW NO PHYSICAL TIES TO ANY WET LANDS CROSS 3 SUBSTANTIAL SWAMPS. 40 CHAINS NORTH FROM SE COR OF 6 LANDS IN SWAMP; 41 CHAINS SOUTH OF NE COR. 6 FALLS IN SWAMP; THERE ARE NO OCCUPATION LINES; ALL NEW MARKING TREE SCRIBED, PAINTED AND TAGED. SET 8' STEEL FENCE PEGS APPROX. 5' NORTH AND SOUTH OF CORNER WITH DOUBLE TIES.

Certification certificate prepared: Yes No
 Filed in county Cass Date 9/27/82 County Document No. 265247
 Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 S. 5th Mer. N.F. LAIPPEWA County CASS State MO.
Quarter Corner common to sections _____, _____, and 7

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Black Pine Black Pine
Diameter 7" 5"
Bearing S35°E N6°E
Distance 5 LINKS 34 LINKS

Subsequent Corner Restoration

Year surveyed 1958 By Peter J. Meyer
Where filed or recorded CASS CO. COUNTY RECORDER
Monument 2" x 5" Iron Pipe with Brass Cap
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Jack Pine Jack Pine Red Pine
Diameter 8" 7" 6"
Bearing N58 1/2° W S25 1/2° W N76° E
Distance 10.3' 8.5' 8.4'

Original Evidence Found

Year of search 1758 By Peter J. Meyer
Monument found NONE

Original Bearing Trees Found


Species Jack Pine windfall
Diameter 10"
Bearing N6°E
Distance 34 LINKS

Evidence of Subsequent Corner Restoration Found

Year of search 1981 By Tony Kerick
Found 2" x 5" Iron Pipe with brass cap
and three bearing trees set by Peter J. Meyer
in 1958.

Bearing Trees, Reference Objects

Species Jack Pine Jack Pine Red Pine
Diameter 9" 7" 8"
Bearing N58 1/2° W S25 1/2° W N76° E
Distance 10.3' 8.5' 8.4'
(windfall) (Stump)



Sketch

○ Corner ◻ F.S. Land

Relation of Evidence to Record Features Along Section Lines

E-3

Section line to sections N 1/4 7 to NE. 7
 Object 2" Brass capped MONUMENTS
 Record distance 40 chains
 Measured distance 2578.82

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. NONE

8' SIGN POSTS S 2.85' 8' SIGN POST E 3.8' CK

At time of search:

1. Did you have the record description?
 Yes X No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. Photos Maps

3. Man hours spent in search 1 hr

4. Do you think additional search might
 recover evidence? Yes X No _____

5. Signature Anthony E. Kerick

Perpetuation Record

Monument and accessories established. Include brief description of area.

Set Two New Bearing Trees, scribed, painted and Tagged:

RED Pine with nail on side
10"

Jack Pine with nail on side
10"

N 28° E
12.45'

S 25 1/2° W
15.77'

Tornado Passed Through Area there are many blow down

Tagged all bearing trees; set 1 fence post approx 5' south 3.5' East

of corner south signed
 Certified corner restoration certificate prepared: Yes X No _____
Anthony Kerick

Filed in county records at Case Date 9/29/62 County Document No. 265251

Identified on aerial photo No. _____ Which is filed at _____

CERTIFICATE

FILED

T. 145 R. 29 Mer. N.F. Chippewa County Cass State MN.
East 1/16 Corner common to sections 6 and 7

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument NONE
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species NONE
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed NONE By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species NONE
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search NONE By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1981 By T. KERICK
Set 2" x 5' Iron Pipe with brass cap
set Three bearing trees with nail
on side

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects		
<u>JACK Pine</u>	<u>JACK Pine</u>	<u>JACK Pine</u>
<u>15"</u>	<u>12"</u>	<u>8"</u>
<u>N82°W</u>	<u>N70°W</u>	<u>S88°W</u>
<u>75.08'</u>	<u>66.98</u>	<u>87.97'</u>



Sketch

○ Corner ▣ F.S. Land

Relation of Evidence to Record Features Along Section Lines

E-4

Section line to sections North 1/4 SOR Sec. 7 to NE. COR. Sec. 7
 Object 2' brass capped monuments
 Record distance 20 chains
 Measured distance 1299.41
set on line split

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. NONE

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. NONE

3. Man hours spent in search NONE

4. Do you think additional evidence can be recovered? Yes _____ No _____

5. Signature Anthony S. Kerck

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

E 1/4 CORNER set in a swamp.
all bearing trees scried, painted and tagged.
set 8' fence posts approx 8' East and west of corners
with double signs.

8' SIGN POST W 2.7' 8' SIGN POST E 4.15'

CERTIFICATE FILED

Certificate of Association prepared: C Yes Anthony Kerck No _____
 Filed in county records at CLM Date 7/29/82 County Document No. 265250
 Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 S. 5th Mer. N.F. Chippewa County Cass State MN.
SECTION _____ Corner common to sections 5, 6, 7 and 8

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, post, etc.)

Bearing Trees

Species Black Pine Black Pine
Diameter 12" 10"
Bearing S 37° E N 45° E
Distance 33 links 54 links

Subsequent Corner Restoration

Year surveyed 1958 By Peter J. Meyer
Where filed or recorded Cass Co. County Recorder
Monument 2" x 5" Iron Pipe with brass cap
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>
Diameter	<u>9"</u>	<u>10"</u>	<u>6"</u>	<u>7"</u>
Bearing	<u>S 12° E</u>	<u>S 58° E</u>	<u>N 80° E</u>	<u>N 34° E</u>
Distance	<u>48.0'</u>	<u>29.0'</u>	<u>53.5'</u>	<u>18.2'</u>

Original Evidence Found

Year of search 1958 By Peter J. Meyer
Monument found NONE

Original Bearing Trees Found

Species Jack Pine
Diameter 20"
Bearing N 45° E
Distance 54 links

(und soil)

Evidence of Subsequent Corner Restoration Found

Year of search 1981 By T. Kerick
No Evidence of original corner, Found
one original bearing tree; Found 2" x 5"
Iron pipe with brass cap and four bearing
trees set by Peter J. Meyer in 1958
(original) Jack Pine 20" N 45 E 54 links (stump)


Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Jack Pine</u>
Diameter	<u>11"</u>	<u>11"</u>	<u>7"</u>	<u>7"</u>
Bearing	<u>S 12° E</u>	<u>S 58° E</u>	<u>N 80° E</u>	<u>N 34° E</u>
Distance	<u>48.0</u>	<u>29.0</u>	<u>53.5'</u>	<u>18.2'</u>

(Dead)

(stump)

(Dead)



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

E-5

Section line to sections N 1/4 COR 7 to NE COR 7
 Object 2" brass capped monuments
 Record distance 40 chains
 Measured distance 2598.82

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. NONE

8' SIGN POST N 5.7' 8' SIGN POST W 5.2'

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Photos, Maps

Chaining

3. Man hours spent in search 2 Hours

4. Do you think the search might recover evidence? Yes _____ No _____

CERTIFICATE

Perpetuation Record

Monument and accessories established. Include brief description of area.

Set ONE new bearing tree, scribed, painted and tagged
JACK PINE with nail on side

8"
N 50° E

46.20'

Tornado passed through area there are many blow downs
Set bearing tree tags on all other bearing trees

Set 8' sign fence just approx. 5' west and 5' north of corner

Certified corner restoration certificate prepared by Anthony Kerick Yes _____ No _____

Filed in public records at Cass Date 9/29/82 County Document No. 265248

Identified on aerial photo No. _____ Which is filed at _____

5. Signature Anthony E. Kerick

FILED

Index No. G-21
(Alphabetical - Numerical)

Book #1
Page #33

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/13/67)
GPO 806-924

T. 145 R. 29 Mer. N.F. CHIPPEWA County CASS State MN
QUARTER BET. Corner common to sections 11 and 12

EXISTING SURVEYS

Original Government Survey

Year surveyed JAN. 2 1894 P.H. CONGER
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species BL. PINE BL. PINE
Diameter 12 14
Bearing N9E N8W
Distance 232 LKS. 334 LKS.
153.1' 220.4'

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search 6-15-84 By Hayes, Allison & Bruma
Monument found none


Original Bearing Trees Found

Species none
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

6-15-84 Chained 2640' North from ^{11/12} and moved E in swamp to fit original swamp call. No evidence of BT's found but there are many jackpine stumps in the area. *M.H.*

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No *M.H.*5. Signature *Quentin K. Krause*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 11
(Aligns with Memorized)

notes by 145 30

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

T. 29W & 5th Mer. N.F. Chippewa County Cass State Minnesota
 Section 13 Corner common to sections 13, 18, 12 and 7

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By _____

Where filed or recorded _____

Monument Brasscap set in concrete
(Original, concrete post, iron rod, etc.)


Evidence of Subsequent Corner Restoration Found

Year of search 1964 By CEDRIC SCHLUTER
Found corner

Bearing Trees, Reference Objects

Species	<u>J. P.</u>	<u>J. P.</u>	<u>J. P.</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>14"</u>
Bearing	<u>N76 1/2 E</u>	<u>S57 3/4 E</u>	<u>N14 W</u>
Distance	<u>213 lks</u>	<u>118 lks</u>	<u>466 lks</u>

T115 R30W T115N R29W



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Compass & chaining

3. Man hours spent in search 1 hr

031

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature CEDRIC A. SCHLUTER

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Corner is in low, brushy meadow. Two B.T.'s remain. One is alive and the other is a snag.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 5th Mer. N.F. Chippewa County Cass State MN.
Quarter Corner common to sections 7 and 18

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
 Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>8"</u>	<u>5"</u>
Bearing	<u>N5°E</u>	<u>S37°E</u>
Distance	<u>7 links</u>	<u>17 links</u>

Subsequent Corner Restoration

Year surveyed 1958 By Peter J. Meyer
 Where filed or recorded Cass Co. County Recorder
 Monument 2" X 5" Iron Pipe with brass cap
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>5"</u>	<u>4"</u>	<u>4"</u>
Bearing	<u>N46°W</u>	<u>S24°E</u>	<u>N26°E</u>
Distance	<u>21.2'</u>	<u>8.9'</u>	<u>9.6'</u>

Original Evidence Found

Year of search 1958 By Peter J. Meyer
 Monument found 3" X 3" Scridal cedar post partly decayed

Original Bearing Trees Found

Species	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>10"</u>	<u>9"</u>
Bearing	<u>N5°E</u>	<u>S37°E</u>
Distance	<u>7 links</u>	<u>17 links</u>

(windfall) (windfall)


Evidence of Subsequent Corner Restoration Found

Year of search 1981 By T. Kerick
No Evidence of original survey
found 2" X 5" Iron pipe with brass cap
and two bearing trees set by Peter J. Meyer
in 1958

Bearing Trees, Reference Objects

Species	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>6"</u>	<u>5"</u>
Bearing	<u>N46°W</u>	<u>N26°E</u>
Distance	<u>21.2'</u>	<u>9.6'</u>

(windfall)



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

J-3

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. None

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. chaining, photos, maps

3. Man hours spent in search 1 Hour

4. Do you think Yes you might recover evidence?

5. Signature Anthony E. Keirch

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Set two new bearing trees, scribed, painted and tagged

Tamarack with nail on side

Cedar with nail on side

5 1/2" S 32° W 1-33'

6" S 31° 30' E 19.27

Set 8' Steel Fence post approx. 5' East and 5' North of corner and double signed post

Certified corner restoration certificate prepared: Yes Anthony Keirch No _____
 Filed in county records at Cass Date 9/29/82 County Document No. 265246
 Identified by serial photo No. _____ Which is filed at _____

CERTIFICATE FILED

Index No. J-6
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 5 Mer. N.F. CHIPPEWA County CASS State MN.
WEST 1/16 Corner common to sections _____, _____, 8 and 17

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found


Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 3-15-82 By CK-LS.
CHAINED TO EAST FROM IRON PIPE
AT SEC. COR. - 1320' E TO APPROX.
W 1/16 COR. - PLACE FSLP ON 4" W. OAK
ON E. SIDE - 15' E OF TAG IS APPROX.
W 1/16 - THEN RUN SOUTH TO WOODS TRAIL
Bearing Trees, Reference Objects OVER



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

DISTRICT NEEDS LINE N & S
 FROM APPROX. W 1/4 TR. SOUTH 2200'S E OF
 WOODS ROAD NW-SE-BACK ROAD INTO JOB CORP CAMP
 AT LYDICK LAKE - OUR LINE AT WOODS ROAD WAS
 125' E OF OLD FIELD TO SW

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature Curt Kramer

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-9
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 Mer. N.F. CHIPPEWA County CASS State MN.
SECTION Corner common to sections 8, 9, 16 and 17

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 P. H. CONGER
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	N. PINE	N. PINE	N. PINE	N. PINE
Diameter	<u>20</u>	<u>18</u>	<u>20</u>	<u>24</u>
Bearing	<u>N70E</u>	<u>S28E</u>	<u>S22W</u>	<u>N81W</u>
Distance	<u>100 LKS.</u> <u>66.0'</u>	<u>58 LKS.</u> <u>38.3'</u>	<u>70 LKS.</u> <u>46.2'</u>	<u>75 LKS.</u> <u>49.5'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____


Evidence of Subsequent Corner Restoration Found

Year of search 1-13-75 By C. KRAUSE
FROM IRON PIPE AT SW COR. 7-8-17-18
CHAINED TO EAST TO STATION S290'E
ESTABLISH APPROX. COR. - PLACE FSLP ON
12" N. PINE ON SOUTH SIDE AS APPROX. COR.
NO EVIDENCE OF ORIG. TIES ON BACK

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

OVER



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

FROM 2" IRON PIPE AT SW COR. 7-8-17-18 RAN EAST TO
 THROUGH PINE PLANTATION
 1685'E 1/2 OF LYNDEN RD N+S
 4245'E 1/2 OF FW 100 NW-SE
 4380'E THEN 125'S; 6" CEDAR POST WITH OLD TAG
 4990'E 24" N. PINE BLAZED EFW 10' S OF OUR LINE
 5100'E ENT. N. PINE PLANTATION (CCU)

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 3 HRS.

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature Carl Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

5290'E BEY. APPROX. LEG. COR.
 EVERY THING IN AREA HAS BEEN SHEARED YEARS AGO
 AND PUSHED INTO WIND ROWS - SNAGS IN PILES SHOW BURN
 AND PIECES OF STAMPS FD. ARE BARELY BURNED ALSO
 NO TRACE OF ORIG. COR. COULD BE LOCATED

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-13
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 S. 5 Mer. N.F. CHIPPEWA County CASS State MN.
SECTION Corner common to sections 9, 10, 15 and 16

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 P. H. CONGER

Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species <u>TAM</u>	<u>TAM.</u>
Diameter <u>4</u>	<u>6</u>
Bearing <u>S31W</u>	<u>S68E</u>
Distance <u>150 LKS.</u>	<u>69 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1-13-75 By C. KRAUSE

CHAINED FROM APPROX. SEC. COR. 8-9-16-17

DUE EAST 5275 TO APPROX. SEC. COR.

9-10-15-16 - PLACED FSLP 7" TAM.

ON W SIDE AS APP ROX. SEC. COR.


NO EVIDENCE OF ORIG. TIES ON BACK

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

FROM APPROX. SEC. COR. 8-9-16-17 EAST TO
 800'E INT. BRUSH SWP. NW-SE
 3040'E OF FINN ROAD N+S
 3300'E INT. SPRUCE SWP. N+S
 3900'E LN. SPRUCE SWP. - INT. J. PINE
 4350'E INT. TAMM SWP. SWP NW-SE
 5275'E APPROX. SEC. COR. 9-10-15-16

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

SEARCHED IN TAMM + SPRUCE SWP. - NOT MANY TREES LIVING
 IN AREA HEAVY BRUSH - NEED FOR LINE WAS WE TRÉSPASSED
 ON STATE LAND - CUT THERE J. PINE - DISTRICT RAN LINE
 FROM PHOTO AND PICKED WRONG SWAMP AS THERE LINE
 E+W WAS 750' TO FAR NORTH - NOTIFIED (STATE FORESTER)
 AS TO OUR LINE AND APPROX. COR. HAROLD LEE

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps
 etc. _____

3. Man hours spent in search 3 HRS.

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature Curt Krause

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 S. 5 Mer. N.F. Chippewa County Cass State Md
Section Corner common to sections 11, 12, 13 and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed Jan. 1874 - P.H. Carger
 Original monument Wood post
(Wood post, stone, pile of stones, etc.)

Bearing Trees
 Species B. Pine B. Pine B. Pine
 Diameter 3" 6" 7"
 Bearing N67°E S85°E S41°W
 Distance 260 lks 337 lks 816 lks
(171.60 ft) (222.42') (56.76')

Subsequent Corner Restoration

Year surveyed 1958 By Meyer (Lausche & Bohn)
 Where filed or recorded USFS Book #1 Page #6 - Cert #21
 Monument 2" x 1/2" standard monument
(Original, concrete post, iron rod, etc.)
RLS # 3628

Bearing Trees, Reference Objects

Species B. Pine Tam. Tam.
 Diameter 20" 14" 6"
 Bearing S57°W S22°E S56°E
 Distance 103.5' 62.0' 103.0'

Original Evidence Found

Year of search 1958 By Lausche & Bohn
 Monument found -

Original Bearing Trees Found


Species B. Pine stub
 Diameter 10"
 Bearing S41°W
 Distance 56.8' ← (also fd. 6-15-84)
up scribe

Evidence of Subsequent Corner Restoration Found

Year of search 6-15-84 By Hayes, Prama, Allison
fd. monument in place, up 24" and larning

Bearing Trees, Reference Objects

Not fd. Dead Tam. Dead Tam.
 Diameter 17" 7"
 Bearing S22°E S56°E
 Distance 62.0' 103.0'



Sketch

O Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature

M. L. Hayes

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

6-15-04 Took a new tie N. Pipe, 4", S32°E, 217.8', scribed. Also put new tags on tl. orig. and 1250 trees.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-21
Alphabetical - Numerical

*Book #1
Page #46*

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

2 of 2

29-5680-11 (5/12/64)

T. 145 R. 89

5th

Mer. N.F. Chippewa

County Cass

State Minnesota

Corner common to sections

11

12

13

and 14

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found.

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing Restoration Certificate on file
Distance _____

Subsequent Corner Restoration


Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1-5-68 By J. Morrison
Tag on N side of 12" Tamarack - notes
on tag say corner lies 62 ft - N. 22° W
from tag, but I was unable to
locate because of deep snow.
This tag put up by Lonsdale &
Rehn on 11-5-58
It may be desirable to check this
location when snow goes down



Sketch

○ Corner ▨ F.S. Land

J-21 Relation of Evidence to Record Features Along Section Lines 2 of 2

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

- At time of search:
1. Did you have the record description?
 Yes _____ No
2. How was search area located?
 Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 1
4. Do you think additional search might recover evidence? Yes _____ No

Certified corner restoration certificate prepared: Yes _____ No _____
 Filled in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

5. Signature *J. Morrison*

Index No. J-23
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145N R. 29W 5TH Mer. N.F. CHINAHA County _____ State MA
74 Corner common to sections 12, 13 and _____

EXISTING SURVEYS

Original Government Survey
Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Original Evidence Found
Year of search 1958 By P. MEYERS
Monument found _____

Bearing Trees
Species BL. PINE BL. PINE
Diameter 6" 4"
Bearing N54°E S85°E
Distance 1001Ks 142Ks
66.0' 93.72'


Original Bearing Trees Found
Species BL. PINE
Diameter 16" STUMP
Bearing N54°E
Distance 660'
BT VISIBLE

Subsequent Corner Restoration
Year surveyed 1958 By P. MEYERS
Where filed or recorded _____
Monument 2" DIA. 5' LONG IRON PIPE
(Original, concrete post, iron rod, etc.)
B/C MAP T145N R29W
Y4 512

Evidence of Subsequent Corner Restoration Found
Year of search 12-29-80 By SCHNEIDER
IRON IN PLACE 2' ABOVE GROUND

Bearing Trees, Reference Objects
Species R. PINE R. PINE J. PINE
Diameter 13" 16" 4"
Bearing S48°W S26°E N61.5°E
Distance 80.1' 82.5' 66.9'

Bearing Trees, Reference Objects
Species R. PINE R. PINE J. PINE
Diameter 20" 20" 8' SNAG 9"
Bearing S48°W S26°E N61.5°E
Distance 80.1" 87.5' 66.9'



Sketch

○ Corner ▣ F.S. Land

Relation of Evidence to Record Features Along Section Lines

J. 23

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

7-5-67 Jim Ekstrom was in and iron was torn out by DAZARS so set new iron from B13 MKD

T145N R29W

X 512
 513

1967
 RLS No 6907

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps, etc. COMPASS

3. Man hours spent in search 1 HR.

4. Do you think additional search might recover evidence? Yes No

Perpetuation Record

Monument and accessories established. Include brief description of area.

MKD NW 1/4 BT. TAGGED and Painted 1958 BTs

W. 1/4 BT

547° E
 49.2'

CERTIFICATE FILED

Qualified corner _____ certificate prepared: Yes No _____
 Filed in county _____ Date 9/14/82 County Document No. 264972
 Identified on aerial photo No. _____ Which is filed at _____

5. Signature Jim Schoonover

T. 145 N. R. 29 W. Mer. N.F. Chippewa County Cass State MN
1/4 Corner common to sections 13, 18, and
145-29 145-28

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees
Species Jack Pine Nor. Pine
Diameter 8" 20"
Bearing West N84 1/2° E
Distance 60 lbs 4 lbs
39.60' 2.64'

Subsequent Corner Restoration

Year surveyed 1955 By Harold Lum - Cass Co. Survey
Where filed or recorded Book # 270
Monument 1 1/2" x 3/4" pipe
(Original, concrete post, iron rod, etc.)

This corner was supposedly set from J. Lucas's map cor.

Bearing Trees, Reference Objects

Species Jack Pine Jack Pine
Diameter 14" 8"
Bearing S 54° W Mag. N 90° E Mag.
Distance 11.6' 4.9'

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1958 By McDonald - Meyer
Corner was found to be marked by a 1 1/2" x 3/4" pipe. No original evidence found

Bearing Trees, Reference Objects

J. Pine J. Pine
Diameter 14" 8"
Bearing S 10° W true N 79° E
Distance 11.6' 4.9'

no sec. br. just blazed


Relation of Evidence to Record Features Along Section Lines

Section line to sections 13-18 13-18

Object Pr. of dry marsh Wedge of Marsh

Record distance 16.56' 25.50'

Measured distance _____



Sketch

○ Corner ■ F.S. Land

At time of search:

1. Did you have the record description?
 Yes No

2. How was search area located?
 Pacing, staining, photos, maps,
 etc. _____

3. Man hours spent in search 2 1/2

4. Do you think additional search might recover evidence? Yes No

5. Signature M.C. Hayes

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. 7/9/60 Klaus, No Donald Hayes searched for original evidence in an area between South and 0.1000 West of the property traps set by Meyer. Area had been furrowed and planted (supposed to be CCC work) Was now covered with roots aspen, hemlock. Some of the planted J. Pine stumps were visible with some older Red Jack Pine stumps around. No evidence was found.

Perpetuation Record

Monument and accessories established. Include brief description of area.
1958. Set a 2" dia x 5' long pipe with brass tablet stamped Mark 3 new B.T.'s
W. Oak R. Oak J. Pine
8" 5 20'E 7" 2 1/2"
44.5' 39.8'
1958
R 89 W 1/4 R 28 W 1/4
513 | 518
A.L.S. No. 3628

CERTIFICATE FILED

Certified corner restoration certificate prepared: Yes No

Filed in county records at Doss Date 4/21/60 County Document No. 11

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 S. 5 Mer. N.F. CHIP County CASS State MN.
SECTION Corner common to sections 17, 18, 19 and 20

EXISTING SURVEYS

Original Government Survey			
Year surveyed	<u>1874</u>		
Original monument	<u>WOOD POST</u> <small>(Wood post, stone, pile of stones, pipe, etc.)</small>		
Bearing Trees			
Species	<u>Y. PINE</u>	<u>Y. PINE</u>	<u>Y. PINE</u>
Diameter	<u>16"</u>	<u>14"</u>	<u>10</u>
Bearing	<u>N19°E</u>	<u>N30W</u>	<u>S28E</u>
Distance	<u>20</u>	<u>20</u>	<u>16</u>
Feet =	<u>13.2</u>	<u>13.2</u>	<u>10.6</u>

Original Evidence Found	
Year of search	<u>1958</u> By <u>R. H. McDONALD</u>
Monument found	<u>NONE</u>
Original Bearing Trees Found	
Species	<u>PINE STR.</u>
Diameter	<u>24"</u>
Bearing	<u>N19°E</u>
Distance	<u>13.2</u>
	<u>"BT"</u>


Subsequent Corner Restoration	
Year surveyed	<u>1958</u> By <u>R. H. McDONALD</u>
Where filed or recorded	<u>COURT HOUSE</u>
Monument	<u>6" DIA. 5' LONG CON. MON.</u> <small>(Original concrete post, iron rod, etc.)</small> <u>WITH BRASS CAP MKD. T145N R29W</u>
	<u>S18/S17</u>
	<u>S19/S20</u>

Evidence of Subsequent Corner Restoration Found	
Year of search	<u>8-7-73</u> By <u>CURT KRAUSE</u>
<u>FOUND CONCRETE MONUMENT - IN PLACE</u> <u>IN GOOD CONDITION - 20" ABOVE GROUND</u> <u>CORNER IS IN SW CORNER OF PINE PLANTATION</u> <u>AND APPROX. 200' SOUTH OF OLD HOMESTEAD</u> <u>SITE - IN CUT OVER AREA (THIS YEAR)</u>	

Bearing Trees, Reference Objects ¹⁹⁵⁸			
Species	<u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>
Diameter	<u>13</u>	<u>12</u>	<u>12</u>
Bearing	<u>N49W</u>	<u>S43W</u>	<u>S80E</u>
Distance	<u>45.6</u>	<u>28.4</u>	<u>42.0</u>

Bearing Trees, Reference Objects			
Species	<u>J. PINE SNAKE</u>	<u>J. PINE</u>	<u>J. PINE</u>
Diameter	<u>14</u>	<u>17"</u>	<u>18</u>
Bearing	<u>N49°W</u>	<u>S43°W</u>	<u>S80E</u>
Distance	<u>45.6</u>	<u>28.4</u>	<u>42.0</u>

SCRIBE OPEN ON ALL TREES



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

FOUND MONUMENT IN PLACE IN CUT OVER AREA
BTS OK - BUT 1 PINE TO NW IS DEAD ALSO NEEDS
SIGN POST & SIGNS
PUT FSLP ON A 37" W. PINE 320' SOUTH OF CORNER
AT NORTH EDGE OF WOODS ROAD TO SHELLEY STORE E-W
PUT TAGS ON BEARING TREES THIS DAY 8-7-73

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 1/2 HR.

4. Do you think additional search might
 recover evidence? Yes _____ No

5. Signature Curtis R. Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. N-6
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 Mer. N.F. _____ County _____ State _____
W 1/16 BET. Corner common to sections 17, 20, _____ and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed NONE

Original monument (Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument (Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 8-13-73 By M. NORNBERG

CHAINED EAST FROM SEC. COR. TO
APPROX. LOCATION OF 1300'
FSLP ON 18" J. PINE WEST SIDE OF
LYBE RD. LINE RUNS ALONG AN OLD
FENCE LINE TO J. PINE

Bearing Trees, Reference Objects


Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search. _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. N-7
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
APD 802-127

T. 145 R. 29
QUARTER

5th Mer. N.F. HIP County CASS State MISSOURI
 Corner common to sections 17, 20 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1877

Original monument Iron
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species <u>B. Pine</u>	<u>Aspen</u>
Diameter _____	_____
Bearing <u>N22°E</u>	<u>S18°W</u>
Distance <u>11</u>	<u>27</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1973 By MARK NOBENBERG


Chain on 11th Section CORNER 1300'
along 2nd line - Put six FSLP
on a 15' line on west side of
lybe road.

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Chained east from corner
CORNER 2640' found a N. Pine with
an FSLP on east side of tree. Put an FSLP
on west side of tree facing FIRE to a 20.
N. Pine has SCIPRS marks

4/30/97 REVISITED CK - SEE FIELD BOOK (SCRIBE READABLE)
FIELD BOOK 1-Pg. 56
NOW 27" N. PINE w/OLD TAG (REMOVED TODAY)

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

T. 14/5 R. 29 Mer. N.F. CHIP County L'ASS State Miss.
SECTION Corner common to sections 15 16 21 and 22

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>N. Pine</u>	<u>J. Pine</u>	<u>Tam.</u>	<u>N. Pine</u>
Diameter	<u>10"</u>	<u>10"</u>	<u>10"</u>	<u>12"</u>
Bearing	<u>N 59° W</u>	<u>S 89° E</u>	<u>S 9° E</u>	<u>N 34° E</u>
Distance	<u>34 lks.</u>	<u>47 lks.</u>	<u>56 lks.</u>	<u>34 lks.</u>
$H_c =$	<u>22.4'</u>	<u>31.0</u>	<u>37.0</u>	<u>22.4'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete, steel, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 8-24-73 By C.K.
CHAINED NORTH OF HWY #2 2640
NO EVIDENCE FOUND
PUT ESKP ON 10" J. PINE AS APPROX.
517.24'
3 LARGE N PINE ARE APPROX 150' NORTH

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

FSLP ON 16" N. PINE 880' WEST OF APPROX. COR.

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. N-21
(Alphabetical - Numerical)

BOOK # 1
PAGE # 20

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RR-7150-4 (Rev. 6/13/67)
GPO 806-924

T. 145 R. 29 Mer. N.F. Chippewa County Cass State Minnesota
5th Section Corner common to sections 13, 14, 23 and 24

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 12-1-69 By Morrison & Morgan
Tog on white post by inter-section of old
fireway and new graded road. The
post was lying on ground. He re-set it.
There used to be a pine stump BT at this
location but we were unable to locate
now.

Bearing Trees, Reference Objects



Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Peering, chaining, photos, maps, etc.

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature [Signature]

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 Mer. N.F. Chippewa County Cass State Maine
114 Corner common to sections 13 & 24 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search <u>12-3-69</u> By <u>Morrison & Morgan</u> <u>Tag on S. side of 12" J. Pine Stub</u> <u>which is an old B.T. This is an</u> <u>old tag and apparently has been</u> <u>accepted as the Corner for many</u> <u>years. Actual Corner may lay a</u> <p style="text-align: center;">Bearing Trees, Reference Objects</p> <u>few ft. S. of } B.T. Blue line</u> <u>pointed S.</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> _____ _____ _____



14
Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Peering, chaining, photos, maps, etc. _____

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes X No _____

5. Signature S. M. Morrison

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145N R. 29W Mer. N.F. Chippewa County Cass State MN
 Section 13 Corner common to sections 13, 24, 18 and 19
145-29 145-28

EXISTING SURVEYS

Original Government Survey			
Year surveyed	<u>1874</u>		
Original monument	<u>Post</u> <small>(Wood post, stone, pile of stones, pipe, etc.)</small>		
Species	<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>
Diameter	<u>12"</u>	<u>8"</u>	<u>7"</u>
Bearing	<u>N31°E</u>	<u>N19°W</u>	<u>S65°W</u>
Distance	<u>23 lks.</u>	<u>15 lks.</u>	<u>46 lks.</u>
	<u>15.18'</u>	<u>9.9'</u>	<u>7.92'</u>

Original Evidence Found			
Year of search	<u>7/11/63</u> By <u>Hedman, McDonald, Okerman</u>		
Monument found	<u>_____</u>		
Species	<u>stump</u>	<u>hole charred</u>	<u>stump hole</u>
Diameter	<u>w/charred</u>	<u>stump</u>	<u>w/charred</u>
Bearing	<u>N31°E</u>	<u>N19°W</u>	<u>S65°W</u>
Distance	<u>15.18'</u>	<u>9.9'</u>	<u>30.36'</u>
			<u>7.92'</u>


Subsequent Corner Restoration	
Year surveyed	<u>7/11/63</u> By <u>McDonald, Okerman</u>
Where filed or recorded	<u>Cass County</u>
Monument	<u>2" dia. x 5' long pipe w/brass tablet</u> <small>(Original, concrete post, iron rod, etc.)</small>
	<u>A.L.S. # 6807</u>

Evidence of Subsequent Corner Restoration Found	
Year of search	<u>7/9/80</u> By <u>Krause, McDonald, Hayes</u>
Found monument in place and good condition	<u>_____</u>
	<u>_____</u>

CERTIFICATE FILED

Bearing Trees, Reference Objects			
Species	<u>J. Pine</u>	<u>Oak</u>	<u>J. Pine</u>
Diameter	<u>15"</u>	<u>6"</u>	<u>11"</u>
Bearing	<u>N65½°W</u>	<u>N44°E</u>	<u>S53½°W</u>
Distance	<u>61.3'</u>	<u>126.5'</u>	<u>56.7'</u>
	<u>steel sign post south 4.25'</u>		

Bearing Trees, Reference Objects			
Species	<u>J. Pine</u>	<u>Oak</u>	<u>J. Pine</u>
	<u>no evid.</u>	<u>no evid.</u>	<u>still</u>
	<u>was seen</u>	<u>was seen</u>	<u>standing</u>
	<u>standing</u>		
	<u>Not measured</u>		<u>Not measured</u>



Sketch
 O Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes No

2. How was search area located?

Pacing chaining photos maps,
 etc. _____

3. Man hours spent in search 2

4. Do you think additional search might

recover evidence? Yes No

5. Signature M.C. Hayes

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. 7/9/80 Krause, McDonald, Hayes
 Found 4 large depressions of the bearing and dist. of the orig. BT's (Possible holes caused by pulling roots & stumps out)
 The area is now a Red Pine Plantation approx. 12 yrs. old, ~~so~~
 area has been heavily disturbed. Also searched for original evidence an area 650-750' S and 100' E & W of present brass cap
 No evidence found. Some of this area had been disturbed and planted about 40-50 yr's ago

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes No

Filed in county records at Cass Co. Date 9-16-63 County Document No. 166

Identified on aerial photo No. _____ Which is filed at _____

Index No. 0-25 0-25
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)


RP-7150-4 (Rev. 6/13/67) 5.0
 GPO 502-127

T. 145 N R. 29 W 29th S. 7th Mer. N.F. CHIPPENAW County MN State
N Y16 Corner common to sections 19 and

EXISTING SURVEYS

Original Government Survey				Original Evidence Found			
Year surveyed _____				Year of search _____ By _____			
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>				Monument found _____			
Bearing Trees				Original Bearing Trees Found			
Species _____	_____	_____	_____	Species _____	_____	_____	_____
Diameter _____	_____	_____	_____	Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____	Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____	Distance _____	_____	_____	_____
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Year surveyed <u>7-18-68</u> By <u>LYLE ELLIOTT</u>				Year of search <u>12-30-80</u> By <u>SC HOONOVER</u>			
Where filed or recorded _____				_____			
Monument _____ <small>(Briquet, concrete post, iron rod, etc.)</small>				<u>FOUND MONUMENT IN PLACE</u> <u>18" ABOVE GROUND. IN GOOD</u> <u>CONDITION</u>			
<u>2' dia. x 5' Long GAL. Pipe WITH</u> <u>B/C M&O</u> <u>T145 N</u>							
Bearing Trees, Reference Objects				Bearing Trees, Reference Objects			
Species <u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>	<u>R29th R29W</u>	<u>J. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>	
Diameter <u>11"</u>	<u>9"</u>	<u>9"</u>	<u>5.241</u> <u>5.19</u>	<u>13"</u>	<u>12"</u>	<u>13"</u>	
Bearing <u>N17°E</u>	<u>N84°30'W</u>	<u>S38°E</u>	<u>1968</u>	<u>N17°E</u>	<u>N84°0'W</u>	<u>S38°E</u>	
Distance <u>34.01'</u>	<u>43.45'</u>	<u>60.90'</u>	<u>ALSM 16807</u>	<u>34.01'</u>	<u>43.45'</u>	<u>60.90'</u>	
<u>CRORR POST 4" x 4" x 6.0" WITH ROD TOP ONE</u>							

NORTH 10.0' WITH SIGNS 54-2 + 54-4 ATTACHED.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

0-25

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc.

COMPASS

3. Man hours spent in search 1 HR

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature J. Johnson

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

REPAINTED ALL B.T.S. - GOOD CONDITION

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 Mer. N.F. Chippewa County Cass State Minn
 Corner common to sections 20, 21 and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874

Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Species <u>Aspin</u>	Bearing <u>E</u> Trees <u>Aspin</u>
Diameter <u>2"</u>	<u>2"</u>
Bearing <u>576E</u>	<u>537W</u>
Distance <u>14</u>	<u>16</u>

Original Evidence Found

Year of search 1966 By HIRSCHY, -MARTINSON

Monument found none

Original Bearing Trees Found

Species No Evidence Found

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____


Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Compass-Chaining

3. Man hours spent in search 1

4. Do you think additional search might

recover evidence? Yes No _____

5. Signature Jerry E. Martin

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. P-25
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 608-127

T. 145N R. 29W ~~30W~~ 5th Mer. N.F. CH. PEWA County _____ State MN
Y4 Corner common to sections 24 19 and _____

EXISTING SURVEYS

Original Government Survey				Original Evidence Found			
Year surveyed <u>1873</u>				Year of search _____ By _____			
Original monument <u>Wood Post</u> <small>(Wood post, stone, pile of stones, pipe, etc.)</small>				Monument found _____			
Bearing Trees				Original Bearing Trees Found			
Species	<u>J. Pine</u>	<u>N. Pine</u>	_____	Species	_____	_____	_____
Diameter	<u>7"</u>	<u>8"</u>	_____	Diameter	_____	_____	_____
Bearing	<u>N138°E</u>	<u>S74°W</u>	_____	Bearing	_____	_____	_____
Distance	<u>15.8'</u>	<u>48.18'</u>	_____	Distance	_____	_____	_____
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Year surveyed <u>1968</u> By <u>CURT KRAWSC</u>				Year of search <u>12-30-80</u> By <u>Schoorlander</u>			
Where filed or recorded _____				Found <u>Iron in place 12"</u>			
Monument <u>2" dia 25" long pine w. 74 ft</u> <small>(Original, concrete post, iron rod, etc.)</small>				<u>above ground, in good</u>			
<u>corner set proportionally measured</u>				<u>condition.</u>			
<u>from CADASTRAL SURVEY</u>							
Bearing Trees, Reference Objects				Bearing Trees, Reference Objects			
Species	<u>J. Pine</u>	<u>J. Pine</u>	<u>N. Pine</u>	<u>S24 S.19</u>	<u>J. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>12"</u>	<u>11"</u>	<u>9"</u>	<u>1968</u>	<u>(Spring)</u>	<u>13 (Spring)</u>	<u>14"</u>
Bearing	<u>N18°E</u>	<u>N89°W</u>	<u>S17°E</u>	<u>15 Nods</u>	<u>N8°E</u>	<u>N8°E</u>	<u>S17°E</u>
Distance	<u>45.53'</u>	<u>66.08'</u>	<u>92.87'</u>		<u>45.53'</u>	<u>60.08'</u>	<u>92.87'</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

P-25

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, mags., etc. _____

3. Man hours spent in search 1 Hr

4. Do you think additional search might recover evidence? Yes _____ No X

5. Signature Jim Johnson

Perpetuation Record

Monument and accessories established. Include brief description of area.
MFD 2 NEW BLS AND REPRINT 210 ONES

W. OAK 7" S 70° E [redacted] MFD Y4 S 19 BT
J. Pine 13" S 80° W [redacted] MFD Y4 S 24 BT

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records at _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

Index No. P-25
(Alphabetical - Numerical)


Book #1 Pg. #12

LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 145N R. 29W S. 5th Mer. N.F. Chippewa County Cass State MN

Corner common to sections _____ and _____

EXISTING SURVEYS

Original Government Survey				Original Evidence Found			
Year surveyed <u>1873</u>				Year of search _____ By _____			
Original monument <u>Wood Post</u> <small>(Wood post, stone, pile of stones, pipe, etc.)</small>				Monument found _____			
Bearing Trees				Original Bearing Trees Found			
Species	<u>J. Pine</u>	<u>N. Pine</u>	_____	Species	_____	_____	_____
Diameter	<u>7"</u>	<u>24"</u>	_____	Diameter	_____	_____	_____
Bearing	<u>N13½E</u>	<u>S74°W</u>	_____	Bearing	_____	_____	_____
Distance	<u>24 lks.</u>	<u>73 lks.</u>	_____	Distance	_____	_____	_____
	<u>15.84'</u>	<u>48.18'</u>	_____		_____	_____	_____
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Year surveyed <u>7/15/68</u> By <u>Okerman, Krause</u>				Year of search _____ By _____			
Where filed or recorded <u>U.S.F.S. Set by Propstionate Measure</u>				_____			
Monument <u>2" dia. x 5' long pipe w/brass cap.</u> <small>(Original, concrete post, iron rod, etc.)</small>				_____			
<u>RLS # 6807</u>				_____			
_____				_____			
_____				_____			
Bearing Trees, Reference Objects				Bearing Trees, Reference Objects			
Species	<u>J. Pine</u>	<u>J. Pine</u>	<u>N. Pine</u>	_____	_____	_____	_____
Diameter	<u>12"</u>	<u>11"</u>	<u>9"</u>	_____	_____	_____	_____
Bearing	<u>N8°E</u>	<u>N88°W</u>	<u>S17°E</u>	_____	_____	_____	_____
Distance	<u>45.53</u>	<u>66.08'</u>	<u>92.87'</u>	_____	_____	_____	_____



Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. 7/9/80 Krause, McDonald, Hayes
 Searched for original evidence in an area approx. 350' S. of present brass cap. Fd. old down fence at NW corner of old field. Field was in use on 1939 aerial photo. Large Pine stump at west edge, of field (appears to have been pulled from field) Need to check old Hwy. 2 plans as it is only 200' South, should also check for Plat of old Ryan Indian Village

At time of search:

1. Did you have the record description?
 Yes No _____

2. How was search area located?
 Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 2

4. Do you think additional search might recover evidence? Yes No _____

5. Signature M.C. Hayes

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Q-R-17
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 145 R. 29 5 Mer. N.F. CHIPPEWA County CASS State MN.
MEANDER BET. Corner common to sections 22 and 23

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 P.H. CONGER
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. PINE W. PINE
Diameter 36 30
Bearing N32E N45W
Distance 16 LKS. 64 LKS.
10.56' 42.24'

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument (Concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 4-6-95 By RM + CK
Ed. REMAINS OF BOTH PINE STUMPS
CORNER POST WOULD FALL AT EDGE
OF BANK - PLACED FSLP ON 19" W. PINE
N40E - 18.5' FROM CORNER - WILL HAVE
TO PUT IN WITNESS COR. POSITION

Bearing Trees, Reference Objects

Species PINE STP. PINE STP.
Diameter LARGE LARGE
Bearing N32E N45W
Distance 10.56' 42.24'

Relation of Evidence to Record Features Along Section Line


Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes No

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature Curtis R. Krause

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. R-1
(Alphabetical - Numerical)BOOK 145-30
Pg. 9LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/87)
GPO 802-127T. 145 R. 29 Mer. N.F. CHIPPEWA County CASS State MO.
SECTION Corner common to sections 19, 24, 25 and 30

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)
Bearing Trees
Species N. PINE N. PINE N. PINE N. PINE
Diameter 18 14 24 12
Bearing N25E N36W S54E S87W
Distance 9 LKS. 48 LKS. 94 LKS. 23 LKS.
5.94' 31.68' 62.04' 15.18'

Subsequent Corner Restoration

Year surveyed 1933 By GLO RESURVEY
Where filed or recorded ON FILE
Monument SET 6" X 24" CONC. CYLINDER
(Original, concrete post, iron rod, etc.)MARKED NEW BT.

Bearing Trees, Reference Objects

Species N. PINE
Diameter 5
Bearing S91/2 E
Distance 44 LKS.
29.04'

Original Evidence Found

Year of search 1933 By GLO RESURVEY
Monument found FROM REMAINS OF ORIG.
BT'S
Original Bearing Trees Found
Species N. PINE N. PINE N. PINE
Diameter 20 14 18
Bearing N25E S87W N36W
Distance 9 LKS. 23 LKS. 48 LKS.
REMARK REMARK REMARK


Evidence of Subsequent Corner Restoration Found

Year of search 10-12-94 By C.K. P.M.
FD. CONC. CYL. - IN PLACE - 1" ABOVE GRD.
IN N. PINE N4E45 - HARDWOODS SW
FD. EVIDENCE OF ORIG. BT'S
PLACE F.SLP ON 10" N. PINE N36W - 125'
OF COR. ON SOUTH SIDE OF FR 2911

Bearing Trees, Reference Objects

Species GLO
N. PINE STUB N. PINE STUB N. PINE STUB N. PINE
Diameter 20" X 25'H 24" X 30'H 19 X 60'H WINDFALL
Bearing N25E S87W N36W S9E
Distance 5.94' 15.18' 31.68' 29.04
SCRIBED SCRIBED SCRIBED SCRIBED

R 29 W



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

125' SOUTH OF FR 2911

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 1 HR.

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. 10-12-94
MARKED NEW B.T.E. P.M. PETE MOBERG D.N.R.

- N. PINE 9 N12E - 23.64' MKD S19 BT
- N. PINE 10 N54E - 34.53' " S19 BT
- N. PINE 11 S39E - 24.95' " S30 BT
- N. PINE 12 N32W - 15.20' " S24 BT
- 8' STEEL SIGN POST SOUTH 3.45'


Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

1. T 145 R 29 No. R1 Cor. Sec. Mer. 5 State MINNESOTA N. F. CHIPPEWA Dist. CASS LAKE

2. Corner Status



7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By: _____
Field Book No. _____
Where Filed _____


9. Evaluation
Authentic
Needs Verif. Monument
Re-estab. Survey _____
Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: Orig. notes of GLO Survey of 1874
N. Pine 18" N25E 9 LKS or 5.94'
N. Pine 14" N36W 78 LKS or 31.68'
N. Pine 12" S87W 23 LKS or 15.18'
N. Pine 24" S57E 94 LKS or 62.04'

5. Investigation Notes: TAKE Logging road at junction of PIPELINE & Ketchum Road (2135) west & south to end of road (follow blue line). 2 chains south of road is interior 1/16 corner (R-2) - due west 20 chains to section corner

THREE Bearing trees are present but no visible signs of corner or express +



6. Signed M. Reed Title Asst Range Date 3/21/61

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By JLD Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____
(Agency)

(Date) (City) (County) (State)

14. Remarks:

T. 145 R. 29 4 Mer. N.F. Chippewa County Cass State Minn
Corner common to sections 20 29 and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Species W Pine Bearing Trees W Pine
Diameter 40" 30"
Bearing S49E N14E
Distance 8 80

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found


Year of search 1966 By HIRSCHEY-MARTINSON
Monument found none

Original Bearing Trees Found

Species No Evidence Found
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. Compass-Chaining

3. Man hours spent in search 2

4. Do you think additional search might
 recover evidence? Yes No _____

5. Signature Jerry E. Martin

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. B-9
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

T. 145 R. 29 S. Mer. N.F. Chippewa County Cass State Minn
Corner common to sections 20, 21, 28 and 29

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Species	Bearing Trees			
	W Pine	W Pine	W Pine	W Pine
Diameter	30"	30"	20"	18"
Bearing	S49W	N48W	N62W	S67E
Distance	17	27	68	64

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search 1966 By HIRSCHEY, -MARTINSON
Monument found none

Original Bearing Trees Found


Species No Evidence Found
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

20

21



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes No

2. How was search oreo located?

Pacing, chaining, photos, maps,
etc. Compass-Chaining3. Man hours spent in search 14. Do you think additional search might
recover evidence? Yes No 5. Signature Jerry E. Martinson

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 S. 5 Mer. N.F. Chippewa County Cass State Minn
Corner common to sections 21, 28 and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species Maple Elm
Diameter 8" 6"
Bearing N10W S75E
Distance 14 21

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found


Year of search 1966 By HIRSCHEY, -MARTINSON
Monument found none

Original Bearing Trees Found

Species No Evidence Found
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Compass-Chaining

3. Man hours spent in search 1

4. Do you think additional search might
recover evidence? Yes No _____

5. Signature Sarvy E. Martinson

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

LAND CORNER RECORD

1. T. 115 R. 29 NoR-15 Cor. 1/4, Mer. 5th State Minnesota (Rectangular) N. F. Chippewa Dist. Bena

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

Remains of original scribed stake and 2 orig. B.T.
Face visible of one but only stump of other. Both flat
Cedar stake erected.

5. Investigation Notes:

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

F.S.L.P. on 6" Cedar (NE side) 3' from corner

Orig. notes:
Spruce 6" S29E 5 LKs or 3.3'
Spruce 6" N42W 16 LKs or 10.56'

Checked 4-19-61 OK ~~AKM~~
8:78 SR + 7
W. ~~1003~~

checked 9/63 could not verify
Recheck who 8/70 who

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
~~Re-estab.~~ Survey _____
Land Status _____

6. Signed R. H. Christopher Title D.F.R. Date 6-17-60

PERPETUATION RECORD

10. Monument:

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ Volume _____ Page _____

(Agency)

(Date) (City) (County) (State)

14. Remarks:

Index No. R-21
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 802-127

T. 14S R. 29 Mer. N.F. 5 CHIPPEWA County CASS State MN.
SECTION Corner common to sections 23, 24, 25 and 26

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 P. H. CONGER
 Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	J. PINE	J. PINE	J. PINE	J. PINE
Diameter	8	8	10	10
Bearing	S45W	N56E	N61E	S35W
Distance	6.60'	9.90'	19.14	25.08'

Subsequent Corner Restoration

Year surveyed 2-24-31 By O. R. BOEWER
 Where filed or recorded _____
 Monument FD. SCRIBED POST POOR CONDITION
(Original concrete post, iron rod, etc.)
FD. J. PINE WIND FELL
DUT FSLP ON 14" N. PINE ON N SIDE
CORNER. BRS. N10E 78'

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search 1914 By J. A. DONEY
 Monument found FD. J. PINE STAKE
FD. FALLEN J. PINE (BT) IN SEC. 26

Original Bearing Trees Found

Species 594' SOUTH OF R.R. TRACKS
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found


Year of search 12-17-75 By C. KRAUSE L. SOBIECK
CHAINED EAST FROM OLD TAG (RUSTED)
ON EAST SIDE OF WOODS TRAIL N1S
490'E TO SEC. COR. (APPROX.) FD. 22" N. PINE
S10°W - 78' WITH OLD TAG DATED - 2-24-31
ALSO TAG ON 8" R. OAK - S60E - 19.5'

Bearing Trees, Reference Objects OVER

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____



Sketch

○ Corner ◻ F.S. Land

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 2 HRS.

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature Curt R. Kramer

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

TAG ON R. OAK DATED 5-29-62 JPR + JFL
 FD. SQUAD STAKE WITH FINISHING NAIL IN TOP
 FROM 1931 POSITION - SQD STAKE IS S33E 70'
 BRUSHED LINE RUNS N10E FROM SQD STAKE
 AND RIBBON LINES RUN E + W FROM STAKE
 WE PLACED FSLP ON 14" J. PINE 510 W 75' FROM APPROX.
 SEC. COR. AS ESTABLISH FROM 1931 TAG

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

NO EVIDENCE OF OLD POST OR WINDFALL J. PINE BT
 APPROX. COR. IN J. PINE - N. PINE + W. PINE PLANTATION
 SMALL OPENING TO SE

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. S-21
(Alphabetical - Numerical)

~~BOOK #~~
~~PAGE #~~
~~5TH~~

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7 150-4 (Rev. 6/13/67)
GPO 502-127

T. 145 N. 29 W
N 1/4

Mer. N.F. Chipp

County CASS

State MO

Corner common to sections 2526

and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

check in field

Original Evidence Found

Year of search 1973

By African?

Monument found 2' galv. pipe w/ brass cap

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____

By _____

Where filed or recorded _____

Monument _____

(Brick, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1978

By Bob Bixant

Pipe with Brass cap dated 1973

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

R. Pine

P. Birch

9 inch


8 inch

S 39° W

S 41° E

.325 ch

.59 ch



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps,

etc. compass

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

2" galvanized pipe w/ brass cap between power line on NE and Road on W.

3. Mon hours spent in search zero

4. Do you think additional search might recover evidence? Yes _____ No

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records at _____ Date _____ County Document No. _____

5. Signature _____

Identified on aerial photo No. None Which is filed at _____

T. 145 N R. 29W ~~30W~~ 5 Mer. N.F. Chippewa County Cass State Minnesota
South 1/16 Corner common to sections 25, 30, and

EXISTING SURVEYS	
Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1933</u> By <u>G.L.O.</u>	Year of search <u>1962</u> By <u>R. H. McDonald</u>
Where filed or recorded <u>St. Paul, Minnesota</u>	<u>Found the iron pipe with brass cap as</u>
Monument <u>iron post with brass cap</u> <small>(Original, concrete post, iron rod, etc.)</small>	<u>described in G.L.O. notes. Post is</u>
	<u>tipped will be reset in summer.</u>
Bearing Trees, Reference Objects	
Species <u>Cedar</u> <u>Cedar</u>	<u>Cedar</u> <u>Cedar</u>
Diameter <u>10"</u> <u>8"</u>	<u>Stub</u> <u>10"</u>
Bearing <u>S18 1/2 E</u> <u>S58-3/4 W</u>	<u>S19E</u> <u>S59W</u>
Distance <u>23.10'</u> <u>30.36'</u>	<u>23.1'</u> <u>30.36'</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Corner is in the southeast edge of a cedar swamp

At time of search:

1. Did you have the record description?

Yes X No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. chaining

3. Man hours spent in search _____

2

4. Do you think additional search might recover evidence? Yes _____ No ✓

5. Signature R. H. McDonald

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Scribed two new bearing trees

Cedar 10" Sh2°W 32.8' mkd S. 25 BT

Elm 6" N53½°E 5.1' mkd S 1/16 S 30 BT

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. U-2
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN.
SOUTHWEST 1/16 APPROX. Corner common to sections _____ and 30

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1-6-76 By C. KRAUSE D. PARKER
FROM APPROX. W 1/16 BET. 30-31 RAN LINE
DUE NORTH 1320'N - THEN 60 TO S 1/16 BET.
25-30 IRON PIPE W/ CAP AND RUN N 89 E
1280' E AND INTERSECT LINES AT 20" N. PINE
TAG ON SOUTH SIDE AS APPROX. SW 1/16 COR.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

FD. OLD FSLP ON 9" ELM ON SOUTH SIDE OF WOOD TRAIL
E+W TO KETCHUM ROAD - STATES 390' SOUTH TO W'1/4


Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____



Sketch

○ Corner ▣ F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Index No. V-1
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 14S R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN.
SECTION Corner common to sections 25 , 30 , 31 and 36

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1933 By GLO RESURVEY
Where filed or recorded _____
Monument CONCRETE CYLINDER 1/2 CAP
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found


Year of search 12-31-75 By C. KRAUSE
FD. CONCRETE CYL IN PLACE - IN GOOD
CONDITION - 2" ABOVE GROUND - IN HARDWOODS
CEDAR SWP. 150' W OF COR. - FD. FSLP ON
N SIDE OF 12" BASSWOOD - 4' SW OF COR.
BT'S LIVING VERY LITTLE CHANGE IN SIZE

Bearing Trees, Reference Objects

NEEDS SIGN POST

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. 12/31/75

C. KRAUSE D. PARKER
SET 4" X 4" X 8' CEDAR POST ALONGSIDE
CONCRETE MONU.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145N R. 29-30W Mer. N.F. 5 Chippewa County Cass State Minnesota
 Section Corner common to sections 25, 36, 30 and 31

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1933 By G. L. O.
 Where filed or recorded St. Paul, Minnesota
 Monument 2' x 6" diameter concrete monument
(Original: concrete post, iron rod, etc.)
with brass cap

Bearing Trees, Reference Objects

Species	Y. Birch	W. Birch	Elm	Elm
Diameter			10"	10"
Bearing			S29 $\frac{1}{2}$ W	N25W
Distance			36.96'	9.90'

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found


Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1962 By R. H. McDonald
Found the brass capped concrete monument
as described in G. L. O. notes.

Elm Elm

	Elm	Elm
Diameter	12"	stump
Bearing	S30W	N25W
Distance	36.96'	9.9'



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Logging road bearing N-W, S-E crosses section line approx. 400 ft. north of corner.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. photo

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature R. H. McDonald

Perpetuation Record

Monument and accessories established. Include brief description of area.

Marked 3 new bearing trees:-

Cedar 15" N81°W 60.9' mkd S 25 BT

Maple 5" N30°E 6.3' X BT

Maple 9" S65°E 45.5' S 31 BT

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. V-2
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RG-7150-4 (Rev. 6/13/67)
 GPO 802-127

T. 14S R. 29 Mer. N.F. CHIPPEWA County CASS State MN.
WEST 1/4 APPROX. Corner common to sections _____ and 31

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p>
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	Year of search <u>12-31-75</u> By <u>C. KRAUSE & D. PARKER</u> <u>FROM IRON PIPE AT 1/4 BET. 30-31 RAN LINE</u> <u>AT S89°W - 2608' TO SEC. COR. 25-30-31-36</u> <u>MISSED COR. 5' SOUTH - LINE OK - GO BACK</u> <u>TO STATION 1320' W AND EST. APPROX. W 1/4</u> <u>PUT FSLP ON 9" W. OAK ON SOUTH SIDE AS</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects <u>OVER</u></p>

Index No. V-15
(Alphabetical - Numerical)

BOOK 1
Pg. 47

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 S. 5 Mer. N.F. CHIPPAWA County CASS State MN.
QUARTER BET. Corner common to sections 27 and 34

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 By P. H. CONGER
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. OAK W. OAK
Diameter 10 10
Bearing S42E N17W
Distance 50 Lks. 67 Lks.
33.0' 44.22'

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 5-4-95 By RM-CK
FROM GPS CORRECTED LOCATION
WE SEARCHED IN AREA - NOTHING
COULD BE FOUND - HAVE OLD DOWN
OAK LOG LYING ON GROUND - STILL
FROZEN AT THIS TIME - WILL COME

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____



Sketch

○ Corner ▣ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

80 CHS. E + W INTERSECTION OF FR 2341D NORTH IN SEC 27.
750' NE CORNER OF 2341 - THEN 100' E TO APPROX SEARCH AREA
SCALED OFF QUAD. 3-23-95

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. V-17
(Alphabetical - Numerical)BOOK 1
Pg. 48LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 145 R. 29 S. 5 Mer. N.F. CHIPPEWA County CASS State MN.
SECTION Corner common to sections 26, 27, 34 and 35

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>W. PINE</u>	<u>N. PINE</u>	<u>W. OAK</u>	<u>W. PINE</u>
Diameter	<u>24</u>	<u>24</u>	<u>14</u>	<u>30</u>
Bearing	<u>N10E</u>	<u>S23E</u>	<u>S89W</u>	<u>S2W</u>
Distance	<u>15 LKS.</u> <u>9.90'</u>	<u>10 LKS.</u> <u>6.60'</u>	<u>17 LKS.</u> <u>11.22'</u>	<u>6 LKS.</u> <u>3.96'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 3-23-95 By C. KRAUSE
USED TIES FROM R.R. PLAN TO GET TO
SEARCH AREA - FROM CONCRETE CULVERT
UNDER GRADE - RAN S48E - 18.34' THEN
RAN S2W - 770' TO SEARCH AREA - NOW
N. PINE PLANTATION WITH WIND ROWSBearing Trees, Reference Objects OVERSpecies _____
Diameter _____
Bearing _____
Distance _____

FR 2341



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. 3-23-95

EVERY THING HAS BEEN SHEARED + PILED YEARS AGO
NOW WHOLE AREA IS 6" TO 10" N. PINE IN ROWS
FD. EVIDENCE OF SOME OLD BURNED PINE STUMPS IN
PILES - NO TRACE OF ANYTHING VERY OLD IN AREA
CORNER + EVIDENCE HAS BEEN DESTROYED
PLACED TAG ON NORTH SIDE 7"-4 BLAZED N. PINE
ON SOUTH EDGE OF WINDROW - APPROX. COR. IS 24'-AT

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

NZE FROM TAG ON BLAZED 7" N. PINE
GPS THIS COR. 3/30/95 RM

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search 1 HR.

4. Do you think additional search might

recover evidence? Yes _____ No _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

5. Signature Curt Krause

Index No. V-H, 45
(Alphabetical - Numerical)

145-30

BOOK #1
PAGE #4

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

89-5890-11 (5/12/81)

T. 145 N R. 29W, 30W 5th Mer. N.F. Chippewa County Cass State Minnesota
Witness Meander Corner common to sections 31, 36, and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1933 By G.L.O.
Where filed or recorded St. Paul, Minnesota
Monument Iron post with brass cap
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species Cedar Balm of Gilead
Diameter 5"
Bearing N58-3/4E
Distance 75.24'

Original Evidence Found

Year of search _____ By _____
Monument found _____


Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1962 By R. H. McDonald
Found iron post with brass cap - stamp on cap does not include W.C. as called for.

Cedar
7"
N59E
76.24'



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections -----
 Object -----
 Record distance -----
 Measured distance -----

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Corner is on edge of woods on the Northeast shore of Lower Sucker Lake.

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. photo

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes _____ No ✓

5. Signature R. H. McDonald

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Scribed two new bearing trees

Cedar

Ash

7"

8"

N34¹⁰E

N63°E

76.0'

35.4'

MKD S 31 BT

S 31 BT

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. W-2
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 S Mer. N.F. CHIPPEWA County CASS State MN.
NORTH WEST 1/16 APPROX. Corner common to sections _____ and 31

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1-20-76 By C. KRAUSE + D. PARKER
FROM APPROX. CN 1/16 SEC. 31 - RAN LINE AT
S 89° W - 1300' W TO APPROX. NW 1/16 SEC. 31
PLACED FSLP ON 13" ASPEN ON SOUTH SIDE
OF TREE FACING WOOD ROAD - APPROX. COR.
IS 20' NORTH OF TAG TIES ON BACK

Bearing Trees, Reference Objects OVER

Species _____
Diameter _____
Bearing _____
Distance _____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

TIES OF LINE FROM CN 1/16 TO NW 1/16

125' W ENT. LOWLAND N & S

250' W ENT. TAM SWP + BRUSH

500' W LV. TAM - ENT BLK. SPRUCE + THICK BRUSH

835' W ENT. ASPEN RIDGE NE - SW

1320' W INTERSECT OLD BLUE LINE N & S ALSO OLD BLAZED LINE ^{N & S}

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

N & S - APPROX. 40' NORTH OF WOODS TRAIL NE - SW

OPEN GRASS MEADOW 100' SOUTH OF APPROX. NW 1/16 COR.

RAN LINE NORTH FROM APPROX. NW 1/16 COR.

100' N ENT. SPRUCE SWP. - 420' N LV. SWP - ENT ASPEN + N. PINE

1050' N ENT. ASH - CEDAR LOWLAND NW - SE - 1275' N LV. SWP

1310' N AT W 1/16 COR. TAG ON 9" W. OAK AS APPROX. W 1/16

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. W-3
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 14S R. 29 Mer. N.F. CHIPPEWA County CASS State MN.
CENTER NORTH 1/16 Corner common to sections _____ and 31

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p>
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	Year of search <u>1-19-76</u> By <u>C. KRAUSE - D. PARKER</u> <u>FROM IRON PIPE AT 1/4 BET. 30-31 - RAN LINE</u> <u>SOUTH 1320'S TO CN 1/16 SEC. 31 - PLACED</u> <u>E SLP ON 20" N. PINE ON WEST SIDE APPROX.</u> <u>CN 1/16 IS 14' WEST OF TAG - N. PINE IS BLAZED</u> <u>E+W AND HAS SCAR FROM OLD TAG ON W SIDE</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects <u>OVER</u></p>



Sketch

○ Corner ▣ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

TAG HAS EITHER FALLEN OFF OR IS GROWN INTO PINE
 FOUND ~~AN~~ OLD BLAZED LINE RUNNING WEST INTO SWP.
 TIES ALONG LINE SOUTH FROM 1/4 COR.
 400'S ENT. LOWLAND SWP. NW-SE
 1200'S LV, SWP NE-SW
 1320'S APPROX. CN 1/16

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Mon hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____


Identified on aerial photo No. _____ Which is filed at _____

5. Signature Curt Krause

T. 145 R. 29 5^d Mer. N.F. Chippewa County Que State Wisconsin
 Corner common to sections 35 and

EXISTING SURVEYS	
Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>11-8-65</u> By <u>S. Morrison</u>
Where filed or recorded _____	<u>Tag on S. side of 22" Red Pine which</u>
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<u>is a B.T. - This tag is visible from</u>
_____	<u>R.R. Tracks and is on N. side of</u>
_____	<u>Tracks. Blue line painted W</u>
_____	<u>from corner. Tag was put up in</u>
_____	<u>1961 by Ross Tucker.</u>
_____	<u>Old ECC notes indicate they</u>
_____	<u>thought the corner should be 39' (lks.</u>
_____	<u>W. of B.T. - I believe it should be S.</u>
_____	<u>of B.T. as the scribing from S. - Recorment</u>
_____	<u>further check be made by S.O. survey crew</u>
Bearing Trees, Reference Objects	
Species <u>Red Pine</u>	
Diameter <u>32"</u>	
Bearing _____	
Distance _____	

copy for S.O.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes No _____

5. Signature *J. Morrison*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-3
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)


RR-7150-4 (Rev. 6/13/67)
GPD 802-127

T. 14S R. 29 Mer. N.F. CHIPPEWA County CASS State MN.
CENTER QUARTER Corner common to sections _____ and 31

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p>
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	Year of search <u>1-19-76</u> By <u>C. KRAUSE & D. PARKER</u> <u>CONTINUE SOUTH FROM CN 1/16 (APPROX.) 1300'S</u> <u>FL. 2" X 48" HIGH TAM STAKE (SOLID) AND FSLP</u> <u>DATED 10-13-54 NO NAMES COULD BE READ - RUSTED</u> <u>PLACED NEW TAG ON 8" TAM AS APPROX. C 1/4</u> <u>OLD TAG FROM 54 ON SAME TREE - TIES ON BACK</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> _____ _____ _____ _____

LOWER
SUCKER
LAKE



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature Curt Krause

TIES SOUTH FROM APPROX. CN 1/4
2100'S ENT. LOWLAND SWP. NW-SE
2300'S ENT. MOSTLY TAM. SWP.
2620'S INTERSECT 2" SQD. 48" HIGH TAM. STAKE (FAIRLY SOUND)
AND FSLP ON 8" TAM. N60W 8.0' FROM STAKE

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CORNER IN TAM + BRUSH SWP.
PAINTED LINE SOUTH FROM 1/16 COR. TO SWP. (800')
J. PINE + N. PINE TO EAST OF OUR LINE (F.S.)
RAN EAST TO KETCHUM ROAD NW-SE (TTS) PAINTED BLUE
NOTHING TO PUT TAG ON - BUT BRUSH + ALL CUT OVER AT ROAD
STATE HAS BLUE RIBBON LINE RUNNING SOUTH FROM C 1/4
ALSO BLUE RIBBON RUNNING EAST ALONG OUR LINE TO ROAD

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-14
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 145 R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN
CENTER WEST 1/16 Corner common to sections _____ and 34

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1/3/90</u> By <u>GB CK</u>
Where filed or recorded _____	<u>RAN LINE AT DUE WEST + CHAINED 1320'</u>
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<u>TO 4" ASH - PLACE E.S.L.P. ON 4" ASH</u>
_____	<u>AS APPROX. CW 1/16 SEC. 34</u>
_____	<u>OLD BLUE PAINT ON LARGE BIRCH STUB</u>
_____	<u>100' NORTH OF OUR POSITION - NO OTHER TAG</u>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

*RAN LINE FROM APPROX C 1/4 SEC. 34
 NO BLAZES OR PAINT SEEN ALONG LINE
 CASS LAKE DISTRICT NEEDS LOCATION OF CW 1/16
 TO LAY OUT TIMBER SALE TO WEST + NW*

At time of search:

1. Did you have the record description?
 Yes _____ No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-15

(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 802-127

T. 14S R. 29 Mer. N.F. CHIPPEWA County CASS State MIN.
CENTER 1/4 Corner common to sections _____ and 34

EXISTING SURVEYS

Original Government Survey

Year surveyed NONE
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By E.M. HANDY
Where filed or recorded 874
Monument FD. WOOD POST - ROTTED OFF
2" x 3" SCRIBED C'1/4 S34
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species CEDAR
Diameter 10
Bearing N12E
Distance 42 WS.
27.7'

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 12/22/75 By CURT KRAUSE - O.F.
NO POST FOUND - 6" SNOW COVER AND FROZEN
GROUND - IN ASH + CEDAR SWAMP
OLD BLAZED LINE ON CEDAR TREES - SOUTH OF
CORNER - OLD RUSTED FSLP ON CEDAR BT
FACING NE OVER

Bearing Trees, Reference Objects

FD. CEDAR SNAG NO OTHER
11 INFO
S72W
618'
MRD. C'1/4 S VISABLE



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

SET 3" X 5' CEDAR POST FOR APPROX. C 1/4 COR.
 NO POST FOUND - SNOW COVER + FROZEN GROUND
 TAKE BEARING FROM PRIBE (NE) TO LINE OF BLAZES
 ON CEDAR TO SOUTH - 618' FROM CEDAR BT - SCRIBE FACES NE
 NO OTHER EVIDENCE WAS VISIBLE AT THIS TIME
 SPRUCE + PINE PLANTATION 300' TO SE
 CORNER IN ASH + CEDAR SWALE - ICE UNDER SNOW

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 2 HRS.

4. Do you think additional search might
 recover evidence? Yes No _____

5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

DON'T KNOW WHO MARKED CEDAR OR SET POST
 1/3/70 GB-CK
 EST. 3" CEDAR POST LEANING IN ASH SWALE
 CEDAR BT IS NOW WINDFALL - LYING EAST ALONGSIDE POST
 SCRIBE IS ON UNDER SNOW
 PUT ESLP ON ASH 11 FEET 16.8' FROM 3" CEDAR POST
 ASH IS BLAZED + PAINTED RED - ALSO 15" ASH TO NORTH
 LIVING LARGE CEDAR JUST TO SOUTH OF CORNER

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 5th Mer. N.F. Chippewa County Cass State Minnesota
C 114 Corner common to sections 34 and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ <u>H</u> _____ Bearing _____ <u>H</u> _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search <u>8-3-66</u> By <u>Morrison</u> <u>Tag on N. E. side 911° dead Cedar</u> <u>which old CCC notes say is a B.T.</u> <u>squared stake nearly rotted off.</u> <u>Stands at base of tree. Old CCC notes</u> <u>say the corner lies N 12° E 42 ch.</u> <u>It would be well to re-establish</u> <u>this corner if possible as we are</u> <u>in danger of losing it.</u> <u>I could not tell for sure if the</u> <u>Cedar is a B.T.</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">S.O. Copy</p>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

~~Racing~~, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 1

4. Do you think additional search might
 recover evidence? Yes No _____

5. Signature A. Morrison

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-17
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/15/67)
GPO 802-127

T. 145 R. 29 Mer. N.F. 5 CHIPPEWA County CASS State MN.
QUARTER BET. Corner common to sections 34 and 35

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 P. H. CONGER
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. PINE NO
Diameter 16 OTHER
Bearing S67E
Distance 65 LKS.
42.90'

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search 1-3-90 By CK+GB
CHAINED NORTH FROM STD. SEC. COR. - 2640'
FOUND 2 OLD TAGS ON 16" ASPEN ON S
SIDE AS APPROX. 1/4 COR. - ALSO 13" W. PINE
5' W OF 16" ASPEN - 13" W. PINE HAS BEEN
BLAZED ON 4 SIDES AS APPROX. COR.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects OVER

FR 2341



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

CHAINED NORTH FROM STA. SEC. COR. AT 1200' N HIT W. EDGE OF FR 2341 - THEN DOWN ROAD $\frac{1}{2}$ TO STA. 2640' N

1 OLD TAG HAS DATES AS FOLLOWS 3/17/25 - 3/19/41
 ↓ 4/28/54

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. 3/23/95
 Fd. 19" ASPEN WITH SOLID RUSTED TAG (TOP TAG) PAINTED
 RED TODAY AS TAG WAS SOLID RUST OTHER TAG HAS
 DATES AS ABOVE - 15" W. PINE 5' WEST - 4 BLAZED
 IS STILL ALIVE - NOT SURE IF CORNER SHOULD BE
 IN ROAD OR AT THIS TAGGED POSITION - R. MAIN
 G.P.S. THESE TAGS ON 3/30/95 - G.P.S. DISTANCE
 WAS 2641.8' AT BEARING OF N 0°N - 34°W

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-17
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 14S R. 29 S. 5 Mer. N.F. CHIPPEWA County CASS State MN.
QUARTER BET. Corner common to sections 34 and 35

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W. PINE
Diameter 16
Bearing S67E
Distance 65 LKS.
42.9'

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found


Year of search 12-19-75 By CURT KRAUSE
CHAINED NORTH TRUE BET. SEC'S. 34-35
2640' N TO APPROX. 1/4 COR. - FD. 2 OLD
FSLP'S ON SOUTH SIDE OF 12" ASPEN
AND A 10" W. PINE BLAZED ON (4) SIDES
5' WEST OF 12" ASPEN - BLAZED W. PINE

Bearing Trees, Reference Objects

_____ OVER

Relation of Evidence to Record Features Along Section Lines

34



35

Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

IS 60' EAST OF ROAD CENTER LINE
NO EVIDENCE OF ORIG. W. PINE COULD BE FOUND AT
THIS TIME - AREA ON EAST SIDE OF ROAD HAS BEEN
LOGGED RECENTLY - APPROX. CORNER IS IN PINE
+ ASPEN WITH BRUSH AND WINDFALLS

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search 2 HRS.

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-18
(Alphabetical - Numerical)


LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)
 GPO 802-127

T. 14S R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN.
CENTER WEST 1/16 APPROX Corner common to sections _____ and 35

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p> Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p> Year of search <u>12-19-75</u> By <u>C.K.</u> <u>RAN LINE TRUE EAST FROM (4) BLAZED W. PINE</u> <u>D.S APPROX. 1/4 COR. - CHAINED 1320' E TO APPROX.</u> <u>CW 1/16 SEC. 35 - PLACE FSLP ON 8" BALSAM ON W</u> <u>SIDE - APPROX. COR IS 2' W OF TAG - BLAZED</u> <u>ON 4 SIDES</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> _____ _____ _____ _____



Sketch

○ Corner ▣ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

400'E LV. PINE - ENT. ASPEN, BIRCH + ASH

500'E MOSTLY ASH

660'E ENT. LOWLAND NW-SE

880'E ENT. ASH - TAM. BRUSH

1250'E LV. LOWLAND ENT. GALSAM BIRCH ASPEN

1290'E Fd. OLD FSLP 15'S OF THIS STATION

1320'E APPROX. CW '116

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. X-19
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
GPO 802-127

T. 145 R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN.
CENTER QUARTER Corner common to sections _____ and 35

EXISTING SURVEYS

Original Government Survey
Year surveyed _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>
Bearing Trees
Species _____
Diameter _____
Bearing _____
Distance _____


Original Evidence Found
Year of search _____ By _____
Monument found _____
Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Where filed or recorded _____
Monument _____ <small>(Original, concrete post, man rod, etc.)</small>

Evidence of Subsequent Corner Restoration Found
Year of search <u>12-19-75</u> By <u>C.R.K.</u>
<u>CONTINUE LINE TRUE EAST FROM CW 116 TO</u>
<u>APPROX. C 1/4 SEC. 35 - 2640'E</u>
<u>PLACED FSLP ON WEST SIDE OF 8" ELM</u>
<u>APPROX. COR. IS 7' WEST OF TAG</u>

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

1930'E ENT. CEDAR, LV. SPRUCE - BALSAM + BIRCH NW-SE
 2480'E SMALL CREEK 2' WIDE FLOW N - LV. CEDAR, ENT. ASH
 2625'E OLD FSLP ON 10" ASH 60' SOUTH OF THIS STATION
 2640'E APPROX. C'LY SEC. 35

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krane

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

SOUTH FROM C'LY (APPROX)
 570'S CENTER OF WOODS ROAD ETLW
 Fd. 15" ASH WITH FSLP ON N SIDE STATES 12.36 CHS.
 SOUTH TO: '14 COR.
 TAG WAS 32' WEST OF MY LINE SOUTH

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Y-3
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)
GPO 802-127

T. 14S R. 29 Mer. N.F. 5 CHIPPEWA County CASS State MN.
CENTER SOUTH 1/16 APPROX. Corner common to sections _____ and 31

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____


Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1-5-76 By C. KRAUSE + D. PARKER
RAN LINE NORTH FROM GLO CONCRETE MON.
AT S 1/4 SEC. 31 - Fd. FSLP ON 13" TAM.
THEN FENCE LINE RUNNING WEST TO LAKE
THIS LINE PAINTED BLUE TODAY - 1360'N
OF S 1/4 - NO NEW TAG TIES ON BACK

Bearing Trees, Reference Objects



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object DEG DARWIN GAMACHE
 Record distance JFL JOE ~~LAUSCHE~~ LAUSCHE
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

TIES OF LINE NORTH FROM S¹/₄

30' N CROSS FENCE BRG. NE-SW - 575' N FENCE LINE BRG. NE-SW

610' N OVERHEAD POWERLINE NE-SW - 737' N KETCHUM ROAD

975' N ENT. CEDAR + BALSAM SWP. NE-SW - 1320' N ENT. TAM SWP

1360' N INTERSECT OLD BLAZED LINE E+W IN TAM. SWP.

FD. FSLP ON 13" TAM ON W SIDE DATED 1954 DEG + JFL

TAG IS 40' WEST OF OUR LINE - OLD FENCE LINE RUNS

Perpetuation Record

Monument and accessories established. Include brief description of area.

WEST FROM 13" TAM TO LOWER SUCKER LAKE

THIS LINE WAS PAINTED BLUE (TODAY)

FRANK OAKES OWNS LAND SOUTH OF FENCE LINE

PRIVATE LAND HAS BEEN LOGGED VERY RECENTLY

UP TO CEDAR + BALSAM SWP. - ABOUT 1000' W OF CS¹/₁₆

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Certified corner restoration certificate prepared: Yes _____ No _____


Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 145 R. 29 5^a Mer. N.F. Chippewa County Cass State Maine
116 Corner common to sections SE 114 36 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small> <i>Dead J. Pine</i> Bearing Trees, Reference Objects Species <u>J. Pine</u> Diameter <u>12"</u> Bearing _____ Distance _____	Year of search <u>7-20-67</u> By <u>Morrison & Smith</u> <u>B.T. is a 12" dead J. Pine - Corner</u> <u>Tag is on W. side of it. Blue line</u> <u>Painted N. If it is possible to</u> <u>establish this corner it should</u> <u>be done as we will lose this</u> <u>B.T. soon. Blue line painted N.</u> S.O. copy



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes No _____

5. Signature *[Signature]*

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. Z-11
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/15/67)
 GPO 802-127

T. 145 R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN.
SOUTH QUARTER Corner common to sections _____ and 33

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 P. H. CONGER
 Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>
Diameter	<u>40</u>	<u>40</u>
Bearing	<u>N63E</u>	<u>N23W</u>
Distance	<u>46 Lks.</u>	<u>50 Lks.</u>
	<u>30.36'</u>	<u>33.00'</u>

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

G.R.S. 5/3/95 RM+CK

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

G.P.S.

3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

LAND CORNER RECORD

5680-2
7

1. T. 115 R. 29 No. 2-16 Cor. 1/16 Mer. 5th State Minnesota N. F. Chippewa Dist. Bena

2. Corner Status



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

5. Investigation Notes:

No brass cap in evidence

6. Signed L. M. Harrison Title Forestry Technician Date 10-16-61

PERPETUATION RECORD

10. Monument:

11. Accessories Metal tag on E. side of 5" aspen - Blue line painted E. & W of corner.
 B. T. 12" aspen stamp badly rotted - lies 4 ft. N. of tag.

		Field Book _____	Page _____
12. Set By _____	Title _____	13. Recorded By _____	Volume _____
License _____	Agency _____	(Agency)	Page _____
Date _____		(Date) _____	(City) _____
		(County) _____	(State) _____

14. Remarks: This corner should be re-established if possible, as the B. T. will disappear in a short time.

Index No. Z-21
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
 GPO 802-127

T. 145 R. 29 S. Mer. N.F. CHIPPEWA County CASS State MN.
STA SECTION Corner common to sections 35 and 36

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed. 1926 By GLO RESURVEY
 Where filed or recorded ON FILE
 Monument 2" x 36" IRON POST WITH BRASS CAP MKD.
(Original, concrete post, iron rod, etc.)
T145N S CR24W
S35 S36

1926

Bearing Trees, Reference Objects

Species N. PINE _____ N. PINE _____
 Diameter 14 _____ 12 _____
 Bearing N42W _____ N75W _____
 Distance 56.76' _____ 21.78 _____


Evidence of Subsequent Corner Restoration Found

Year of search 7-6-67 By JHE
FOUND MONU. IN PLACE.
MKD. NEW BT N. PINE 19 N25W 60.2'
6' STEEL SIGN POST 7.7' WEST BOTH SIGNS.

NEW INFO (87) CK

Bearing Trees, Reference Objects

N. PINE = 6LO _____ N. PINE = 6LO _____
18 _____ 21 _____
N42W _____ N75W _____
56.76' _____ 21.78 _____



Sketch

Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search 1/2

4. Do you think additional search might recover evidence? Yes _____ No

5. Signature Curtis E. Kravos

Perpetuation Record

CK M'Harran

Monument and accessories established. Include brief description of area. 8/10/87

FD. GLORIANA. IN PLACE 10" ABOVE GROUND - IN HEAVY BRUSH

WITH PINE, OAK + ASPEN - 125' SOUTH OF SOUTH EDGE OF PIPELINE

CLEARING - BT. Rd. N. PINE 24 N75W 21.78 - N. PINE 21

N25W 60.20' - N. PINE 19 N42E 56.76'

8' STEEL SIGN POST EAST 5.5' BOTH SIGNS - 8' STEEL SIGN POST

WEST 4.2' BOTH SIGNS - FSLP ON 15" N. PINE ON SOUTH SIDE

OF PIPELINE CLEARING FROM TAG S12W 89.0' TO STA. SEC. COR.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 2-25
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-7150-4 (Rev. 6/13/67)
 GPO 502-127

T. 14S R. 29 Mer. N.F. 5 CHIPPEWA County CASS. State MN.
STD. SECTION Corner common to sections 31 and 36

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1968 By WHO
 Where filed or recorded ON FILE
 Monument 6" X 5' LONG CONCRETE CYLINDER
(Original, concrete post, iron rod, etc.)

R29W T145N
S36 R29W
S31

S1
1968

Bearing Trees, Reference Objects


Species	R. PINE	R. PINE	R. PINE	J. PINE
Diameter	<u>8</u>	<u>5</u>	<u>7</u>	<u>8</u>
Bearing	<u>N39E</u>	<u>N6E</u>	<u>N18W</u>	<u>N58W</u>
Distance	<u>37.0</u>	<u>42.37</u>	<u>41.34</u>	<u>23.36'</u>

Evidence of Subsequent Corner Restoration Found

Year of search 8/14/87 By CK MARRISON
FD. 6" CONC. MON. 20" ABOVE GROUND IN HEAVY
BRUSH - IN PLACE - IN GOOD CONDITION
PUT FSLP ON 17" J. PINE ON SOUTH EDGE OF 500
LINE ABANDOND R.R. GRADE. FROM TAG S17W-80'
TO CORNER LOCATION

BT'S. FOUND	Bearing Trees, Reference Objects	NEW
<u>N. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>
<u>15</u>	<u>9</u>	<u>17</u>
<u>N39E</u>	<u>N6E</u>	<u>N18W</u>
<u>37.0'</u>	<u>42.37</u>	<u>41.34</u>
		<u>54.50'</u>

MKD. S36 BT



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record-Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature _____

1968 J. PINE IS NOW 10" X 12' HIGH JACK PINE SNAG WITH SCORCH
8' STEEL SIGN POST DUE WEST 9.0' WITH SIGN 54-9

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____