

LEGEND

○ = Corner having information on form 7100-52 in this file.

T146N R27W 5th PM


FILING INSTRUCTION

(Ref. FSM 7150)

File 7100-52 card record by letter and number coordinates behind the file guide for the township in which it falls.

File the 7100-52 card record by letter and then by number i.e., all A cards first, then B cards etc.

The first card behind the file guide (if data have been obtained and recorded) will be card A-1 for N.W. Township Corner, then card A-2 for 1/16 corner then card A-3 for 1/4 corner etc.



Index No. C-21
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RP-7 150-4 (Rev. 6/13/67)
 GPO 802-127

T. 146 R. 27 S. Mer. N.F. CHIPPEWA County ITASCA State MINN.
QUARTER BET. Corner common to sections _____, _____, _____ and 2

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874 By P.H. CONGER
 Original monument WOOD POST
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>J. PINE</u>	<u>J. PINE</u>
Diameter	<u>8</u>	<u>10</u>
Bearing	<u>N59W</u>	<u>S47E</u>
Distance	<u>12 LKS.</u> <u>7.92'</u>	<u>20 LKS.</u> <u>13.20'</u>

Subsequent Corner Restoration

Year surveyed 1958 By ITASCA COUNTY
 Where filed or recorded COURTHOUSE & ON FILE AT S
 Monument SET 2" X 5' IRON PIPE W/ CAP MKD.
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>
Diameter	<u>14</u>	<u>6</u>	<u>6</u>
Bearing	<u>N30E</u>	<u>S74E</u>	<u>S25W</u>
Distance	<u>18.43'</u>	<u>5.20'</u>	<u>29.00'</u>

Original Evidence Found

Year of search 1900 By CORPS OF ENG.
 Monument found Ed. BOTH ORIG. J. PINE'S
BOOK 268 Pg 5

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____


Evidence of Subsequent Corner Restoration Found

Year of search 9-5-96 By CK
Ed. 2" IRON W/ CAP IN PLACE
113' WEST OF CO. ROAD # 148
30' EAST OF COR. 9' OF POWER LINE
15' EAST OF COR. EDGE OF CLEARING

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	<u>J. PINE STP.</u>	<u>J. PINE DEAD</u>
Diameter	<u>10</u>		
Bearing	<u>N30E</u>	<u>S74E</u>	<u>S25W</u>
Distance	<u>18.43'</u>	<u>5.20'</u>	<u>29.0'</u>

Relation of Evidence to Record Features Along Section Lines



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

113' WEST OF COUNTY ROAD # 148
 FSLP ON 5" J. PINE ON WEST SIDE OF COUNTY ROAD
 113' W TO COR.

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature Curt Krause

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MARKED NEW BT'S.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 146 R. 27 5TH Mer. N.F. CHEPPEWA County ITASCA State MN
MEANDER Corner common to sections 3 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1958 SAM BENZING
 Original monument 2" X 5" IRON MONUMENT
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>MAPLE</u>	<u>OAK</u>	<u>OAK</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N51W</u>	<u>S30W</u>	<u>S60W</u>
Distance	<u>14.3</u>	<u>22.24</u>	<u>25.82</u>

Original Evidence Found


Year of search 1987 By R MAEN
 Monument found 2 X 5 IRON

Original Bearing Trees Found

Species	<u>MAPLE</u>	<u>OAK</u>
Diameter	<u>6"</u>	<u>8"</u>
Bearing	<u>N51W</u>	<u>S60W</u>
Distance	<u>14.3</u>	<u>25.82</u>
	<u>15'SNAG</u>	<u>8'SNAG</u>

Subsequent Corner Restoration

Year surveyed 1987 By R MAEN
 Where filed or recorded _____
 Monument 2 X 5" IRON STAMPED:
(Original, concrete post, iron rod, etc.)




Bearing Trees, Reference Objects

Species	<u>ROAK</u>	<u>R.OAK</u>	<u>MAPLE</u>
Diameter	<u>15"</u>	<u>16"</u>	<u>13"</u>
Bearing	<u>N41W</u>	<u>S58W</u>	<u>S1°E</u>
Distance	<u>22.54'</u>	<u>31.05'</u>	<u>34.37'</u>

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects



LK
WINNIE GOSWICK

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

8" STEEL SIGN POST 2.4' WEST.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. 0-1516
(Alphabetical / Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 802-127

T. 146 R. 27 STA Mer. N.F. CHIPPEWA County ITASCA State MN
~~NW 1/4 & SW 1/4 of SE 1/4~~ Corner common to sections 3 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1958 S BENZING
 Original monument 2" X 5' IRON MONUMENT
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>BASSWOOD</u>	<u>BASSWOOD</u>	<u>oak</u>
Diameter	<u>9"</u>	<u>12"</u>	<u>6"</u>
Bearing	<u>S27W</u>	<u>N1E</u>	<u>EAST</u>
Distance	<u>11.83</u>	<u>31.00</u>	<u>6.78</u>

Original Evidence Found

Year of search 1987 By R MAIN
 Monument found 2" X 5' IRON.

Original Bearing Trees Found

Species	<u>BASSWOOD</u>	<u>BASSWOOD</u>
Diameter	<u>11"</u>	<u>26"</u>
Bearing	<u>S27W</u>	<u>N1E</u>
Distance	<u>11.83</u>	<u>31.00</u>

Subsequent Corner Restoration

Year surveyed 1987 By R MAIN
 Where filed or recorded _____
 Monument 2" X 5' IRON PIPE WITH 3" BRASS
CAP. 1.5' ABOVE GROUND.
(or pipe, concrete post, wood rod, etc.)

Bearing Trees, Reference Objects


Species	<u>W OAK</u>	<u>ASH</u>
Diameter	<u>12"</u>	<u>9"</u>
Bearing	<u>S20E</u>	<u>N7E</u>
Distance	<u>43.76</u>	<u>66.33'</u>

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____


4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MONUMENT STAMPED: T1462



8' STREET SIGN POST 3.5' EAST
 11 11 11 11 11 SOUTH

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 146 R. 27 5TH Mer. N.F. CHIPPEWA County ITASCA State MN
MEANDER CORNER Corner common to sections 3 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1958 S. BENZING

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	<u>OAK</u>	<u>X ROCK</u>	<u>X ROCK</u>
Diameter	<u>6"</u>	<u>2 1/2 X 4</u>	<u>3' Ø</u>
Bearing	<u>N 8 W</u>	<u>S 30 E</u>	<u>S 45 W</u>
Distance	<u>72.78</u>	<u>58.44</u>	<u>5.67</u>

Subsequent Corner Restoration

Year surveyed 1987 By R. MAIN

Where filed or recorded _____

Monument SET A 2" X 5' GALVANIZED STEEL PIPE
(Original, concrete post, iron rod, etc.)
WITH 3" BRASS CAP AND PLASTIC BREAKAWAY
BASE 1.8' ABOVE GROUND.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Original Evidence Found

Year of search 1987 By R. MAIN

Monument found NONE

Original Bearing Trees Found


Species	<u>OAK</u>	<u>X ROCK</u>	<u>X ROCK</u>
Diameter	<u>11"</u>	<u>2 1/2 X 4</u>	<u>3' Ø</u>
Bearing	<u>N 8 W</u>	<u>S 30 E</u>	<u>S 45 W</u>
Distance	<u>72.78</u>	<u>58.44</u>	<u>5.67</u>

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____



Sketch

O Corner  F.S. Land

Relation of Evidence to Record Features Along Section.

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

MONUMENT ± 10' FROM EDGE OF LAKE.

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____


3. Man hours spent in search _____

4. Do you think additional search might
 recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area.

MONUMENT STAMPED: T146NR21



Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records of _____ Date _____ County Document No. _____

5. Signature _____

Index No. D.E-16
(Alphabetical-Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 146 R. 27 5TH Mer. N.F. C HIPPEWA County ITASCA State MN
MEANDER Corner common to sections 3 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1958 S. BENZING
Original monument IRON MONUMENT 2"X5'
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species BASSWOOD BASSWOOD MAPLE
Diameter 9" 7" 5"
Bearing S73W S30E S14W
Distance 18.56 43.00 29.4

Subsequent Corner Restoration

Year surveyed 1987 By R MAIN
Where filed or recorded _____
Monument RESET MONUMENT 2.5' ABOVE
(Original, concrete post, iron rod, etc.)
GROUND.

Bearing Trees, Reference Objects

Species MAPLE
Diameter 6"
Bearing S25E
Distance 23.3

Original Evidence Found

Year of search 1987 By R MAIN
Monument found 2"X5' IRON WITH 3" BRASS CAP.
4' ABOVE GROUND.


Original Bearing Trees Found

Species BASSWOOD BASSWOOD MAPLE
Diameter 12 12" 9"
Bearing S73W S30E S14W
Distance 18.56 43.00 29.4

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
 Yes _____ No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____


4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MONUMENT STAMPED:



8" STEEL/STEEL POST 4' SOUTH.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records of _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 146 R. 27 STH Mer. N.F. CHIPPEWA County ITASCA State MN
EAST 1/16 Corner common to sections 3 10 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1958 S. BENZING
 Original monument 2" X 5' IRON MONUMENT
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species	BASSWOOD	MAPLE	MAPLE
Diameter	8"	5"	10"
Bearing	N56W	N70E	S2W
Distance	11.65	16.24	26.18

Subsequent Corner Restoration

Year surveyed 1987 By R. MAZN
 Where filed or recorded _____
 Monument 2" X 5' IRON PIPE WITH 3" BRASS CAP
1.8" ABOVE GROUND.

Bearing Trees, Reference Objects

Species	BASSWOOD	MAPLE	MAPLE
Diameter	18	18"	12"
Bearing	N38W	S14W	S89W
Distance	11.56	26.18	27.25

Original Evidence Found

Year of search 1987 By R MAZN
 Monument found 2" X 5' IRON MONUMENT

Original Bearing Trees Found


Species	BASSWOOD	MAPLE 3" STUB	MAPLE
Diameter	18"	5"	18"
Bearing	N38W	N84E	S14W
Distance	11.56	16.24	26.18

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			



Sketch

O Corner F.S. Land

Section no to _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____


3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established include brief description of area.

MONUMENT STAMPED:



8' STEEL SIGN POST 4.0' NORTH
8' " " " 3.3' SOUTH

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____

Which is filed at _____

T. 146 R. 27 5TH Mer. N.F. CHIPPEWA County ITASCA State MN
MEANDER Corner common to sections 10 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed 1958 S. BENZING
Original monument 2" X 5' IRON MONUMENT
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species OAK MAPLE BASSWOOD
Diameter 20" 9" 6"
Bearing N8W N39E N81E
Distance 26.68 27.36 20.97

Subsequent Corner Restoration

Year surveyed 1972 By R.H. McDONALD
Where filed or recorded _____
Monument SET NEW MONUMENT 62.35' NORTH
(Original corner to post, iron pin, etc.)
OF POINT FOR SMC.

Bearing Trees, Reference Objects

Species MAPLE MAPLE
Diameter 7" 10"
Bearing N52E S85E
Distance 45.2' 25.5'

Original Evidence Found

Year of search 1969 By J.P. ROLES M. DROTTS
Monument found NONE


Original Bearing Trees Found

Species MAPLE OAK (STP)
Diameter 9" 20"
Bearing N39E N8W
Distance 27.36 26.68

Evidence of Subsequent Corner Restoration Found

Year of search 1987 By R MAIN
FOUND 2" Ø MONUMENT WITH 3" BRASS CAP 2.3'
ABOVE GROUND. ACCESSORIES AND MONUMENT
ARE IN GOOD CONDITION.

Bearing Trees, Reference Objects



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
 Yes _____ No _____

2. How was search area located?
 Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____


4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

MONUMENT STAMPED:



4x4 CEDAR POST 5' NORTH
 8' STEEL SIGN POST 4.2' SOUTH.

Certified corner restoration certificate prepared: Yes _____ No _____
 Filed in county records of _____ Date _____ County Document No. _____
 Identified on aerial photo No. _____ Which is filed at _____

T. 146 R. 27 Mer. N.F. 2nd DEW County 1st DEW State MINN.
116 Corner common to sections 11 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____


Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1963 By XXXXXXXXXXXXXXXXXX
Found Iron Pipe 18" Above ground
B.T.S Scribbed 1/16 #8 S 11 BT

Maple 51M-Dead
7" 5"
S 58° W 21°
16.5 34.6 T



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc., Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____


Identified o aerial photo No. _____ Which is filed at _____

5. Signature A. B. White

T. 142 N R. 27 W Mer. N.F. Iowa County ITaska State Iowa
14 Corner common to sections 11, 12 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
<p style="text-align: center;">Subsequent Corner Restoration</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p>
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	Year of search <u>1953</u> By <u>A. Wells M. Hanser</u> <u>Found Iron Pipe 20" above</u> <u>ground with Alum cap Marked</u> <u>T146 BTS scribble</u> <u>111 12 12. 9 12 - E</u>
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> <u>2 1/2" 0 5</u> <u>6" "</u> <u>N86°E S30°E</u> <u>18.7 FT 9.8 FT</u>



Sketch

O Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. _____

3. Mon hours spent in search 1

4. Do you think additional search might
 recover evidence? Yes _____ No _____

5. Signature [Signature]

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____


Index No. 6-22
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-5680-11 (5/12/84)

T. 14 R. 1 Mer. N.F. Chippewa County 1 State WI
C.W. V16 Corner common to sections 12 and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1963</u> By <u>F. Wells M.H. Ansoy</u>
Where filed or recorded _____	<u>Found 1" Iron pipe 3" Above</u>
Monument _____ <small>(Original, concrete post, iron rod, etc.)</small>	<u>Ground 2 BTs scribed V16 #4</u>
_____	<u>S 12 BT</u>
_____	_____
Bearing Trees, Reference Objects	_____
Species _____	<u>Ash</u>
Diameter _____	<u>9"</u>
Bearing _____	<u>5 25° W</u>
Distance _____	<u>5.8 FT</u>
_____	<u>1'</u>
_____	<u>N 63° W</u>
_____	<u>2' E</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No X _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. By GPS and LIDAR

3. Man hours spent in search 1

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature A.E. [unclear]

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

Index No. J-2122
(Alphabetical & numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)
GPO 802-127

T. 146 N. R. R27W 5 Mer. N.F. Chipp County Itasca State MN
Meander Corner common to sections 12 and 13
East shore Winnie

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found


Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 4/22/02 By E. Smith
Ed. Approx. location tags By Itasca

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____



Sketch

○ Corner ▨ F.S.

At time of search:


1. Did you have the record of search?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, etc. _____

3. Man hours spent in search _____

4. Do you think additional search is warranted to recover evidence? Yes _____

5. Signature _____



Scale: 1/4" = 1 mile

x approximate location
Itasca Co meander corner tag
T146 R27 4/22/82 ESm/gh

Vertical list of lines for notes, including 'timber cutting lines', 'ea.', and 'No.'.

Index No. R-9
(Alphabetical - Numerical)

BOOK 1 LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 802-127

T. 146N R. 27W
SECTION

PAGE 1
5TH Mer. N.F. Chippewa County Cal State mn
 Corner common to sections 20, 21, 28 and 29

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874 GLO
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
SEE RESTORATION CERTIFICATE

Bearing Trees, Reference Objects
Jackpine Red Pine Red Pine
7" 8" 8"
N 75.5° W N 60.50° E N 25° E
33.10' 41.20' 36.60'



Sketch

○ Corner F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?
Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____

5. Signature _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

CERTIFICATE FILED

Clerk of Court for this certificate prepared: by Milo Stefan Yes No

Filed in county records at Cass Date 4/12/79 County Document No. 246214


Identified on aerial photo No. _____ Which is filed at _____

T. 146N R. 27W 5th Mer. N.F. Chippewa County Itasca State MINN
Center Quarter Corner common to sections 25 and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ <small>(Wood post, stake, pile of stones, pipe, etc.)</small>	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____

Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>1987</u> By <u>R. MAIN</u>	Year of search <u>1965</u> By <u>R.H. McDonald</u>
Where filed or recorded _____	Found a square concrete post w/ brass cap - top 2" post broken off. I set up post again and placed a cedar post 4"x4"x72" adjacent to and on the north side of monument. Standard F.S. sign 57-4 attached.
Monument <u>CONCRETE POST WITH 3" BRASS CAP.</u> <small>(Original, concrete post, iron rod, etc.)</small>	
Bearing Trees, Reference Objects	
Species <u>SPINE</u> <u>WPINE</u> <u>ROAK</u>	
Diameter <u>10"</u> <u>18"</u> <u>17</u>	
Bearing <u>N02E</u> <u>S68W</u> <u>S86E</u>	
Distance <u>31.0</u> <u>36.76</u> <u>55.16</u>	



Sketch

○ Corner ▨ F.S. Land

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. a woods road passes by corner on left side about 5' from corner. corner is in south side of a mud clearing area.

At time of search:

1. Did you have the record description?


Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. map3. Mon hours spent in search 04. Do you think additional search might
recover evidence? Yes _____ No _____5. Signature A.H.M. Donald

Perpetuation Record

Monument and accessories established. Include brief description of area.

MONUMENT STAMPED:

Certified corner restoration certificate prepared:

Yes _____ No _____

Filed in county records at _____ Date _____ County Do _____

Identified on aerial photo No. _____


T. 146 R. 27 5th Mer. N.F. Chippewa County Cass State Minn.
E 1/16 Corner common to sections 29, 32, and _____

EXISTING SURVEYS

Original Government Survey	Original Evidence Found												
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____												
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____												
<p style="text-align: center;">Subsequent Corner Restoration</p>	<p style="text-align: center;">Evidence of Subsequent Corner Restoration Found</p>												
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Metal, concrete post, iron rod, etc.)</small>	Year of search <u>5-8-70</u> By <u>S. M. Morrison</u> <u>Tag on N. side of 14" J. Pine which is</u> <u>a B.T. Blue line painted E & S.</u>												
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Bearing Trees, Reference Objects</p> <table border="0"> <tr> <td><u>J. Pine</u></td> <td><u>J. Pine</u></td> <td>_____</td> </tr> <tr> <td><u>10"</u></td> <td><u>14"</u></td> <td>_____</td> </tr> <tr> <td><u>West</u></td> <td>_____</td> <td>_____</td> </tr> <tr> <td><u>25 ft.</u></td> <td>_____</td> <td>_____</td> </tr> </table>	<u>J. Pine</u>	<u>J. Pine</u>	_____	<u>10"</u>	<u>14"</u>	_____	<u>West</u>	_____	_____	<u>25 ft.</u>	_____	_____
<u>J. Pine</u>	<u>J. Pine</u>	_____											
<u>10"</u>	<u>14"</u>	_____											
<u>West</u>	_____	_____											
<u>25 ft.</u>	_____	_____											

So. Copy

29



32
Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes _____ No X

2. How was search area located?

~~Ranging~~, chaining, photos, maps, etc. _____

3. Man hours spent in search 1

4. Do you think additional search might recover evidence? Yes _____ No X

5. Signature J.M. Morrison

(Rectangular)

1. T 146 R 27 No. 1-9 Cor. 5 Mer. 5 State Minn N.F. Chipp. Dist. Bemidj

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners:

7. Photo Identification
 Photo No. _____
 Ident. By: _____

5. Investigation Notes:

33" Norway Pine stump - mkd. BT. S56°W. 36.96' } orig pts.
 30" Norway Pine No mkd. N78°E 34.98' }

I got a oak stake for Temporary Corner.

F.S. Location Post Located on Norway Pine just North of Corner.

8. Plane Coordinate Position Data
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Field Book No. _____
 Where Filed _____

9. Evaluation
 Authentic _____
 Needs Verif. Monument _____
 Re-estab. _____ Survey _____
 Land Status _____

6. Signed Ces 9 Title Asst Eng. Date _____

PERPETUATION RECORD

10. Monument :

11. Accessories

Field Book _____ Page _____

12. Set By _____ Title _____

License _____ Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____

(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:

Index No. V-21
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
 GPO 802-127

T. 146N R. 27W 5th P. Mer. N.F. Chippewa County Cass State Minnesota
 Corner common to sections _____ and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____ By _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)


See Book 1, PP 6-7, Book 2, PP 2

Evidence of Subsequent Corner Restoration Found

Year of search 1982 By K.L. Whitehorn

Found 6 in x 4 in concrete monument with 3 in
Brass Cap. Near N. Pine

23.0 in
58° 30' 51" W
57.08 ft



Bearing Trees, Reference Objects

Species _____


Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>Orig N. Pine</u>	<u>New W. Oak</u>	<u>Orig N. Pine</u>	<u>Orig N. Pine</u>
<u>25.2 in</u>	<u>9.9 in</u>	<u>23.3 in</u>	<u>24.2 in</u>
<u>N33° 12' E</u>	<u>N49° 41' E</u>	<u>S17° 41' E</u>	<u>S06° 25' W</u>
<u>33.66 ft</u>	<u>20.00 ft</u>	<u>56.90 ft</u>	<u>57.42 ft</u>



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps, etc. _____

3. Man hours spent in search _____

4. Do you think additional search might recover evidence? Yes _____ No _____

5. Signature *[Signature]* RS

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes No _____


Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____

T. 146 R. 27 5th Mer. N.F. Chippewa County Cass State Minn.
1/4 Center Corner common to sections 35 and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____ Original monument _____ <small>(Wood post, stone, pile of stones, pipe, etc.)</small>	Year of search _____ By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc.)</small> <p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	Year of search <u>1962</u> By <u>Monison & Fulk</u> B.T. is 26" red pine approx Corner lies 15' N.W. of B.T. tag on 24" Red Pine - approx Corner lies 20' N.E. of tag - 2 timber sale b.dry. markers on 7" I.P. which is approx. Corner - No Brass Caps found. Blue line painted E. & S. of Corner.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes No _____

2. How was search area located?

~~Racing~~, chaining, ~~photos~~, maps,
etc. _____

3. Man hours spent in search 1/2

4. Do you think additional search might

recover evidence? Yes No _____

5. Signature J.M. Morrison

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified o aerial photo No. _____ Which is filed at _____

T. 146 R. 27 5^a Mer. N.F. Chippewa County Cass State Minn.
 Corner common to sections 35 & 36 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)


Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1962 By Morison & Julek
 New tag put upon S. side 74" Balsam
 Corner lies 6' 5 1/4 tag. Old tag on 9" red
 oak next to corner. B.T. is 9" Red Oak
 broken off 3' above ground. Corner consists
 of squared stake rotted off leaning against
 B.T. Blue line painted S&W of corner.
 No Brass Cap - possible B.T.'s is 12" Red
 Oak which lies 26' N. of corner.

7-146 27
Sec 25



7-146 27
Sec 36

Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified o aerial photo No. _____ Which is filed at _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Compass

3. Man hours spent in search 1

4. Do you think additional search might

recover evidence? Yes No _____

5. Signature J.M. Morrison

Index No. Y-17
(Alphabetic - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RB-5680-11 (5/12/61)

T. 146 R. 27 5th Mer. N.F. Chippewa County Cass State Minnesota
5 1/16 Corner common to sections 34 a 35 and

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____


Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1962 By Fulk & MorrisonB.T. is 8" Black Spruce which has been broken off @ 6" tag on 5" Black Spruce which lies 8' NW of B.T. - tag is assumed to be approx. corner. Blue line painted S & E of corner.

34

35



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____3. Man hours spent in search 1/2

4. Do you think additional search might

recover evidence? Yes No _____5. Signature S. M. Morrison

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified o aerial photo No. _____ Which is filed at _____

Index No. 2-19
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

RD-5680-11 (5/12/61)

T. 146 R. 27 5th Mer. N.F. Chippewa County Cass State Minn.
35 Corner common to sections _____ and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
 Original monument _____
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Where filed or recorded _____
 Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Evidence Found


Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration Found

Year of search 1962 By Morrison & Full
Tag on E. side of 7" Black spruce
which is a B.T. - tree is dead.
Squared post 3' E. of B.T. Post is scribed
Blue line painted N & W. of Corner.



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. _____

At time of search:

1. Did you have the record description?

Yes _____ No

2. How was search area located?

_____ Pacing, chaining, photos, maps,
 etc. Compass

3. Man hours spent in search 1/2

4. Do you think additional search might

recover evidence? Yes No _____

5. Signature J. M. Marwan

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified a aerial photo No. _____ Which is filed at _____