

..... National Forest
Township Range Meridian

Corner 1/4 Bet 16-17 144 27 5th

Corner Description

New Stake 3" Spruce faced two sides

Corner Markings

Witnesses

*Norway 18" S 50 W 15 Feet Scribbled 1/4 S
cedar 12" N 55 E 12 Feet Scribbled 1/4 S B.T.*

General Location

(Relation to other corners by alignment and measurement, also with topographic features, roads, streams, trails, fence corners or other distinctive objects which will enable others to locate. Mention blazing done if any.)

JAN - 9 1924

J. A. Soney
Forest Ranger

SH
3-28

*checked
1/20
H.H.*

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Minn

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N* R. *27W* Mer.

4 Corner common to Sections

17, and *16*

DESCRIPTION OF CORNER

Corner consists of a *Corner stake*

Dimension above ground *obliterated* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *NP Cedar* _____

Diameter *32'* *8* _____

Bearing *S25°W* *N27°E* _____

Distance *34* *17* _____

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

P. O. T. - W. L. S.

Signature.

1-5-28


Date.

Title.

T. 1414 R. 27 5th Mer.

8-3027

(Make sketch of topography near Corner.)



Metal Location Poster is on a Cedar
tree 10 inches diameter, on the _____
side of _____
from which this Corner bears S 36° W
28 links chains distant.

Give any further facts which will aid in finding this
Corner again.

Original corner gone
but its location
corresponds with
the original B.T.
on which the scribe
is not now visible.